

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 660T - AIG**AAD1802-060***Not Authorized*
1/1/2018 4:15 PM

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF660T - CANDY

VF1ABL15AUC278724

RENAULT

LATITUDE

05.02.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	Sm	1,259.42
2	1	BUMPER ABSORBER FRT	\$	Sm	394.68
3	1	BUMPER BEAM FRT	\$	R	914.08
4	1	BUMPER SPOILER FRT	\$	Sm	181.75
5	1	BUMPER UNDERTRAY FRT	\$	Sm	472.83
6	1	BUMPER GRILLE LOWER FRT	\$	Sm	266.80
7	1	BUMPER FOG LAMP GRILLE LH	\$	Sm	207.22
8	1	BUMPER RETAINER FRT LH	\$	Sm	151.41
9	1	BUMPER BRACKET FRT LH	\$	R	181.75
10	1	HEADLAMP LH	\$	Sm	1,184.43
11	1	HEADLAMP PANEL FRT LH	\$	R	152.15
12	1	FENDER PANEL FRT LH	\$	R	783.83
13	1	FENDER INSULATOR LH	\$	Sm	130.84
14	1	FENDER BRACKET FRT LH	\$	R	34.14
15	1	WHEELARCH FRT LH	\$	Sm	278.84
16	1	RADAITOR GRILLE	\$	Sm	1,707.78
17	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	Sm	173.36
18	1	RADAITOR GRILLE FRAME	\$	Sm	1,353.75
19	1	FRAME FULL SUPPORT PANEL	\$	Sm	615.90
20	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79
21	1	BONNET	\$	R	1,941.63
22	1	DOOR MIRROR LH	\$	Sm	1,483.40
23	1	DOOR MIRROR GLASS LH	\$	Sm	242.33
24	1	DOOR MIRROR BACK COVER LH	\$	Sm	218.46
25	1	DOOR MIRROR LAMP LH	\$	Sm	194.18
26	1	DOOR PANEL FRT LH	\$	R	2,844.66
27	1	DOOR FRAME PANEL FRT LH	\$	R	5,550.98
28	1	DOOR HINGE UPPER LH	\$	R	274.50
29	1	DOOR HINGE LOWER LH	\$	R	300.55
30	1	DOOR CHECK FRT LH	\$	Sm	194.77
31	1	DOOR LOCK FRT LH	\$	R	908.75
32	1	DOOR CATCH FRT LH	\$	Sm	131.23
33	1	DOOR GRAB HANDLE FRT LH	\$	Sm	210.96
34	1	DOOR HANDLE OUTER FRT LH	\$	Sm	477.76

X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-060

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 660T - AIG

35	1	DOOR HANDLE CAP FRT LH	\$	Sh	35.52	}	X
36	1	DOOR HANDLE SEAL FRT LH	\$	Sh	7.89		
37	1	DOOR HANDLE COVER FRT LH	\$	Sh	13.22		
38	1	DOOR HANDLE MODULE FRT LH	\$	Sh	133.60		
39	1	DOOR FINISHER FRT LH	\$	Sh	515.06		
40	1	DOOR MOULDING FRT LH	\$	Sh	176.82		
41	1	DOOR WHETHERSTRIP FRT LH	\$	Sh	410.27		
42	1	DOOR SEAL LOWER FRT LH	\$	Sh	91.17		
43	1	DOOR SEAL FRT LH	\$	Sh	72.82		
44	1	DOOR GLASS RUNNER SEAL FRT LH	\$	Sh	626.36		
45	1	DOOR WAIST SEAL OUTER FRT LH	\$	Sh	291.27	}	
46	1	ROCKER PANEL OUTER LH	\$	R	987.49		
47	1	DOOR PANEL REAR LH	\$	Not in	2,844.66	}	X
48	1	DOOR GUIDE REAR LH	\$	Sh	176.82		
49	1	DOOR HINGE UPPER LH	\$	R	274.50		
50	1	DOOR HINGE LOWER	\$	R	300.55		
51	1	DOOR CHECK REAR LH	\$	Sh	203.06		
52	1	DOOR GRAB HANDLE REAR LH	\$	Sh	210.96		
53	1	DOOR HANDLE OUTER REAR LH	\$	Sh	126.49		
54	1	DOOR HANDLE CAP REAR LH	\$	Sh	35.52		
55	1	DOOR HANDLE SEAL REAR LH	\$	Sh	7.89		
56	1	DOOR HANDLE COVER REAR LH	\$	Sh	13.22		
57	1	DOOR HANDLE MODULE REAR LH	\$	Sh	133.60	}	
58	1	DOOR FINISHER REAR LH	\$	Sh	423.10		
59	1	DOOR MOULDING REAR LH	\$	Sh	176.82		
60	1	DOOR SEAL REAR LH	\$	Sh	162.02		
61	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sh	334.69		
62	1	FENDER PANEL REAR LH	\$	R	3,299.13		
63	1	BUMPER COVER REAR	\$	Sh	1,108.46	}	

TOTAL	\$	38,701.89
10%	\$	3,870.19
	\$	34,831.70

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	Nu	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	Nu	66.00	X
3	1SET	BUMPER SUPPORT FRT CLIP LH	\$	Nu	9.80	X
4	1SET	BUMEPR RETAINER FRT CLIP LH	\$	Nu	12.50	X
5	1	RIM LH FRT	\$	Sh	385.00	X
6	1	TYRE LH FRT	\$	Sh	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	Nu	80.00	6050

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-060

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 660T - AIG

8	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 <i>15sn</i>
9	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>60sn</i>

TOTAL	\$	1,059.30
TOTAL PARTS	\$	35,891.00

To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 <i>5001</i>
Putty and spray painting of the affected portion.	\$	4,500.00 <i>8801</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>

TOTAL	\$	10,060.00
Over All Total	\$	45,951.00

(PARTS BY PARTS) Repair Days**15 Days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: