

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002464

Date : 30/04/2018

Vehicle Num. : C6C6440M

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2015027548/1KD2707749

Accident Date : 06/02/2018

Claim No. : S8M008L4MC/NPS

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER		577.40 <i>de</i> ✓
3.	8	BUMPER SIDE BRACKET, LH		123.50 <i>NN</i>
		BUMPER CLIP	5.00	40.00 <i>nee</i> ✓
List Total S\$:				740.90
25.00% Discount S\$:				185.23
				555.67
LABOUR :				200
TO PANEL BEAT/REPAIR LH BODY				250.00
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				
LOSS OF USE : 1 DAY @ \$ 120/DAY				
Labour Total S\$:				250.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 805.67

=====

Tanpin 97495749
- up
30/4/18 @ 3:15 pm
Guysun
Resurvey after repair
sure lkk auto-con
01 day