

To: YIHKWANGHAN@gmail.com

H Sir ,

Attached the report for your perusal.

Rdgs

Brenda Ng ,Customer Care Specialist ,CDGE Claim Dept, Braddell Branch Tel: 63837730 Fax: 62844284

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 29 October 2018 10:12 AM
To: William Tan
Subject: RE: SJW 779Y-DOA: 8/2/2018

Dear William,

WITHOUT PREJUDICE

Offer Lump Sum \$5500/- @ 6 working days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: William Tan <tanlihao74@gmail.com>

Sent: Friday, 26 October 2018 6:52 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; William Tan <tanlihao74@gmail.com>

Subject: Re: SJW 779Y-DOA: 8/2/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/02/2018 11:31
Date Of Accident	08/02/2018 10:00
Exact Location Of Accident	WOLSKEL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW779Y
Insured/Policyholder	
Name Of Registered Owner	HAN YIH KWANG (HAN YIGUANG)
NRIC No	S7919961C
Email Address	YIHKWANGHAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91150383
Alternative Phone No	OFFICE-91150383
Vehicle Particulars	
Manufacturer	BMW
Model	X3 XDRIVE28I M SPORT A/T S/R LED NAV HUD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1821127
Cover Note Number	
Driver	
Name of Driver	HAN YIH KWANG (HAN YIGUANG)
NRIC No	S7919961C
Date Of Birth	09/07/1979
Occupation	INDOOR
Date Of Driving Pass	21/09/1999
Driving Experience	18 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91150383
Fax Number	
Contact Number	OFFICE-91150383
Email Address	YIHKWANGHAN@GMAIL.COM

Address	3 SUNDRIDGE PARK ROAD
Postcode	358134
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	OWNER DID NOT FURNISH AT TIME OF REPORTING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM9696G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAK KOK CHOONG AUGUSTIN
NRIC/Passport Number	S2009126F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: SJW 779Y
B: SQM 96969

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Wolstel Rd on 08 February 2018 at around 10:00 am. Suddenly a vehicle which was stationary on my lane in the lane on my left dashed into my lane and hit onto my car left side. My left doors were dented as a result. my video.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Sompo Insurance Singapore Pte Ltd**
50, Raffles Place, #05-01 / 06,
Singapore Land Tower,
Singapore 048623

Attn : Motor Claims Department
Tel : 6221 2211, 6461 6555
Fax : 6221 3147

Estimate bill : TT 10 / 18 / TP / WT

Registration No : SJW779Y

Make / model : BMW X3 xDrive 28i

Mileage :

Date : 08 / 02 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGM9696G AND SJW779Y ALONG WOLSKEL ROAD ON 08 FEBRUARY 2018 AT ABOUT 1000 HRS.

1pc	Front LH door	\$	R	1,998.00	X
1pc	Front LH door protector	\$	Del	324.00	Z
1pc	Front LH door rubber	\$	R	270.00	X
1pc	Rear LH door	\$	Del	2,198.00	L
1pc	Rear LH door protector	\$	Del	324.00	L
1pc	Rear LH door rubber	\$	Del	270.00	L
1pc	LH door side skirt	\$	R	864.00	X
1pc	Rear LH fender	\$	R	1,980.00	X
1pc	Rear LH fender wheel art	\$	Del	297.00	L
1pc	Rear LH 19inch sport rim	\$	Del	1,980.00	L
1pc	Rear LH wheel bearing	\$	Del	700.00	X
1pc	Rear bumper	\$	R	1,800.00	X
1pc	Rear bumper lower lip	\$	Del	300.00	X
1pc	Rear bumper side bracket (LH)	\$	Del	120.00	X
Sub total :		\$		13,425.00	
Less 10% discount :		\$		1,342.50	
A total :		\$		12,082.50	
Total amount of Page 1 :		\$		12,082.50	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~the~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Sompo Insurance Singapore Pte Ltd**
50, Raffles Place, #05-01 / 06,
Singapore Land Tower,
Singapore 048623

Estimate bill : TT 10 / 18 / TP / WT

Registration No : SJW779Y

Make / model : BMW X3 xDrive 28i

Attn : Motor Claims Department
Tel : 6221 2211, 6461 6555
Fax : 6221 3147

Mileage :

Date : 08 / 02 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGM9696G AND SJW779Y ALONG WOLSKEL ROAD ON 08 FEBRUARY 2018 AT ABOUT 1000 HRS.

Remove & refit LH door door skirt	\$ 801 150.00
Remove and transfer front LH door & necessary attachment spare part items.	\$ 801 500.00
Remove and refit front LH door, front LH door protector, front LH door rubber.	
Remove & refit rear LH fender quarter glass.	\$ un 200.00 X
Remove and transfer rear bumper & necessary attachment spare part items.	\$ un 200.00 X
Remove and refit rear bumper, rear bumper lower lip, rear bumper side bracket (LH).	
Remove and transfer rear LH door & necessary attachment spare part items.	\$ 600 500.00
Remove and refit rear LH door, rear LH door protector, rear LH door rubber.	
Remove & refit rear LH wheel bearing.	\$ 200.00 X
Heat / weld / cut / renew rear LH fender, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.	\$ 600.00
Remove and refit rear LH sport rim.	\$ 201 50.00
Balancing rear LH wheel.	
Total amount of Page 2 :	\$ 2,400.00

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Sompo Insurance Singapore Pte Ltd**
50, Raffles Place, #05-01 / 06,
Singapore Land Tower,
Singapore 048623

Estimate bill : TT 10 / 18 / TP / WT

Registration No : SJW779Y

Make / model : BMW X3 xDrive 28i

Attn : Motor Claims Department
Tel : 6221 2211, 6461 6555
Fax : 6221 3147

Mileage :

Date : 08 / 02 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGM9696G AND SJW779Y ALONG WOLSKEL ROAD ON 08 FEBRUARY 2018 AT ABOUT 1000 HRS.

Diagnostic rear bumper parktronic sensor.	\$	122	150.00	X
Tuff kote rear damaged portion.	\$	301	200.00	
Conduct wheel alignment test	\$		100.00	60
Putty / primer application, spray painting front LH door (Inner & Outer), rear LH door (Inner & Outer), LH door side skirt, rear LH fender, rear bumper, rear bumper lower lip.	\$	12001	2,200.00	
Balance amount bought from Page 1 :	\$		12,082.50	
Balance amount bought from Page 2 :	\$		2,400.00	
Grand final amount :	\$		17,132.50	

17, 776.90

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Sompo Insurance Singapore Pte Ltd**
50, Raffles Place, #05-01 / 06,
Singapore Land Tower,
Singapore 048623

Supplementary bill : TT 10 / 18 / TP / WT

Registration No : SJW779Y

Attn : Motor Claims Department
Tel : 6221 2211, 6461 6555
Fax : 6221 3147

Make / model : BMW X3 xDrive 28i

Mileage :

Date : 09 / 02 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SGM9696G AND SJW779Y ALONG WOLSKEL ROAD ON 08 FEBRUARY 2018 AT ABOUT 1000 HRS.

Supplimentary rear spare part item :

lpc	Rear Michelin Primacy 3, 275 / 40 R19 runflat tyre (LH)	\$	716.00	<i>ln</i>	<i>X</i>
	Sub total :	\$	716.00		
	Less 10% discount :	\$	71.60		
	A total :	\$	644.40		
	Grand final amount for supplementary :	\$	644.40		

Tropical Tech Automobile Services


(Authorised Signature)
William Tan




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO18002598/Kvbe2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623			Date : 02-11-2018	
				
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGM 9696G	Veh. Inspected	SJW 779Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800645/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3 (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBAWX920900F72742	Colour	METALLIC DARK BLUE	
Odometer	12054	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R19	MICHELIN	8 mm	
L/H Front Tyre	245/45 R19	MICHELIN	8 mm	
R/H Rear Tyre	275/40 R19	MICHELIN	8 mm	
L/H Rear Tyre	275/40 R19	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	09/02/2018	
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 779Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,998.00	-
1	FRONT LH DOOR PROTECTOR	DENTED	324.00	324.00
1	FRONT LH DOOR RUBBER	SERVICEABLE	270.00	-
1	REAR LH DOOR	BENT / WARPED	2,198.00	2,198.00
1	REAR LH DOOR PROTECTOR	DENTED	324.00	324.00
1	REAR LH DOOR RUBBER	NECESSARY	270.00	270.00
1	LH DOOR SIDE SKIRT	TO REPAIR SEE LABOUR	864.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,980.00	-
1	REAR LH FENDER WHEEL ART	DENTED	297.00	297.00
1	REAR LH 19INCH SPORT RIM	DENTED	1,980.00	1,980.00
1	REAR LH WHEEL BEARING	NOT NECESSARY	700.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR BUMPER LOWER LIP	SERVICEABLE	300.00	-
1	REAR BUMPER SIDE BRACKET (LH)	SERVICEABLE	120.00	-
1	REAR MICHELIN PRIMACY 3, 275/40 R19 RUNFLAT TYRE (LH)(ADDITIONAL)	SERVICEABLE	716.00	-
	LESS 10% DISCOUNT		-1,414.10	-539.30
			12,726.90	4,853.70
<u>LABOUR</u>				
	REMOVE & REFIT LH DOOR DOOR SKIRT.		150.00	80.00
	REMOVE AND TRANSFER FRONT LH DOOR & NECESSARY ATTACHMENT SPARE PART ITEMS. }		500.00	80.00
	REMOVE AND REFIT FRONT LH DOOR,FRONT LH DOOR PROTECTOR,FRONT LH DOOR RUBBER. }		-	-
	REMOVE & REFIT REAR LH FENDER QUARTER GLASS.	NOT NECESSARY	200.00	-
	REMOVE AND TRANSFER REAR BUMPER & NECESSARY ATTACHMENT SPARE PART ITEMS. }	NOT NECESSARY	-	-
	REMOVE AND REFIT REAR BUMPER,REAR BUMPER LOWER LIP,REAR BUMPER SIDE BRACKET (LH).		200.00	-

Report Ref No. CS/SMO18002598/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	HEAT/WELD/CUT/RENEW REAR LH FENDER,HEAT/WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.INCLUSIVE OF THE REPAIR OF FRONT LH DOOR,LH DOOR SIDE SKIRT, REAR LH FENDER AND REAR BUMPER }		600.00	600.00
	REMOVE AND TRANSFER REAR LH DOOR & NECESSARY ATTACHMENT SPARE PART ITEMS. }	NOT NECESSARY	500.00	-
	REMOVE AND REFIT REAR LH DOOR,REAR LH DOOR PROTECTOR,REAR LH DOOR RUBBER. }		-	-
	REMOVE & REFIT REAR LH WHEEL BEARING.	NOT NECESSARY	200.00	-
	REMOVE AND REFIT REAR LH SPORT RIM. }		50.00	20.00
	BALANCING REAR LH WHEEL. }		-	-
	DIAGNOSTIC REAR BUMPER PARKTRONIC SENSOR.	NOT NECESSARY	150.00	-
	TUFF KOTE REAR DAMAGED PORTION.		200.00	30.00
	CONDUCT WHEEL ALIGNMENT TEST.		100.00	60.00
	PUTTY/PRIMER APPLICATION,SPRAY PAINTING FRONT LH DOOR (INNER & OUTER),REAR LH DOOR (INNER & OUTER),LH DOOR SIDE SKIRT,REAR LH FENDER,REAR BUMPER,REAR BUMPER LOWER LIP.		2,200.00	1,200.00
			5,050.00	2,070.00
GRAND TOTAL			17,776.90	6,923.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CS/SMO18002598/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.