

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05722

Vehicle Insured : EH7571X
Accident Date : 05-Feb-2018

Date : 07-Feb-2018

Our Ref : 218026 (AIG) / CHAN

PAGE : 1

GAN YAM SENG
46B TOH TUCK ROAD
#02-04
Singapore 596748

Not Authorized
Liberty & ?
Resurvey After Paint 5 days

ESTIMATED COST OF REPAIR FOR TOYOTA AXIO SGX8050T

- =====
- | | | |
|-------|-------------------------------------|-------------|
| 1 pc | Front o/s door | |
| 1 pc | Front o/s door rubber | |
| 1 pc | Front o/s door glass regulator gear | |
| 1 pc | Front o/s door frame tape(set) | |
| 1 pc | Rear o/s door | |
| 2 pcs | Rear o/s door hinge | @ S\$ 72.20 |
| 1 pc | Rear o/s door rubber | |
| 1 pc | Rear o/s door frame tape(set) | |
| 1 pc | O/s centre pillar | |

Ry	853.10	✓
Sm	144.70	X
	202.60	?
Mr	97.50	—
Ry	804.90	—
Mr	144.40	X
Mr	152.80	X
Mr	87.50	—
R	346.70	X

2,834.20

Less 25% : 708.55

2,125.65

To remove roof lining, front and rear seats, trim board and carpet

Mr 120.00 X

To apply undersealing

60.00 ✓

To putty and spray replaced parts

900.00 *Doc*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 *540*

Total : S\$ 3,905.65

Singapore Dollars Three Thousand Nine Hundred and Five and Cents Sixty Five Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: