



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S Tong Tar Transport Svc Pte Ltd
No 8 Soon Lee Road
SINGAPORE 628072
Insured Tong Tar Transport Svc Pte Ltd
Policy VFX/P0219856/00315

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 6/2/2018

Our Case Ref. SC18/01/013/4TT-TP

Accident Date 8/1/2018

Damaged Vehicle No: PC2166L

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts				10%	
1	LHS REAR PANEL R	1 PC	\$700.00	-	\$700.00
2	PENAL LOCK ✓ JM	2 PC	\$59.64	-	\$119.28
3	ARTWORK ✓ NEC	1 ST	\$600.00	-	400 \$600.00
4	MUDGUARD ✓ Defain	1 PC	\$800.00	-	\$800.00
5	LUGGAGE PANEL 1pcs ✓ DT 1pcs R	1 2 PC	\$1,000.00	-	\$2,000.00
6	MUDGUARD LAMP ✓ CRK	1 PC	\$80.50	-	\$80.50
7	EXCURSION BUS STICKER ✓ NEC	1 PC	\$15.00	-	\$15.00
Labour Charges					
1	LABOUR FOR WIRING	1	\$150.00	-	40 \$150.00
2	SPRAY PAINTING 600-800/panel	1	\$2,800.00	-	1000 \$2,800.00
3	LABOUR FOR LHS PORTION BODYWORK 60 640/day	1	\$3,200.00	-	1760 \$3,200.00 1920
Sebastian. 6/2/18. - Lump Sum Repair. - Photo After Paint. 90036121 Sebastianyeang@lkkauto.com					
5 days. LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					
Acknowledged by Repairer Signature:					
Date:					
Sub Total					\$ 10,464.78

Authorised Signature