A14

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 8660S

MAKE

MODEL : HYUNDAI i40

DATE 7/2/2018 9:21

J4

MODEL	: HYUNDAI i40							
Qty	Parts Description/ Labour	Туре	Uni	t Price		Amount		
	Rear Bumper				\$	603.60		
	Rear Bumper Reinforcement				\$	504.35	F	
	Rear Bumper Reinforcement Bracket (LH/RH) ."		\$	180.00	\$	360.00		
	Rear Bumper Side Bracket ?				\$	49.00		
	Rear Bumper Clips /				\$	22.00		
ľ	Rear Bumper Sponge 2				\$	143.40		
	Rear Bumper Under Cover		ļ		\$	225.00		
					5 - 23 3 - 23			
	SUB TOTAL				\$	1,907.35		
ŀ	LESS 20%				\$	381.47		
	DISCOUNTED TOTAL	1			\$	1,525.88		
			ı:					
	Rear Bumper Reverse Sensor				\$	135.70	Nett	
	Rear Bumper Rubber Mat				\$	50.00	Nett	
	Rear Bumper Advertisement Logo				\$	50.00	Nett	
	Rear Fender Advertisement Logo (LH/RH)		\$	100.00	\$	200.00	Nett	
					\$	435.70	1	
	Labour Charge					200		
	Panel Beating		į		\$	389.00		
	Spray Painting Charge				\$	200.00		
	Wiring Charge				\$	59.00		
	R/Refix Reverse Sensor				\$	129.00	728	
	TOTAL LABOUR	R			\$	750.00	1	
	Refer Pant plan				\$	2,711.58	1	
	10 /2 (1/14)					· ·		
	Jan 110 mil							
	1/1 2/2/-3 11152	I LK	K Auto Con	sultants hence	rotif	у		
ļ		- 10	resurvey before	of the following: ore/after spray pair	atina]		
e e	2/91	a 10	olippiay dama	ged part(s) during	rea	rey		
	0/-	• 11	iro party surve	subject to confirming is on a *Without	ation			
	11	- nc	megal moonic	ation(s) is allowed	1 I	1.		
	21 Part Pht.	• Su	DDIementary is	iem(s) must be res approval from Insi		ed and		
	Lufse 1 200	1 1			urance	Company		
		Ackn	owedged by f	Repairer		- 1		
		Date						
	This is an initial estimate based on a visual inspection of							
	be prepared after the vehicle is surveyed by a motor Surv	eyor appor	nted by th	e insurance co	ompa	any.	┙	