

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 784X

MAKE :

MODEL : HYUNDAI i40

DATE 7/2/2018 10:23

Take

Bill

Charge

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
				\$ 100.00	
	Labour Charge				
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	X
	R/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 820.00	

Kalun 10/1/18
7/2/18 1505L
20/1
45
After Rep p 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.