

John - Mr  
Rasul

fax on 11/10/18 @ 1600

Fax: 12/2/2018

7111

## SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 12 February 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBL 2056P

ACCIDENT DATE: 5 February 2018

Yamaha FZN 150 MEIRH/61392002043/2016 July

| Description             | Qty   | Quotation \$    |
|-------------------------|-------|-----------------|
| 1 Handle Bar            | 1     | 155.00 Bt ✓     |
| 2 Brake Lever           | 1     | 40 75.00 Bt ✓   |
| 3 Clutch Lever          | 1     | 45 68.00 Bt ✓   |
| 4 Signal Lamp R & L H   | 1     | 50 72.00 XRA ✓  |
| 5 Signal Holder Bracket | 1     | 95.00 X ✓       |
| 6 Balancer              | 1     | 50 120.00 SC ✓  |
| 7 Throttle Grip         | 1 set | 180.00 X ✓      |
| 8 Front Mudguard        | 1 set | 110 185.00 SC ✓ |
| 9 LH Side Shroud        | 1     | 150.00 SC ✓     |
| 10 Rear Tail Cover      | 1     | 165.00 SC ✓     |
| 11 Mirror LH            | 1     | 65 75.00 SC ✓   |
| 12 Fork Bracket LH      | 1     | 250.00 X ✓      |
| 13 Wheel Axle           | 1     | 95.00 X ✓       |
| 14 Engine Cover LH      | 1     | 95 138.00 SC ✓  |
| Sub-Total               |       | 1,820.00 925    |
| Less 10%                |       | 182.00 10%      |
| Sub-Total               |       | 1,638.00        |

832.50

(1)

VEHICLE NO : FBL 2056P

Yamaha FZN 150

Nett items

- 1 Rear box
- 2 IU Unit
- 3 Rear number plate
- 4 Towing fee
- 5 Remove & replace parts, align etc
- 6 Replace fork tube & top up fork oil
- 7 Putty & touch up paint

~~350.00~~ 150 ~~scr~~  
~~160.00~~ ~~scr~~  
15.00 ~~PA~~  
40.00  
~~250.00~~ 150  
~~120.00~~ 80  
~~300.00~~ 150 } 745

Sub-Total 1,235.00

Nett Total 2,873.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

PLG

Ram  
Hp 90010068

3 days

4/8

09/02/18

832.50

745.00

1577.50

20%

1262

4/5 - 1,250

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2