

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0169/2018/GW
Date : 7-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Evguenia Nekrassova
Address : Telok Blangah Rd Towards West Coast Highway
#20-03
Singapore 297725
Telephone : HP +65 91873484
Type of Claim : Own Damage Claims
Policy No. : 2100458400-01000
Vehicle No : **SGG 9599 K**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : Mar-16
Engine No : CYG 008157
Chassis No : WAUZZZ4G7GN049280
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Feb-18
Place of Accident : Telok Blangah Rd Towards West Coast Highway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGG 9599 K.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 X	
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓	
3	To dismantle front bumper, renew rhs front fender, rhs front door and rhs wing mirror assy. Reinstall front bumper and all parts removed.	\$ 3,150.00 1000 .	
4	To respray rhs front fender, rhs front door, door handle and rhs wing mirror cover.	\$ 2,400.00 1350 .	
5	To renew rhs front rim and tire, and carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>6,782.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SGG 9599 K.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER-RH <i>Rys</i>	\$ 1,220.00	<i>x</i>
2	FRONT STONE GUARD FILM-RH <i>m</i>	\$ 105.00	<i>✓</i>
3	FRONT FENDER BRACE-RH <i>2 m</i>	\$ 72.00	<i>x</i>
4	FRONT WHEEL HOUSING LINER-RH	\$ 246.00	<i>x</i>
5	WHEEL HOUSING LINER ATTACHMENT PARTS <i>m</i>	\$ 62.00	<i>x</i>
6	FRONT DOOR-RH <i>dented</i>	\$ 3,211.00	<i>✓</i>
7	FRONT OUTER DOOR SEAL-RH <i>m</i>	\$ 202.00	<i>✓</i>
8	BONDING AGENT <i>8</i>	\$ 43.00	<i>?</i>
9	CLEANING SOLUTION <i>?</i>	\$ 64.00	<i>?</i>
10	FRONT DOOR CATCH-RH <i>m</i>	\$ 105.00	<i>x</i>
11	FRONT LOWER DOOR SEAL-RH	\$ 165.00	
12	FRONT EXTERIOR DOOR HANDLE-RH <i>Rys</i>	\$ 516.00	<i>x</i>
13	FRONT DOOR CAP-RH <i>nt</i>	\$ 97.00	<i>✓</i>
14	FRONT DOOR MOUNTING-RH <i>m</i>	\$ 119.00	<i>x</i>
15	FRONT WINDOW SLOT SEAL-RH <i>m</i>	\$ 294.00	<i>x</i>
16	FRONT EXTERIOR MIRROR MOUNTING-RH <i>Rys</i>	\$ 1,237.00	<i>✓</i>
17	FRONT MIRROR GLASS-RH <i>shattered and cracked</i>	\$ 1,506.00	<i>✓</i>
18	FRONT EXTERIOR MIRROR MOUNTING-RH <i>?</i>	\$ 159.00	<i>?</i>
19	TURN SIGNAL INDICATOR <i>not m</i>	\$ 111.00	<i>x</i>
20	FRONT ALUMINIUM RIM-RH <i>nt</i>	\$ 726.00	<i>✓</i>
SUB-TOTAL SPARE PARTS CHARGES		\$ 10,260.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGG 9599 K.

<u>S/N</u>	<u>Parts Description</u>	<u>Damaged Par</u> <u>S/Nett</u>
21	RADIAL TYRE <i>ct</i>	\$ 770.00 ✓
22	SUNDRIES ?	\$ 600.00 ?
TOTAL SPARE PARTS CHARGES		\$ 11,630.00
TOTAL LABOUR CHARGES		\$ 6,782.00
GRAND TOTAL		\$ 18,412.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian ()
Surveyed Date : 07/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant