

INS. CASE OWNER:

CC 4, EQ1 1800 2627, SJ: Ka3sz

LKK:
IDAC:

Surveyor:

Ymk

DOI:

ASSIGNMENT

2/4/18


Date / Time:

8/2/18

Registered in Merimen:

Pre-assign / CCU / FTE

YN4242Y



Insured Vehicle No.:

APPLIED LOGISTICS P/L

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: *31-01-18*

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Muhammad Rifan bin Ahmad Latim

Driver Tel No.:

84857720

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

PA 84835



INSRS:
WSP: *Long Sheng*
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
<i>29/3</i>	<i>PA 84835 - X;</i>	Non-Reporting ltr (1st):	
<i>Zaini</i>	<i>YN 4242Y, KALCUTTA ROAD / H4; DOA: 16/09/16</i>	Non-Reporting ltr (2nd):	
	<i>TP got CCTV footage and uploaded in y drive.</i>	Non-Reporting ltr (Final):	<i>7 NA</i>
		Notification ltr (if non-pickup):	
		Call OI:	<i>Zaini 27-3-18</i>
		After call ltr to OI:	
<i>27/02/2018 @</i>	<i>Spoke to OI DL (Mr Rifan). Confirmed accident</i>	Documentation Check List: Handler Typist	
<i>4.27 pm</i>	<i>details and mentioned that OI was unaware of any collision. Informed abt TP claim, aware of WSP rates and agreed to settle.</i>	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input checked="" type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

RECEIVED 26 APR 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$S	(days) Reduction:	%
FINAL SETTLEMENT	Date/Time: <i>25-4-18</i>	Confirm with: <i>APPLE</i>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <i>100</i>	(Agreed / Assessed) BOLA S/N No.:	<i>NIL</i>
Repair Cost:	\$S <i>1,950.xx</i>		
Loss of Rental (LOR):	\$S <i>300</i>	(<i>4</i> days) X <i>200</i>	<i>MINIBUS</i>
Loss of Use (LOU):	\$S <i>X</i>	(\$ x days)	
Loss of Income (LOI):	\$S <i>X</i>	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	\$S <i>7.45</i>		
Medical:	\$S		
Disbursement:	\$S <i>X</i>	(e.g. Tow/ Independent)	
Legal Cost	\$S		
Total:	\$S <i>2,757.45</i>	Global Sum \$S:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S <i>2,757.45</i>	Name 1:	<i>LONG SHENG MOTOR SERVICE</i>
Payee 2: (Strike if N.A.)	\$S <i>X</i>	Name 2:	<i>X</i>
Payee 3: (Strike if N.A.)	\$S	Name 3:	<i>X</i>

COPY SENT 16/4/18

REF:

207/4/2013

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PA 84835 Yr Regn: 45/3/2009
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hiace c.c. 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 205331 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDH 2230602280
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195 R15C MIC
 R: " Good tyre

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 31/1/18 D.O.I. 2/4/18
 Survey held at Long Sheng
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 Frt O/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
4/5	\$1,950/-

RE \$2,840.87/5990

Date/Time File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
_____ \$ + RS _____ \$	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18002627/ka3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 08-02-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. YN 4242Y	Veh. Inspected	PA 8483S
	Policy No. DMCFHQ17-000141	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	08/02/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 31/01/2018	Inspection Date	
	Survey held at LONG SHENG MOTOR SERVICE BLK 6, NO. 399-G, WOODLANDS RD YEW TEE IND. ESTATE SINGAPORE 678007.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 02.04.2018

Page 1/2

Owner: Muhammad Firdaus Bin Johari

Attention: **EQ Insurance Company Limited**

RE: Accident to vehicle PA 8483S -Toyota Hiace Commuter GL 3.0 Auto (2008) on 31.01.2018

Estimated cost of repair of the above mentioned vehicle.

Replacement Parts:-

1pcs	Front Bumper ✓ CRK.	\$	521.70
2pcs	Front Bumper Side Retainer L/R @ 170.00 ✗ 1pc ✓ CRK RH	\$	340.00
1pcs	Front Bonnet R	\$	693.20
1pcs	Front Corner Panel RH ✓ NST	\$	195.60
1pcs	Headlamp RH ✓ CRK.	\$	580.50
1pcs	Front Centre Grille ✓ CRK	\$	470.50
1pcs	Front Bonnet Logo Emblem ✓ NTC	\$	68.50
1pcs	Headlamp Centre Grille ✗ NSP.	\$	1,203.60
1pcs	Front Centre Grille Inner Top Panel ✗ R	\$	380.90
		\$	4,454.50
	Less 25%	\$	(1,113.63)
		\$	3,340.87

ADD:

Spray Painting	\$	750.00	500. \$50
Labour Charges	\$	580.00	200
Anti Rust Treatment	\$	60.00	30
To Check Wiring	\$	60.00	30
	\$	1,450.00	

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian Total Amount : \$ 4,790.87

- Lump Sum Repair. 2/4/18

- Photo After Paint

90036121

sebastianyeang@lkk.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18002627/Ska3

Date: 06.04.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

PA 8483S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.04.2018 at the premises of M/s Long Sheng Motor Service - Woodlands and have the following to report:-

Workshop Estimate Amount	: S\$	<u>4,790.87</u>
Revised Estimate Amount	: S\$	<u>2,465.10</u>
"Check" Items Amount	: S\$	<u>-</u>
Total (Including Check Items)	: S\$	<u>2,465.10</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

10 Sin Ming Drive Singapore 575701

Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

10 Nov 2016

Our ref 1011160501N052765617

JOE BROTHERS SERVICE
APT BLK 294 CHOA CHU KANG AVENUE 2
#11-179
SINGAPORE 680294

Dear Sir/Madam

NOTIFICATION ON TRANSFER OF OWNERSHIP FOR VEHICLE NO. PA8483S

We are pleased to inform you that your application to transfer ownership of the above-mentioned vehicle has been approved. The Business Transaction Reference No. is 20161110153717741266. You are the registered owner of the vehicle with effect from 10 Nov 2016.

2. The following are the key owner and vehicle particulars for the vehicle. The full particulars are given at Annex A. Please check and ensure that the details are correct.

- | | |
|----------------------------|---|
| 1. Name | : JOE BROTHERS SERVICE |
| 2. Identification No. Type | : Business |
| 3. Identification No. | : 53349790J |
| 4. Place Of Passport Issue | : - |
| 5. Vehicle No. | : PA8483S |
| 6. Vehicle Type | : Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus |
| 7. Vehicle Scheme | : Public Service Vehicle (Others) |
| 8. Vehicle Make | : TOYOTA |
| 9. Vehicle Model | : HIACE COMMUTER GL 3.0 A |
| 10. Remarks | : To renew the COE, the Prevailing Quota Premium payable is that of Category C. This is a public service vehicle. |

Transaction ref 20161110153717741266

The owner and vehicle particulars for Vehicle No. PA8483S as at 10 Nov 2016 are as follows:

1. Name	: JOE BROTHERS SERVICE
2. Identification No. Type	: Business
3. Identification No.	: 53349790J
4. Place Of Passport Issue	: -
5. Vehicle No.	: PA8483S
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 10 Nov 2016
8. Original Registration Date	: 25 Mar 2009
9. First Registration Date	: 25 Mar 2009
10. Vehicle Type	: Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus
11. Vehicle Scheme	: Public Service Vehicle (Others)
12. Attachment 1	: Air-Conditioned
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: TOYOTA
16. Vehicle Model	: HIACE COMMUTER GL 3.0 A
17. Year of Manufacture	: 2008
18. Primary Colour	: White
19. Secondary Colour	: -
20. Passenger Capacity	: 13
21. Chassis/Trailer Chassis No.	: KDH2230005280 / -
22. Propellant	: Diesel
23. Engine No./Motor No.	: 1KD1874144 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 2982 / -
25. Maximum Power Output(kW/bhp)	: - / -
26. Unladen Weight(kg)	: 2180

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 8 February, 2018 1:24 PM
To: assignments
Cc: Admin A
Subject: FW: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018
Attachments: WhatsApp Video 2018-02-07 at 14.33.46.mp4; c33a9463-b8bd-4de0-a34e-52934e278075.jpg; 07022018163656.pdf

Hi,

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

08/02/2018 @ 2:46pm
Apple veh not in

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]
Sent: Thursday, 8 February, 2018 1:12 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

Dear LKK

We refer to the above new assignment, please find attached for easy reference.

Please be informed that our insured has yet lodge the GIA report.

Thank You.

Regards,
Lynn Ahmad
Executive | Claims

eqinsurance


EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: LSMTYC [<mailto:ismstyc@singnet.com.sg>]
Sent: Thursday, February 8, 2018 12:38 PM

To: Bazlin Ahmad

Subject: RE: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

Dear Sir/Madam ,

We choose LKK Auto Consultants Pte Ltd.
Kindly advise us this case have any new update.
Tks

***Wishing you a happy Chinese new year
Gong Xi Fa Cai***

*Best Regards,
Apple Sim*

Long Sheng Motor Service
*Blk 6 , No.399-G , Woodlands Road ,
Yew Tee Industrial Estate ,
Singapore 678007 .
Tel : +65 6763 9733
Fax: +65 6763 9866
Email : lsmstyc@singnet.com.sg*

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]
Sent: Wednesday, 7 February 2018 5:07 PM
To: LSMTYC <lsmstyc@singnet.com.sg>
Subject: RE: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

**Without Prejudice
Save As To Costs**

Dear Apple

Thank you for your email and attachments.
Our insured has yet lodge the GIA report, hence we are unable commit any liability as for now.

In the meantime, you proceed to choose one of our surveyors from the list below to survey your client's vehicle. We shall follow up with our insured on the GIA report.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
---	--

<p>3) LBS Automotive Appraisal Pte Ltd</p> <p>L.B.S. Auto Consultants Pte Ltd</p> <p>Tel: 6281 6690 / 62832866</p> <p>Fax: 6281 8748</p> <p>Contact Person: Amy/ Grace</p>	<p>4) Priority Services</p> <p>Tel: 62934822</p> <p>Fax: 62963283</p> <p>Contact Person: Sharon Kho</p>
<p>5) RT Appraisal Pte Ltd</p> <p>Tel: 67486076</p> <p>Fax: 67480361</p> <p>Contact Person: Ricky Teng</p>	<p>6) LKK Auto Consultants Pte Ltd</p> <p>Tel: 6256-3561</p> <p>Fax: 6741-4108</p>
<p>7) Kelvin Automotive Appraising Services</p> <p>Tel: 81825263</p> <p>Fax: 67461148</p> <p>Contact Person: Kelvin</p>	<p>8) Automotive Appraiser & Surveying Services</p> <p>Tel: 96623655</p> <p>Fax: 67655662</p> <p>Contact Person: Mr Chee</p>
<p>9) JP Knights Pte Ltd</p> <p>Tel: 63450068</p> <p>Fax: 63445328</p> <p>Contact Person: Edna Lee</p>	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,
Lynn Ahmad
 Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190
www.eqnsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: LSMTYC [<mailto:lsmstyc@singnet.com.sg>]
Sent: Wednesday, February 7, 2018 4:55 PM
To: Bazlin Ahmad
Subject: Accident Involving Vehicle No. PA 8483S & YN 4242Y On 31.01.2018
Importance: High

Dear Sir/Madam ,

Your Ref : YN 4242Y
Our Ref : PA 8483S

Enclose herewith attached for Accident Involving Vehicle No. PA 8483S & YN 4242Y On 31.01.2018 documents & video footage.

Your insured's vehicle no.YN 4242Y is the sole cause of the accident. Kindly advise us this case liability.
Please revert back us soonest.

Thanks a lot.

***Wishing you a happy Chinese new year
Gong Xi Fa Cai***

*Best Regards,
Apple Sim*

Long Sheng Motor Service
*Blk 6 , No.399-G , Woodlands Road ,
Yew Tee Industrial Estate ,
Singapore 678007 .
Tel : +65 6763 9733
Fax: +65 6763 9866
Email : lsmstyc@singnet.com.sg*

Mei Kwan (LKKAuto)

From: Zaini (LKK Auto)
Sent: Tuesday, 27 March, 2018 4:42 PM
To: Francis Ng
Cc: Admin A; Hsiao Tong (LKKAuto); Mei Kwan (LKKAuto)
Subject: RE: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018
Attachments: PA8483S.MP4

Categories: HMK

WITHOUT PREJUDICE

Our Ref: CC4/EQI18002627/ka3
Your Ref: TBA

Dear Francis,

ACCIDENT INVOLVING PA 8483S & YN 4242Y ON 31/01/2018

We refer to the email below.

Attach an enclosed copy of the TP CCTV footage for your review.

Based on the TP CCTV Footage, it can be seen that OI vehicle reversed and collided onto TP vehicle.

Kindly be informed that vehicle currently not in the workshop, repairer will arrange.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Francis Ng [<mailto:francis.ng@eqinsurance.com.sg>]
Sent: Wednesday, 21 March 2018 2:39 PM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>; Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: RE: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

Dear Zaini,

Please refer to the attached reports.

Regards,

Francis Ng

Executive | Claims

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 8 February, 2018 2:43 PM

To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

Dear Bazlin Ahmad,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

Sent: Thursday, 8 February, 2018 1:12 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: Accident Involving Vehicle No. PA8483S & YN4242Y On 31.01.2018

Dear LKK

We refer to the above new assignment, please find attached for easy reference.

Please be informed that our insured has yet lodge the GIA report.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims

eqnsurance


EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqnsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

<p>Fax: 6849 9155</p> <p>Contact person : Joey/Joseh</p>	
<p>3) LBS Automotive Appraisal Pte Ltd</p> <p>L.B.S. Auto Consultants Pte Ltd</p> <p>Tel: 6281 6690 / 62832866</p> <p>Fax: 6281 8748</p> <p>Contact Person: Amy/ Grace</p>	<p>4) Priority Services</p> <p>Tel: 62934822</p> <p>Fax: 62963283</p> <p>Contact Person: Sharon Kho</p>
<p>5) RT Appraisal Pte Ltd</p> <p>Tel: 67486076</p> <p>Fax: 67480361</p> <p>Contact Person: Ricky Teng</p>	<p>6) LKK Auto Consultants Pte Ltd</p> <p>Tel: 6256-3561</p> <p>Fax: 6741-4108</p>
<p>7) Kelvin Automotive Appraising Services</p> <p>Tel: 81825263</p> <p>Fax: 67461148</p> <p>Contact Person: Kelvin</p>	<p>8) Automotive Appraiser & Surveying Services</p> <p>Tel: 96623655</p> <p>Fax: 67655662</p> <p>Contact Person: Mr Chee</p>
<p>9) JP Knights Pte Ltd</p> <p>Tel: 63450068</p> <p>Fax: 63445328</p> <p>Contact Person: Edna Lee</p>	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.



To : M/s EQ INSURANCE COMPANY LTD

Date: 27/04/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 4242Y (Insd Veh)	Your Ref. No. : DMCFHQ17-000141
	PA 8483S (TP Veh)	Our Ref. No. : CC4/EQI18002627/Sja3s2
Date of Accident	31/1/2018	

Liability	100%	
Final Repair Cost	: \$ 1,950.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 800.00	4 days
Others:	: \$ 7.45	
	: \$	
	2,757.45	
Final Settlement Sum	: \$ 2,757.45	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	LONG SHENG MOTOR SERVICE	: \$ 2,757.45
		: \$

NUR SHAQILAH
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18002627/Sja3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 27-04-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4242Y	Veh. Inspected	PA 8483S
Policy No.	DMCFHQ17-000141	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KDH2230005280	Colour	WHITE
Odometer	505331	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	195 R15C	GOODYEAR	6 mm
L/H Rear Tyre	195 R15C	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/01/2018	Inspection Date	02/04/2018
Survey held at	LONG SHENG MOTOR SERVICE BLK 6, NO. 399-G, WOODLANDS RD YEW TEE IND. ESTATE SINGAPORE 678007.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8483S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRACKED	521.70	521.70
2	FRONT BUMPER SIDE RETAINER L/R @ \$170.00	O/S CRACKED	340.00	170.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	693.20	-
1	FRONT CORNER PANEL RH	DENTED	195.60	195.60
1	HEADLAMP RH	CRACKED	580.50	580.50
1	FRONT CENTRE GRILLE	CRACKED	470.50	470.50
1	FRONT BONNET LOGO EMBLEM	NECESSARY	68.50	68.50
1	HEADLAMP CENTRE GRILLE	NO SUCH PARTS	1,203.60	-
1	FRONT CENTRE GRILLE INNER TOP PANEL	TO REPAIR SEE LABOUR	380.90	-
	LESS 25% DISCOUNT		-1,113.63	-501.70
			3,340.87	1,505.10
LABOUR				
	SPRAY PAINTING.		750.00	500.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT CENTRE GRILLE INNER TOP PANEL.		580.00	400.00
	ANTI RUST TREATMENT.		60.00	30.00
	TO CHECK WIRING.		60.00	30.00
			1,450.00	960.00
GRAND TOTAL			4,790.87	2,465.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CC4/EQ118002627/Sja3s2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.