

# 龙胜汽车服务

## LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733

Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 02.04.2018

Page 1/2

Owner: Muhammad Firdaus Bin Johari

Attention: EQ Insurance Company Limited

**RE: Accident to vehicle PA 8483S -Toyota Hiace Commuter GL 3.0 Auto (2008) on 31.01.2018**

Estimated cost of repair of the above mentioned vehicle.

Replacement Parts:-

|      |  |    |                 |
|------|--|----|-----------------|
| 1pcs | Front Bumper ✓ CRK.                                    | \$ | 521.70          |
| 2pcs | Front Bumper Side Retainer L/R @ 170.00 ✗ 1pc ✓ CRK RH | \$ | 340.00          |
| 1pcs | Front Bonnet R   | \$ | 693.20          |
| 1pcs | Front Corner Panel RH ✓ DST                            | \$ | 195.60          |
| 1pcs | Headlamp RH ✓ CRK.                                     | \$ | 580.50          |
| 1pcs | Front Centre Grille ✓ CRK                              | \$ | 470.50          |
| 1pcs | Front Bonnet Logo Emblem ✓ N/E/C                       | \$ | 68.50           |
| 1pcs | Headlamp, Centre Grille ✗ NSP.                         | \$ | 1,203.60        |
| 1pcs | Front Centre Grille Inner Top Panel ✗ R                | \$ | 380.90          |
|      |  | \$ | 4,454.50        |
|      | Less 25%   | \$ | (1,113.63)      |
|      |  | \$ | <b>3,340.87</b> |

ADD:

|                     |    |                 |        |
|---------------------|----|-----------------|--------|
| Spray Painting      | \$ | 750.00          | 500.00 |
| Labour Charges      | \$ | 580.00          | 450.00 |
| Anti Rust Treatment | \$ | 60.00           | 30.00  |
| To Check Wiring     | \$ | 60.00           | 30.00  |
|                     | \$ | <b>1,450.00</b> |        |

4 days.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian Total Amount : \$ 4,790.87

- Lump Sum Repair. 2/4/18

- Photo After Paint

90036121

sebastianyang@lkkauto.com