

SKF3052T.

Nissan katio

JNH=AA1120003295

Rees Bumper Reformed

564 ✓

30 ✓

Rees Bumper Clips. New

Me

35 ✓

Rees Bumper Side Holder LH.

NE Me

219 40 X

Rees Bumper Side Holder RH

Repair

1080 X

Rees LH Fender

Wt

~~250~~ (SN) 180 (SN)

Rees LH Tyre

Nett: 629 Labour: 1070

Len 10%: 566.10 total: 1816.10

S/V: 180

L/S: 1.41K

03 Days

Panel Beating

~~800~~ 400

Spray Painting.

~~800~~ 400

Wiring

50 50

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~150~~ 60

To undersend

~~150~~ 50

To perform wheel alignment

~~150~~ 80

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Rees Bumper

Signature:

Date: