

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khor Saw Theng

Date: 14 Feb 2018

Preliminary Advice

Insured Vehicle No	: SHB7600S	Accident Date	: 08/02/2018
TP Vehicle No	: SKQ1663K	Assignment Date	: 08/02/2018
Make	: MAZDA 3	Est. Duration of Repair	: 2 days
Date of Inspection	: 12/02/2018		
Inspection At	: Li Sheng Automobile Trading (HQ) No. 18 Pandan Loop #01-18 Blk K Singapore 129236		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,307.61
Revised Amount	:S\$	1,401.73
Check Items (Estimated)	:S\$	1,647.63
Total	:S\$	3,049.36
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.