

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 8/2/2018
Vehicle No: SKQ1663K
Model: MAZDA 3
Date of loss: 8/2/2018
Our ref: LSA250TJS
Year: 2014

AXA INSURANCE

Your Ref Vehicle No:
SHB7600S - TP

Qty	Description	List Price	Remarks
		REPAIR	
1.00	BOOTLID		
1.00	REAR BUMPER	\$ 849.70	de ✓
10.00	REAR BUMPER CLIPS	\$ 30.00	un ✓
12.00	REAR BUMPER RETAINER	\$ 121.80	? X un
12.00	REAR BUMPER BRACKET	\$ 188.40	? X un
12.00	REAR BUMPER REFLECTOR	\$ 244.60	? X un
1.00	REAR REINFORCEMENT	\$ 431.50	? X un
1.00	END PANEL	\$ 642.50	R-P
4.00	REVERSE SENSOR	\$ 844.40	? X un

TOTAL: \$ 3,352.90
LESS 10 %: \$ 335.29
\$ 3,017.61

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 1,000.00	250
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 900.00	250
1.00	CHECK WIRING	\$ 50.00	20
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 60.00	X
1.00	REMOVE & REFIT AFFECTED REAR TRIM TO FACILITATE REPAIR	\$ 150.00	40
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 80.00	30
1.00	SUNDARIES	\$ 50.00	20

TOTAL: \$ 2,290.00

SUBTOTAL: \$ 5,307.61

Estimate prepared by: WINSON

Telephone : 97684247

winsonls@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
'wp'

12/2/18 @ 11am.
2 days.

Sur @ LKK auto con
Tan Jiah @ LKK auto con
Resurvey before paint