

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd
 22 Gemmill Lane
 Singapore 069257
 Tel : 6223 - 9433
 Fax : 6224 - 3903

Quotation
 DATE : 09.02.2018
 VEH NO : SJK5308D
 MODEL : Honda Accord
 D O A : 06.02.2018
 YR REF : SJG6168E

VIC

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJK5308D (HONDA ACCORD)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Del'd</i>	1	768.50 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	51.00 ✓
4	Rear Bumper Reinforcement <i>Best</i>	1	334.10 ✓
5	Rear End Panel <i>Del'd</i>	1	586.20 ✓
6	Rear End Panel Top Garnish <i>Del'd</i>	1	154.90 ✓
7	Taillamp - LH & RH <i>new</i>	2	591.60 X
8	Bootlid <i>Buckled</i>	1	921.20 ✓
9	Bootlid Lock <i>Del'd</i>	1	260.90 ✓
10	Bootlid Weatherstripe <i>cut</i>	1	168.00 ✓
11	Bootlid Outer Garnish <i>cut</i>	1	367.30 ✓
12	Bootlid Outer Garnish Clips <i>new</i>	1 set	20.00 ✓
13	Bootlid Reflector - LH & RH <i>new</i>	2	430.00 X
14	Honda Logo <i>new</i>	1	35.00 ✓
15	i-vtec Emblem <i>new</i>	1	46.00 ✓
16	Spare Tyre Panel Top Board <i>new</i>	1	153.80 X
17	Rear Exhaust Pipe <i>Best</i>	1	931.60 ✓
18	Rear Exhaust Mounting <i>new</i>	1	38.40 X
19	Rear Fender Inner Trim Board - LH & RH <i>new</i>	2	442.20 X
20	Rear Fender Inner Trim Board Clips <i>new</i>	2 sets	60.00 X
			\$ 6,390.70
Less 20%			(1,278.14)
			\$ 5,112.56
S/NET ITEMS			
1	Reverse Sensor <i>Del'd</i>	340 4	350.00 280
2	Rear End Panel Sealant	1	60.00 ✓
			\$ 410.00

RE: ESTIMATE FOR ACCIDENT REPAIR SJK5308D (HONDA ACCORD)

Total Parts \$ 5,522.56

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 800
2	To putty & spray up paint works	\$	1,200.00 800
3	To check wiring	\$	50.00 30
4	To under seal	\$	100.00 40
5	To remove reverse sensor	\$	100.00 60
6	To remove upholstery	\$	150.00 60
7	To transfer bootlid fittings	\$	150.00 80
8	To remove exhaust pipe	\$	150.00 80

Total Labour \$ 3,100.00

Grand Total \$ 8,622.56

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 602876.
L/S: A.81C.
06Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: