

22/03/2002

ASS. REC. BY:

REF: CS/FCI18002634/Svd3n2 Special Instruction:

Surveyor: Sebastian ASSIGNMENT (Office)

From (Person): CWS May chui of FCI Date/Time: 8/2/18 @ 4:50pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 5399R Insured: SHC2690J

at Workshop m/s Sin Yew Hup Tel: 67600819

of 393M Woodlands Rd, Yew Tee Ind. est.

Policy No: Claim No: D18001154MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 5/2/2018
(Client's Record) 9/2/18 @ 4pm owner waiting

CA / REV / REP. / REV 24 HRS lwp? H.O.D. Endorsement:

Date/Time: 5:10pm @ 8/2/18 Person Contacted: Yong jian Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKD 5399R-CS3/AXA12002051/Rly/m	D.O.A.: 28/1/2012
	SHC2690J-CS3/AG13009346/M/sb3q2	D.O.A.: 19/5/13
13/2/18	Email preli revised to FCI	
27/3/18	LS \$2250 confirmed by email (Ref 3216, 5990)	

Gonzalez

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time / Action / Instruction

Veh No: SKD 5399R Yr Regn: 1/4/2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer c.c. 1584

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 161650 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jmystcs 3484 006507

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15 West Lake

R: 175/60R15 Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/2/18 D.O.I. 28/2/18

Survey held at Sin Yew Hyip

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 0.7 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 2/4- typist

Report Format :

Lump Sum / I.B.I. (\$) 225012

aws

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee: 130

Transportation: 50

) \$ + RS. \$

) Photos 50

) Others 35

TOTAL

265

Survey Department Check List (Case Handler)

Reference No.: CS/FCI/8002634/Svc3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
 C Market Value for OD cases
 C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
 C Days of repair
 C Finalised Amount
 C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

Check By:

VERON

24/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002634/Svd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2690J	Veh. Inspected	SKD 5399R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001154MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	09/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	09/02/2018
Survey held at	SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001154MFSH
Our ref: CS/FCI18002634/Svd3

Date: 13/2/2018

The Motor Claims Department
M/s First Capital Insurance Limited

Without Prejudice

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO.

SKD 5399R


We thank for your instruction on 8/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 9/2/2018 at the premises of M/s SIN YEW HUP AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,616.00
Revised Estimate Amount	: S\$2,998.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

YEANG WAI KEEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-02-2018	Our Ref No. D18001154MFSH
Accident Date	05-02-2018	Claim Type. Third Party
Insured Vehicle	SHC2690J	Third Party Vehicle. SKD5399R
Survey Location	393M WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE	
Contact Person.	YONG JIAN	
Contact No.	67600819/ 0	Fax No. 67690221
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN YEW HUP AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234777)



PRI Documents



Close



PRI Header Details

Claim No	D18001154MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SIN YEW
Workshop Name	SIN YEW HUP AUTO PTE LTD (Contact Person : YONG JIAN)	Survey Location & Contact Details	393M WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE Mobile: 0 , Phone: 67600819 , Fax: 67690221 EmailId: SINYEWHUP@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2690J	TP Vehicle No	SKD5399R
PRI Recieved Date	07-02-2018 07:08:50 PM	Surveyor Appointed Date	08-02-2018 04:49:55 PM	Surveyor Accept Date	09-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Sebastian Yeang (LKK Auto)
Sent: Tuesday, 27 March 2018 3:15 PM
To: Veron Chen (LKKAuto)
Subject: FW: SKD 5399 R

fyi

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sin Yew Hup Auto Pte Ltd [<mailto:sinyewhup@gmail.com>]
Sent: Tuesday, 27 March 2018 3:14 PM
To: Sebastian Yeang (LKK Auto)
Subject: Re: SKD 5399 R

Hi

Good day

Dear Sebastian

Confirm acceptance with the amount of \$2,250 @ 5 days.

Thank you

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD

T : +65 67600819

F : +65 67690221

On Tue, Mar 27, 2018 at 2:52 PM, Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com> wrote:

Dear Yong Jian

Please refer to attachment for the finalization.

Thank You

CS/FCI18002634/Svd3

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sin Yew Hup Auto Pte Ltd [<mailto:sinyewhup@gmail.com>]
Sent: Wednesday, 21 March 2018 11:26 AM
To: Sebastian Yeang (LKK Auto)
Subject: Fwd: SKD 5399 R

Hi

Good day

Dear Sebastian

Attached with COR and photo after paint for your perusal.

Kindly look through and finalize for us.

Thank you.

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD

T : +65 67600819

F : +65 67690221

----- Forwarded message -----

From: **Sin Yew Hup Auto Pte Ltd** <sinyewhup@gmail.com>

Date: Fri, Mar 2, 2018 at 11:35 AM

Subject: SKD 5399 R

To: "Sebastian Yeang (LKK Auto)" <sebastianyeang@lkkauto.com>

Hi

Good day

Dear Sebastian

Attached with COR and photo after paint for your perusal.

Thank you.

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD

T : +65 67600819

F : +65 67690221

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 13 February 2018 4:53 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001154MFSH/1, SKD 5399R
Attachments: SKD 5399R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKD 5399R
Date of survey: 9/2/2018
Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 8 February 2018 5:38 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001154MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 February 2018 4:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001154MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Mitsubishi Lancer

Price Range ▼

Depreciation ▼

2008 ▼

Vehicle Type ▼

Advanced Search

Home » Used Cars » 1 Accurate Auto » Mitsubishi Lancer 1.6A GLX

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



Book hotel with agoda

Amara Singapore

>

Ramada Singapore at Zhongshan Park

>

Marina Mandarin Singapore Hotel

>

Mitsubishi Lancer 1.6A GLX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$8,000	
Depreciation	-	?
Reg Date	07-Apr-2008 (1mth 24days COE left)	
Manufactured	2008	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,584 cc	
Road Tax	\$734 /yr	?
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)	
Curb Weight	1,162 kg	?
Features	-	
Accessories	-	
COE	\$18,854	?
OMV	\$12,613	?
ARF	\$12,613	?
Dereg Value	\$6,575 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 12-Feb-2018 | Last Updated on: 12-Feb-2018

Tags: Mitsubishi Lancer, 2008 Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Upfront Payment

» more Financial Info

Transfer Fee	\$25	?
Down Payment	\$2,400 (change)	Maximum 70% Loan ?
1st Instalment	\$5,614	?
Total Upfront Payment	\$8,039 (excluding Insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Mitsubishi Lancer

» View All

Day Running Light
From \$190Car Mat
\$40

Location Map



Price Analysis

Seller Information

Company	1 Accurate Auto » dealer's pricelist » 100 vehs sold 7 vehs available
Address	53 Ubi Avenue 1 #01-33 Search cars nearby this location
Location	Paya Ubi Industrial Park
Office No	64932109
Contact Person(s)	Jeremy 98888885

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1206K
Vehicle Details	
Vehicle No.:	SKD5399R
Vehicle to be Exported:	No
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4G18JP5254
Chassis No.:	JMYSTCS3A8U006507
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,941.00
Original Registration Date:	01 Apr 2008
First Registration Date:	01 Apr 2008
Transfer Count:	2
Actual ARF Paid:	\$14,236.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2018

PARF Rebate Amount:	\$7,118.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,856.00
COE Rebate Amount:	\$169.00
Total Rebate Amount:	\$7,287.00

The information contained herein is correct as at 13 Feb 2018

OK



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

07-Feb-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHC 2690 J

Date of Accident : 05/02/2018

M/S LEISURE LEASING PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

Sebastian.
7/2/18.

- Lump Sum Repair -
- Photo After Paint
90036121

Sebastianyeang@lktauto.com

13/2/18

5 days.

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATED COST OF REPAIR TO MITSUBISHI LANCER 1.6 (A): SKD 5399 R

A) Chassis No : JMYSTCS3A8U006507

B) Date of Registration : 01 Apr 2008

S/No.	Pc/s	Nett Item(s) :-	
1	1	Front fender RH ✓ OT	573.00
2	8	Front fender inner shield clip @ \$3.00 ✓ NEC	24.00
3	1	Wiper garnish RH ✓ cut	57.00
4	1	Wing mirror RH R	298.00
5	1	Front windscreen ✓ CRK.	632.00
6	1	Front windscreen top moulding ✓ NEC	30.00
7	1	Front windscreen side moulding RH ✓ cut	188.00
8	8	Windscreen side moulding clip @6.00 ✓ NEC	48.00
			1,850.00
<u>Special Nett Item(s) :-</u>			
9	1	Front windscreen sealant ✓ NEC.	40.00
10	1	Front windscreen innerseal ✓ NEC.	20.00
11	1	ERP bracket ✓ NEC.	26.00
			1,936.00

Labour Charges :

- To remove and refit front windscreen 120.00 ✓
- To antirust the affected portion 60.00 40.
- To putty and spray paint front fender RH, front bonnet, wing mirror, wheelhouse RH, door pillar RH, windscreen pillar RH, spoiler RH 800.00 600
- To remove and replace front fender RH, wing mirror RH, wiper garnish RH, remove and refit headlamp RH, front bumper, spoiler RH, panel beat wheelhouse RH, door pillar RH, windscreen pillar RH 700.00 600

GST (7%) :-

Total :-

700.00
3,616.00
253.12
3,869.12

600
5466



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 2009210750

07-Feb-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHC 2690 J
Date of Accident : 05/02/2018

M/S LEISURE LEASING PTE LTD

C/o 393M Woodlands Road
Yew Tee Industrial Estate
Singapore 677981

Sebastian.
7/2/18.

- Lump Sum Repair
- Photo After Paint
90036121

Sebastian.yeap@lkh.com

5 days.

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATED COST OF REPAIR TO MITSUBISHI LANCER 1.6 (A): SKD ~~5399R~~

A) Chassis No : JMYSTCS3A8U006507

B) Date of Registration : 01 Apr 2008

S/No.	Pc/s	Nett Item(s) :-	
1	1	Front fender RH ✓ OT	573.00
2	8	Front fender inner shield clip @ \$3.00 ✓ NEC	24.00
3	1	Wiper garnish RH ✓ cut	57.00
4	1	Wing mirror RH R	298.00
5	1	Front windscreen ✓ CRK.	632.00
6	1	Front windscreen top moulding ✓ NEC	30.00
7	1	Front windscreen side moulding RH ✓ cut	188.00
8	8	Windscreen side moulding clip @6.00 ✓ NEC	48.00
			<u>1,850.00</u>

1552

-10%

1) 1396.80

		Special Nett Item(s) :-	
9	1	Front windscreen sealant ✓ NEC	40.00
10	1	Front windscreen innerseal ✓ NEC	20.00
11	1	ERP bracket ✓ NEC	26.00
			<u>1,936.00</u>

2) 86

Labour Charges :

- | | | |
|----|---|------------|
| a) | To remove and refit front windscreen | 120.00 ✓ |
| b) | To antirust the affected portion | 60.00 40 |
| c) | To putty and spray paint front fender RH, front bonnet, wing mirror, wheelhouse RH, door pillar RH, windscreen pillar RH, spoiler RH | 800.00 600 |
| d) | To remove and replace front fender RH, wing mirror RH, wiper garnish RH, remove and refit headlamp RH, front bumper, spoiler RH, panel beat wheelhouse RH, door pillar RH, windscreen pillar RH | 700.00 600 |

700.00

3,616.00

253.12

3,869.12

1) Parts : \$ 1396.80

2) S/Nett : \$ 86.00

3) Labour : \$ 1360.00

2842.80

-20%

2274.24

GST (7%) :-

Total :-

4/5 : \$ 2250 @ 5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002634/Svd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2690J	Veh. Inspected	SKD 5399R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001154MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JMYSTCS3A8U006507	Colour	GREY	
Odometer	161680	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	6 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2018	Inspection Date	09/02/2018	
Survey held at	SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5399R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH (N)	DENTED	573.00	573.00
8	FRONT FENDER INNER SHIELD CLIP @\$3.00 (N)	NECESSARY	24.00	24.00
1	WIPER GARNISH RH (N)	CUT	57.00	57.00
1	WING MIRROR RH (N)	TO REPAIR SEE LABOUR	298.00	-
1	FRONT WINDSCREEN (N)	CRACKED	632.00	632.00
1	FRONT WINDSCREEN TOP MOULDING (N)	NECESSARY	30.00	30.00
1	FRONT WINDSCREEN SIDE MOULDING RH (N)	CUT	188.00	188.00
8	WINDSCREEN SIDE MOULDING CLIP @\$6.00 (N)	NECESSARY	48.00	48.00
	LESS 10% DISCOUNT		-	-155.20
			1,850.00	1,396.80
SPECIAL NETT ITEMS				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	FRONT WINDSCREEN INNERSEAL (SN)	NECESSARY	20.00	20.00
1	ERP BRACKET (SN)	NECESSARY	26.00	26.00
			86.00	86.00
LABOUR				
	TO REMOVE AND REFIT FRONT WINDSCREEN.		120.00	120.00
	TO ANTIRUST THE AFFECTED PORTION.		60.00	40.00
	TO PUTTY AND SRAY PAINT FRONT FENDER RH, FRONT BONNET, WING MIRROR, WHEELHOUSE RH, DOOR PILLAR RH, WINDSCREEN PILLAR RH, SPOILER RH.		800.00	600.00
	TO REMOVE AND REPLACE FRONT FENDER RH, WING MIRROR RH, WIPER GARNISH RH, REMOVE AND REFIT HEADLAMP RH, FRONT BUMPER, SPOILER RH, PANEL BEAT WHEELHOUSE RH, DOOR PILLAR RH, WINDSCREEN PILLAR RH.		700.00	600.00
			1,680.00	1,360.00
GRAND TOTAL			3,616.00	2,842.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/FCI18002634/Svd3n2



Report Ref No. CS/FCI18002634/Svd3n2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.