

SHARINI

CC 7 / III 1800

7635, K2663

Surveyor:

Kaluh

DOI:

ASSIGNMENT

28/2/18

Date / Time:

8/2/18

Registered in Merimen:

9/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 1922U

Claim No.:

MCT180202AG

Name of Insured:

LTPU

Policy No.:

MLOM0015

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A:

02/02/18

Place of Accident:

WIPART 2 TAXI QUEUE

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

AMM HAN SEMA

OI GIA REPORT (YES/NO) : TP GIA REPORT (YES/NO)

Driver Tel No.:

(V/LA) (YES/NO)

Insured Liability: %

Final ? Yes / No

SHB 8619H



INSRS: WSP: Tel: Liability: RMKS:

pinma



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
12/2/18	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
15/02/18	Call OI:	vic
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
21/02/18	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 20 MAR 2018

VIA VIC 02-03-18

COPY SENT 28/2/18 "REPORT TP CLAIM" TP WONG OP FROM OIIF

**PRELIMINARY ADVICE** Date/Time: Sent By: Confirm with: Confirm by:

**FINALIZATION** Date/Time: Confirm with: Confirm by: Email  Call

Repair Cost: 2,400.00 ( 3 days) Reduction: 82 %

**FINAL SETTLEMENT** Date/Time: Confirm with: Email  Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : If NO or B 28, Ass. Lia :

Repair Cost: \$5 -

Loss of Rental (LOR): \$5 - ( days)

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: \$5 -

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 - Global Sum \$5:

**FINAL PAYMENT** Date/Time: Confirm with: Email  Call

Payee 1: \$5 - Name 1: -

Payee 2: (Strike if N.A.) \$5 - Name 2: -

Payee 3: (Strike if N.A.) \$5 - Name 3: -

1) Claim status: Normal/Reject/Private Settle  
2) Report Format:  
3) Survey fee: \$ 250.00





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18002635/K1hb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 09-02-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1992U	Veh. Inspected	SHB 8619H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/02/2018	Inspection Date	08/02/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8619 H

1 pc	Front n/s wheel cover — <i>bracket</i>	\$ 116.00 —
1 pc	Front n/s fender — <i>bracket</i>	\$ 384.00 —
1 pc	Front n/s fender inner shield — <i>bracket</i>	\$ 120.00 —
1 pc	Front bumper — <i>bracket</i>	\$ 531.00 —
1 pc	Front bumper emblem — <i>bracket</i>	\$ 44.00 —
1 pc	Front bumper n/s side retainer @ \$16.00 — <i>bracket</i>	\$ 16.00 —
1 pc	Front bumper n/s protector @ \$51.00 — <i>bracket</i>	\$ 51.00 —
1 pc	Front bumper n/s fog lamp cover @ \$66.00 — <i>bracket</i>	\$ 66.00 —
1 pc	n/s head lamp — <i>bracket</i>	\$ 1,028.00 —
		\$ 2,356.00
Less 10%		\$ 235.60
		\$ 2,120.40

**S/NETT**

1 set	Front n/s fender inner shield clips — <i>bracket</i>	\$ 28.00 —
1 set	Front bumper clips — <i>bracket</i>	\$ 48.00 —
1 pc	Front n/s fender sticker — <i>X</i>	\$ 30.00
	Sundry <i>Nil</i>	\$ <del>50.00</del> <i>20</i>
	To check wheel alignment	\$ <del>80.00</del> <i>60</i>
	To labour charge for dismantle and renew the accident damaged parts, including knock-out, straighten, repair, reshape and adjust of the same	\$ <del>650.00</del> <i>400</i>
	To putty and spray painting on front bumper, front n/s fender	\$ <del>400.00</del> <i>360</i>
	To apply rustproofing on the repaired and replaced panels.	\$ <del>120.00</del> <i>20</i>
		\$ 3,526.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*12/3/18*  
*continued up to \$2400 / 3A*

*Kelvin LKK*  
*5/2/18 1026*  
*3 B22*  
*43*  
*After Repair p.k.*

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

8-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8619 H

1 pc	Front n/s wheel cover /	\$	116.00
1 pc	Front n/s fender /	\$	384.00
1 pc	Front n/s fender inner shield /	\$	120.00
1 pc	Front bumper /	\$	531.00
1 pc	Front bumper emblem /	\$	44.00
1 pc	Front bumper n/s side retainer @ \$16.00 /	\$	16.00
1 pc	Front bumper n/s protector @ \$51.00 /	\$	51.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00 /	\$	66.00
1 pc	n/s head lamp /	\$	1,028.00
		\$	<u>2,356.00</u>
		Less 10%	\$ 235.60
			<u>\$ 2,120.40</u>

### S/NETT

1 set	Front n/s fender inner shield clips /	\$	28.00
1 set	Front bumper clips /	\$	48.00
1 pc	Front n/s fender sticker X	\$	30.00
	Sundry	\$	<del>50.00</del> 20
	To check wheel alignment	\$	<del>80.00</del> 60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	<del>650.00</del> 400
	To putty and spray painting on front bumper, front n/s fender	\$	<del>400.00</del> 360
	To apply rustproofing on the repaired and replaced panels.	\$	<del>120.00</del> 20
		\$	<u>3,526.40</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LKK 14  
8/2/18 10:24  
3/17  
45  
APR - Repair p LKK

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Tuesday, 6 March, 2018 3:59 PM  
**To:** Gary Shi  
**Cc:** Admin A; Vic (LKKAuto); Asher Sng (LKKAuto)  
**Subject:** Your Ref: SHB 8619H\_ACCIDENT INVOLVING VEHICLES SHC 1992U AND SHB 8619H ON 07.02.18  
**Attachments:** SHC 1992U.MP4

Your Ref: SHB 8619H  
Our Ref: CC3/III18002635/K1hb3

Without Prejudice

Dear Gary,

ACCIDENT INVOLVING VEHICLES SHC 1992U AND SHB 8619H ON 07.02.18

We refer to the subject matter.

Please be informed that our principal is in the view that our Insured driver is not liable of this accident as it shows that our Insured vehicle was within its lane when your client moved out from stationary position. We attached a copy of our Insured's video footage for your reference.

As such, we have our principal's instruction and we are unable to look further into your claim.

We will now close this matter.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Print Received Message

This mail is associated with :

**\*SHB8619H (MCT18020246)  
[SHC1992U]**

TP

PREMIER TAXIS PTE LTD  
Feb 7 2018 3:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Premier Automotive Services Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 21/02/2018 09:31 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Maintained - SHB8619H - Claim Handler: Sherini Pillai

Maintained:Please reject based on video evidence.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2018 <a href="#">Edit Reg</a>		08 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	<b>SHB8619H</b>	Date of Loss:	07/02/2018 15:00 - :59						
Claim Type:	<b>TP / MCT18020246</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHC1992U</b>	Policy No. (Claimant):	5095103893						
	Excess:								
Repairer:	<b>Premier Automotive Services Pte Ltd (HQ)</b> 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sherini Pillai</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 21/02/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (22/03/2018): <b>Submit report</b></li> <li>III_SG (21/02/2018): <b>Alert - Adj Mandate Maintained - SHB8619H - Claim Handler: Sherini Pillai</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SHB8619H (MCT18020246)**  
**[SHC1992U]**  
**TP**  
**PREMIER TAXIS PTE LTD**  
**Feb 7 2018 3:00PM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**Premier Automotive Services Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
<b>Video</b>									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print						
1	21/02/18 09:30	Video - Accident		Load MP4							
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
2	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
3	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
4	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
5	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
6	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
7	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
8	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
9	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
10	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
11	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
12	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
13	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
14	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
15	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
16	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
17	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
18	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
19	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
20	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
21	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
22	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
23	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
24	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
25	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
26	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
27	09/02/18 17:33	General View		Load JPG	<input checked="" type="checkbox"/>						
28	12/03/18 08:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
29	12/03/18 08:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
30	12/03/18 08:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
31	12/03/18 08:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						

Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 09:28	TP ESTIMATE- MARKED		Load PDF	
2	12/02/18 09:28	TP GIA REPORT		Load PDF	
3	06/03/18 16:02	EMAIL TO TP REJECT CLAIM		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 08:50	Singapore Accident Statement		Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18002635/K1HB3Q2

Date: 29/03/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SHB8619H Insured Vehicle No: SHC1992U  
 Date of Loss: 07/02/2018 Nature of Claim: TP Claim No: MCT18020246

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHB8619H  
 Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDDH308031  
 Reg. Date: 28/10/2013 (Man. Year: 2013) Chassis No: KNAGM414ME5448120  
 Colour: Silver Odometer: 519804 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16  
 Front Left Side: Maxxis 7 mm Rear Left Side: Maxxis 7 mm  
 Front Right Side: Maxxis 7 mm Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	2,276.40	2,216.40	60.00	2.64	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,250.00	840.00	410.00	32.80	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>3,526.40</b>	<b>3,056.40</b>	<b>470.00</b>	<b>13.33</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>			
	(S\$)	3,526.40	2,400.00	1,126.40	31.94
	+ GST 7.00/7.00% (S\$)	246.85	168.00	78.85	31.94
	<b>Nett Amount (S\$)</b>	<b>3,773.25</b>	<b>2,568.00</b>	<b>1,205.25</b>	<b>31.94</b>

## INSPECTION

Date of Assignment: 08/02/2018  
 Date Inspected: 08/02/2018 Inspected At: Premier Automotive Services Pte Ltd (HQ)  
 23 Changi South Ave 2, #01-02  
 Singapore 486443  
 Estimated Period of Repair: 3.0 days

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2018)
<b>Parts:</b> 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHB8619H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S WHEEL COVER	Grazed	116.00 FL	*116.00 FL
2	1		*FRONT N/S FENDER	Dented	384.00 FL	*384.00 FL
3	1		*FRONT N/S FENDER INNER SHIELD	Torn	120.00 FL	*120.00 FL
4	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
5	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
6	1		*FRONT BUMPER N/S SIDE RETAINER	Cracked	16.00 FL	*16.00 FL
7	1		*FRONT BUMPER N/S PROTECTOR	Cut	51.00 FL	*51.00 FL
8	1		*FRONT BUMPER N/S FOG LAMP COVER	Cut	66.00 FL	*66.00 FL
9	1		*N/S HEAD LAMP	Grazed	1,028.00 FL	*1,028.00 FL
10	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	28.00 FS	*28.00 FS
11	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
12	1		*FRONT N/S FENDER STICKER	Not Necessary	30.00 FS	*- FS
13	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS
<b>Sub Total (\$\$)</b>					<b>2,512.00</b>	<b>2,452.00</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)					235.60	235.60
<b>Total Parts (\$\$)</b>					<b>2,276.40</b>	<b>2,216.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	60.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR RESHAPE AND ADJUST OF THE SAME	New	650.00	400.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER	New	400.00	360.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,250.00</b>	<b>840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >