

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8619 H

1 pc	Front n/s wheel cover ✓	\$	116.00
1 pc	Front n/s fender ✓	\$	384.00
1 pc	Front n/s fender inner shield ✓	\$	120.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper n/s side retainer @ \$16.00 ✓	\$	16.00
1 pc	Front bumper n/s protector @ \$51.00 ✓	\$	51.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00 ✓	\$	66.00
1 pc	n/s head lamp ✓	\$	1,028.00
		\$	2,356.00
	Less 10%	\$	235.60
		\$	2,120.40

S/NETT

1 set	Front n/s fender inner shield clips ✓	\$	28.00
1 set	Front bumper clips ✓	\$	48.00
1 pc	Front n/s fender sticker X	\$	30.00
	Sundry	\$	50.00 20
	To check wheel alignment	\$	80.00 60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	650.00 450
	To putty and spray painting on front bumper, front n/s fender	\$	400.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 20
		\$	3,526.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin Kkky
8/2/18 10:06
3/1/18
45
After Repair photo