

Alg-LVP

DATE 2/8/2018 10:53

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Report ?			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Clips 10 pcs X			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,858.35
	LESS 20%			\$ 371.67
	DISCOUNTED TOTAL			\$ 1,486.68
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 385.70
	Labour Charge			100
	Panel Beating (Repair)			\$ 350.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 2,572.38
	Kalvin Kelly M 8/2/18 1230 hrs 2 Day, P/P After Repair photo			
	LKK Auto Consultants hence notify the Repairer of the following:			
	To resurvey before/after spray painting			
	To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	No illegal modification(s) is allowed			
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature.			
	Date.			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			