

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

ALT/LKK

TZ

VEHICLE NO : SHD 3370X

DATE 2/8/2018 12:13

MAKE :

WHOLE LEFT Side

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper (LH) ✓			\$ 603.60
	Rear Door (LH) ✓			\$ 1,351.10
	Rear Door 1/4 Glass (LH) ✓			\$ 109.45
	Rear Door Outer Moulding (LH) ✓			\$ 212.15
	Rear Door Outer Handle (LH) ✓			\$ 41.40
	Rear Door W/Screen Black Cover (LH) ✓			\$ 14.40
	Front Door Glass (LH) X repair			\$ 379.55
	Front Door Outer Moulding (LH) ✓			\$ 63.70
	Front Door Mirror (LH) ✓			\$ 980.50
	Front Door Black Cover (LH) ✓			\$ 14.40
	SUB TOTAL			\$ 3,770.25
	LESS 20%			\$ 754.05
	DISCOUNTED TOTAL			\$ 3,016.20
	Rear Door Tel No. Sticker/Apps (LH) ✓			\$ 80.00
	Front Door Coloured Comfort Logo (LH) ✓			\$ 75.00
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 900.00 600
	Spray Painting Charge			\$ 1,000.00 900
	Wiring Charge			\$ 50.00 X
	Tuff Kote			\$ 50.00 20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove/Refix Rear Windscreen Glass			\$ 120.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 X
	Transfer of Door			\$ 120.00 50
	TOTAL LABOUR			\$ 2,510.00
	ESTIMATE TOTAL			\$ 5,681.20

1 call in (LKK)
8/2/18 15:05 hr.
3 Days.
PIP
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.