

INS. CASE OWNER

June

CC 6 / CTI1800 0642, AF16312

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

8/2/18

Pohkin

Date / Time:

8/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 3256J

Name of Insured:

Sonia Penn

Insured Tel No.:

HP:

91052835

Excess Sec II :\$

D.O.A.:

6/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

CNM60046502

Policy No.:

Dmpcswito 4651201

Make / Model:

Toyota

Place of Accident:

IDE TMS Panyabon Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT (YES / NO) : TP GIA REPORT (YES / NO)

Insured Liability:

%

Final ? Yes / No

PC 5983A

GX 678E

SLK 3256J

SGH 2237X



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

MIT

TP

Date / Time	STAGE	DATE / PIC
17/4/18	Non-Reporting ltr (1st):	
2/4/18	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	7 2/4/18
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: 28/4/2018 Sent By: COK		
FINALIZATION Date/Time: Confirm with: Confirm by: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Repair Cost: S\$ 11,000.00 (10 days) Reduction: 61.92 %		
FINAL SETTLEMENT Date/Time: Confirm with: Confirm by: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28		
Repair Cost: S\$ 11,000.00		
Loss of Rental (LOR): S\$ - (days)		
Loss of Use (LOU): S\$ 960.00 (\$ 80.00 x 12 days)		
Loss of Income (LOI): S\$ - (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search: S\$ 7.45		
Medical: S\$ -		
Disbursement: S\$ - (e.g. Tow/Independent)		
Legal Cost: S\$ -		
Total: S\$ 11,967.45 Global Sum S\$: Email <input type="checkbox"/> Call <input type="checkbox"/>		
FINAL PAYMENT Date/Time: Confirm with: Confirm by: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: S\$ 11,967.45 Name 1: Hew Hock Teck Motor Pte Ltd		
Payee 2: (Strike if N.A.) S\$ Name 2:		
Payee 3: (Strike if N.A.) S\$ Name 3:		

REF:

Surveyor

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH2237X

Yr Regn:

2006, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish.

C.C. 1294

Colour:

White.

A/C: Insured / Std / NI / NA

Sp. Reading

167108

T/Radio: Insured / Std / NI / NA

Eng/No:

ZNE100298397

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17-

R:

225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

08/02/18

Survey held at

NHT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Change.

MV: 28K

PV: 16K.

Nett: 12K

45167,000.00 (Redd. 17,883.20 / 61.92%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18002642/Ayb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-02-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 3256J	Veh. Inspected	SGH 2237X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/02/2018	Inspection Date	08/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Toyota Wish

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾

Advanced
Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Wish 1.8A Aerosports (COE
till 08/2021)

Add to Shortlist

Toyota Wish 1.8A (COE till
07/2021)

Add to Shortlist

Toyota Wish 1.8A (COE till
03/2021)

Add to Shortlist

Toyota Wish 1.8A (COE till
03/2021)

Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$30,000	\$28,838	\$29,300	\$27,888
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	28-Aug-2006	07-Jul-2006	25-Mar-2006	23-Mar-2006
Manufactured	2006	2006	2006	2005
Mileage	-	169,000 km	160,000 km	24,600 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,794 cc	1,794 cc	1,794 cc	1,794 cc
Road Tax	\$1,166 /yr	\$1,166 /yr	\$1,166 /yr	\$1,166 /yr
Power	97.0 kW (130 bhp)	97.0 kW (130 bhp)	97.0 kW (130 bhp)	97.0 kW (130 bhp)
Curb Weight	1,300 kg	1,300 kg	1,300 kg	1,300 kg
Features	Equipped With Auto Headlamps, Optron Meter, Rear Disc Brakes, GPS Headunit And Sound System, New 18 Inch Tyres And Collollers.	16 Valves VVTi DOHC Engine, Best Fuel Efficiency MPV, 130Bhp, Steptronic Auto Transmission, Dual Airbags, ABS, Digital Auto Climate Aircon.	Four Speed Auto Transmission, 1.8L DOHC VVT-i Engine, Digital Auto Climatic Aircon Control, 7 Seater.	Four Speed Auto T DOHC VVT-i Engine, Aircon Control, 7 S
Accessories	-	7 Seater, Knockdown Rear Seats, Double Din Entertainment System, Sports Rims, Beautiful Interior, Reverse Sensors And Solar Film.	Sports Rims, Parking Sensors, Hi-Fi System, Central Locking, Rear Knockdown Seats.	Sports Rims, Parkin Reverse Camera, P-Locking, Rear Knock
Description	Beautiful Red Unit, Well Maintained By Owner. Selling Due To Upgrading To Bigger MPV. Highly Recommended For Big Family User. Spacious, Efficient And Reliable. Trade In Welcome! Negotiable. Please Call To Arrange For Viewing!	Tip Top Condition, 100% In House Loan, Low Down Payment, Don't Need Guarantor's No Repairs Need! We Deliver Our Promise! High Trade In Most Welcome! Flexible Bank/In House Loan Available! View To Believe! Don't Miss, Call Today!	Grey Toyota Wish, Spacious And Reliable, Tip Top Condition, Well Maintained, Fussy Owner, Paintwork 97%, Engine Very Clean, New Tires.	Spacious And Relia Condition, Drive Ti Plus). Well Maintai
COE	\$27,232	\$25,815	\$25,466	\$25,466
OMV	\$22,064	\$18,660	\$20,676	\$19,978
ARF	\$24,271	\$20,526	\$22,744	\$21,976
Depreciation	\$8,450 /yr	\$8,460 /yr	\$9,380 /yr	\$8,940 /yr
No. of Owners	5	3	6	3
Type of Vehicle	MPV	MPV	MPV	MPV
Category	COE Car, Consignment Car	COE Car	COE Car, Direct Owner Sale	COE Car, Direct Ov Mileage Car
Availability	Available	Available	Available	Available
Remarks	COE expiry date 2021-03-22	COE expiry date 2021-03-22	COE expiry date 2021-03-22	COE expiry date 2021-03-22

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 4822D

Vehicle Details

Vehicle No.: SGH2237X

Vehicle to be Exported: Yes

Intended De-registration Date: 08 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: WISH 1.8 A

Primary Colour: Blue

Manufacturing Year: 2006

Engine No.: 1ZZ2527137

Chassis No.: ZNE100298397

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$21,237.00

Original Registration Date: 02 Jun 2006

First Registration Date: 02 Jun 2006

Transfer Count: 5

Actual ARF Paid: \$23,361.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$16,069.00
Total Rebate Amount:	\$16,069.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4822D

Vehicle Details

Vehicle No.:	SGH2237X
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	1ZZ2527137
Chassis No.:	ZNE100298397
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$21,237.00
Original Registration Date:	02 Jun 2006
First Registration Date:	02 Jun 2006
Transfer Count:	5
Actual ARF Paid:	\$23,361.00


Intended PARF Rebate Details

PARF Eligibility:	Forfeited
-------------------	-----------

PARF Eligibility Expiry Date:	-
-------------------------------	---

PARF Rebate Amount:	\$0.00
---------------------	--------

Intended COE Rebate Details



COE Expiry Date:	01 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$16,069.00
Total Rebate Amount:	\$16,069.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Feb 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

China Taipei

DIVINE N DYNAMIC PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

08/02/2018

TP China

Jan

48 DAYS

25 - 12200

Accident date: 07/02/2018

Estimated repair cost for vehicle no: SGH2237X TOYOTA WISH 1.8 A '06

(14 day)

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid Distorted.		\$1,315.20 1248
2	2	Rear Boot Lid Hinge ne ne	\$141.40	\$282.80 x
3	2	Rear Boot Lid Shock Absorber Bent	\$371.85	\$743.70 ✓
4	1	Rear Boot Lid Emblem Logo ne		\$51.10 ✓
5	1	Rear Boot Lid Centre Chrome Moulding Cracked		\$274.45 ✓
6	4	Rear Boot Lid Centre Chrome Moulding Clip ne	\$6.50	\$39.00 10
7	1	Rear Boot Lid Number Plate Bent		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp ne ne	\$105.10	\$210.20 x ✓
9	1	Rear Boot Lid Outer Lock Switch ne		\$238.60 x
10	1	Rear Boot Lid Inner Lock Dented		\$374.45 ✓
11	1	Rear Boot Lid Inner Rubber Lt		\$381.90 ✓
12	1	Rear Boot Lid Inner Trim Board Replaced		\$781.45 38510
13	1	Rear Boot Lid Wiper Link ?		\$122.25 x
14	1	Rear Boot Lid Wiper Arm ne		\$181.90 ✓
15	1	Rear Boot Lid Wiper Arm Cover		\$122.35 x
16	1	Rear Boot Lid Wiper Motor ne ne		\$389.20 x
17	1	Rear Boot Lid Windscreen ne ne		\$971.80 x ✓
18	1	Rear Boot Lid Windscreen Top Seal 2 new		\$125.00 ✓
19	2	Rear Boot Lid Windscreen Side Moulding	\$65.00	\$130.00 ✓
20	1	Rear Boot Lid Camera (Special Nett) Damaged.		\$550.00 380/50
21	2	Rear Tail Lamp Cracked	\$387.40	\$774.80 ✓
22	4	Rear Tail Lamp Clip ne	\$8.00	\$32.00 ✓
23	1	Rear L/H Tail Lamp Panel Dented		\$378.85 ✓
24	1	Rear L/H Tail Lamp Inner Panel Repair		\$477.60 x
25	1	Rear Bumper Distorted		\$625.20 ✓
26	8	Rear Bumper Clip ne	\$6.50	\$52.00 30
27	2	Rear Bumper Bracket Dented	\$88.60	\$177.20 ✓
28	2	Rear Bumper Side Retainer ne	\$132.10	\$264.20 36.20

29	2	Rear Bumper Side Reflector LA ut	\$141.45	\$282.90 8550
30	1	Rear Bumper Reverse Sensor (Special Nett) Dugd		\$380.00 200(50)
31	1	Rear L/H Bumper Mud Shield 2 new		\$172.25 x
32	4	Rear L/H Bumper Mud Shield Clip	\$6.50	\$26.00 x
33	1	Rear L/H Fender Buckled		\$972.45 ✓
34	1	Rear L/H Fender Air Duct 2 new		\$100.40 x
35	1	Rear L/H Fender Glass Assy		\$396.20 x ✓
36	2	Rear Fender Inner Trim Board Delnd	\$471.45	\$942.90 ✓
37	1	Rear End Panel Outer } Discolored		\$519.80 ✓
38	1	Rear End Panel Inner		<u>\$780.50</u> 49650
39	1	Rear End Panel Top Garnish Deformed		\$374.45 ✓
40	1	Rear Floor Panel New		\$980.30 x
41	2	Rear Floor Panel Top Cover Delnd	\$282.10	\$564.20 28210
42	2	Rear Floor Panel Side Cover LH Delnd	\$168.40	\$336.80 16840
43	1	Rear Floor Panel Inner Garnish Delnd		\$291.40 ✓
44	1	Rear Floor Panel & End Panel Sealant New		\$450.00 60(50)
45	1	Rear Exhaust Seal		\$961.20 ✓
46	2	Rear Exhaust Mounting New	\$67.60	\$135.20 x
47	1	Rear Centre Exhaust New		\$1,714.20 x ✓
48	1	Rear Spare Tyre Bracket New		\$194.85 x

1102265 S-N 640 Subtotal:- \$20,693.20
826698

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit roof lining	\$380.00 X
To remove & refit petrol tank	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit camera	\$180.00 50
To remove & refit fender glass	\$120.00 60
Gum	\$50.00 30
To remove & refit rear windscreen	\$120.00 100
Gum	\$50.00 ✓

To remove & refit rear & centre exhaust

~~\$380.00~~ 80

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$100.00~~ 50

Tuff kote

3220

~~\$150.00~~ 60

Panel beating

2000

~~\$3,500.00~~ 1300

Spray painting

1800

~~\$2,400.00~~ 1200Subtotal:- \$8,190.00Total:- \$28,883.20

total 12126.98
4/5 9.7K.
080 days



新福德車廠私人有限公司

China Taipei

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

DIVINE N DYNAMIC PTE LTD

08/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TECHING

Jan

Accident date: 07/02/2018

Estimated repair cost for vehicle no: SGH2237X TOYOTA WISH 1.8 A '06

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid Distorted.		\$1,315.20
2	2	Rear Boot Lid Hinge New	\$141.40	\$282.80
3	2	Rear Boot Lid Shock Absorber Bent	\$371.85	\$743.70
4	1	Rear Boot Lid Emblem Logo New		\$51.10
5	1	Rear Boot Lid Centre Chrome Moulding Cracked		\$274.45
6	4	Rear Boot Lid Centre Chrome Moulding Clip New	\$6.50	\$39.00
7	1	Rear Boot Lid Number Plate Bent		\$50.00
8	2	Rear Boot Lid Number Plate Lamp New	\$105.10	\$210.20
9	1	Rear Boot Lid Outer Lock Switch Bnd		\$238.60
10	1	Rear Boot Lid Inner Lock Bnd		\$374.45
11	1	Rear Boot Lid Inner Rubber Cut		\$381.90
12	1	Rear Boot Lid Inner Trim Board Del		\$781.45
13	1	Rear Boot Lid Wiper Link 2		\$122.25
14	1	Rear Boot Lid Wiper Arm 1st		\$181.90
15	1	Rear Boot Lid Wiper Arm Cover 1st		\$122.35
16	1	Rear Boot Lid Wiper Motor New		\$389.20
17	1	Rear Boot Lid Windscreen Cut		\$971.80
18	1	Rear Boot Lid Windscreen Top Seal 3mm		\$125.00
19	2	Rear Boot Lid Windscreen Side Moulding 3mm	\$65.00	\$130.00
20	1	Rear Boot Lid Camera (Special Nett) Damaged.		\$550.00
21	2	Rear Tail Lamp Cracked	\$387.40	\$774.80
22	4	Rear Tail Lamp Clip New	\$8.00	\$32.00
23	1	Rear L/H Tail Lamp Panel Dented		\$378.85
24	1	Rear L/H Tail Lamp Inner Panel Repair		\$477.60
25	1	Rear Bumper Distorted		\$625.20
26	8	Rear Bumper Clip New	\$6.50	\$52.00
27	2	Rear Bumper Bracket Dented	\$88.60	\$177.20
28	2	Rear Bumper Side Retainer New	\$132.10	\$264.20

1248

x

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

29	2	Rear Bumper Side Reflector <i>LH ut</i>	\$141.45	\$282.90 <i>8550</i>
30	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dmgd.</i>		\$380.00 <i>200(s)</i>
31	1	Rear L/H Bumper Mud Shield <i>green</i>		\$172.25 ✓
32	4	Rear L/H Bumper Mud Shield Clip	\$6.50	\$26.00 ✓
33	1	Rear L/H Fender <i>Buckled</i>		\$972.45 ✓
34	1	Rear L/H Fender Air Duct <i>green</i>		\$100.40 ✓
35	1	Rear L/H Fender Glass Assy		\$396.20 ✓
36	2	Rear Fender Inner Trim Board <i>delnd</i>	\$471.45	\$942.90 ✓
37	1	Rear End Panel Outer <i>{ Distorted</i>		\$519.80 ✓
38	1	Rear End Panel Inner		<u>\$780.50</u> <i>4655</i>
39	1	Rear End Panel Top Garnish <i>deformed</i>		\$374.45 ✓
40	1	Rear Floor Panel <i>Reps</i>		\$980.30 ✓
41	2	Rear Floor Panel Top Cover <i>delnd</i>	\$282.10	\$564.20 <i>28210</i>
42	2	Rear Floor Panel Side Cover <i>LH delnd</i>	\$168.40	\$336.80 <i>16840</i>
43	1	Rear Floor Panel Inner Garnish <i>delnd</i>		\$291.40 ✓
44	1	Rear Floor Panel & End Panel Sealant <i>in</i>		\$450.00 <i>60(s)</i>
45	1	Rear Exhaust <i>Rept</i>		\$961.20 ✓
46	2	Rear Exhaust Mounting <i>He n</i>	\$67.60	\$135.20 ✓
47	1	Rear Centre Exhaust <i>He n</i>		\$1,714.20 ✓
48	1	Rear Spare Tyre Lock Regulator <i>Damaged.</i>		\$388.90 ✓

1262195 S.N 640 Subtotal:- \$20,693.20
946646

Labour charges

To remove & refit cushion	\$280.00 <i>80</i>
To remove & refit roof lining	\$380.00 <i>X</i>
To remove & refit petrol tank	\$280.00 <i>80</i>
To remove & refit reverse sensor	\$100.00 <i>50</i>
To remove & refit camera	\$180.00 <i>50</i>
To remove & refit fender glass	\$120.00 <i>60</i>
Gum	\$50.00 <i>30</i>
To remove & refit rear windscreen	\$120.00 <i>100</i>
Gum	\$50.00 ✓

To remove & refit rear & centre exhaust

~~\$380.00~~ 80

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$100.00~~ 80

Tuff kote

3830

~~\$150.00~~ 60

Panel beating

~~\$3,500.00~~ 1300

Spray painting

~~\$2,400.00~~ 1200

Subtotal:- \$8,190.00

Total:- \$28,883.20

total 13736 246

y/s M.K.C.

10 Days

111C

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 12 February 2018 9:48 AM
To: Shu Pei (LKKAUTO)
Cc: Irene Tay
Subject: RE: Direct Settlement - Accident Involving SLK3256J (OI : CTI - SNM18D00765C02) and SGH2237X (TP : LKK REF -CC6/CTI18002642/Ayb3) on 07.02.2018
Attachments: MANC18020165-SLK3256J.pdf

Dear Shu Pei,

Kindly refer to the above attachment.

Thank you.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 12 February, 2018 9:25 AM
To: Lucas Lee
Cc: Irene Tay
Subject: RE: Direct Settlement - Accident Involving SLK3256J (OI : CTI - SNM18D00765C02) and SGH2237X (TP : LKK REF - CC6/CTI18002642/Ayb3) on 07.02.2018

Dear Lucas,

We refer to the below email.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]

Sent: Friday, 9 February 2018 1:59 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving SLK3256J (OI : CTI - SNM18D00765C02) and SGH2237X (TP : LKK REF - CC6/CTI18002642/Ayb3) on 07.02.2018

Dear Shu Pei,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Friday, 9 February, 2018 11:25 AM

To: Claims Dept of CTI

Cc: Irene Tay; Admin A; Jas Khine (LKKAuto); Thin Thin (LKKAuto)

Subject: Direct Settlement - Accident Involving SLK3256J (OI : CAI - TBA) and SGH2237X (TP : LKK REF - CC6/CTI18002642/Ayb3) on 07.02.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SGH 2237X at M/s New Hock Teck Motor Pte Ltd.

Enclosed herewith a copy of TP's GIA report for your perusal.

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD

3 Anson Road #16-00 Springleaf Tower Singapore 079908
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D00765/C02/7**

Date: **09 FEBRUARY 2018**

via Ordinary & Registered Mail

SONG PENG
BLK 196B PUNGGOL FIELD
#13-497
SINGAPORE 822196

Dear Sir / Madam

ACCIDENT INVOLVING SLK3256J AND SGH2237X ON 07 FEBRUARY 2018
ALONG TPE TOWARDS PIE BEFORE PUNGGOL WAY

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SGH2237X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JAS
Ref : CC6/CT118002642/AYB3
Contact No : 68412928
via Email : JAS@LKKAUTO.COM

CC : Agent - (AN0590A) - TECK WEI CREDIT PTE LTD

F02/LKKDSANR-2013

Poh Kin (LKKAuto)

From: Admin nht <admin@nhtmotor.com>
Sent: Thursday, 13 December 2018 12:01 PM
To: Poh Kin (LKKAuto)
Cc: Chloe
Subject: Re: SGH2237X CLAIMING SLK3256J DOA 07.02.18 *LKK REF: CC6/CTI18002642/Amb3

Categories: clear

Without Prejudice

Hi Poh Kin

We accept your offer as \$11,967.45

Please send us your discharge voucher for close case, thanks.



On Thu, Dec 13, 2018 at 10:55 AM Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

WITHOUT PREJUDICE

Our Ref: CC6/CTI18002642/Afb3

Your Ref: NPLT1803-0051/SGH 2237X

Dear Sukyi,

We refer to the above matter.

Thank you for your patient waiting on this matter.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 13 December 2018 10:55 AM
To: 'Admin nht'
Cc: Chloe
Subject: RE: SGH2237X CLAIMING SLK3256J DOA 07.02.18 *LKK REF: CC6/CTI18002642/Amb3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/CTI18002642/Afb3
Your Ref: NPLT1803-0051/SGH 2237X

Dear Sukyi,

We refer to the above matter.

Thank you for your patient waiting on this matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement as below:

1. Cost of Repair	S\$ 11,000.00
2. Loss of Use (\$80.00 x 12 days)	S\$ 960.00
3. LTA search fee	<u>S\$ 7.45</u>
	<u>S\$ 11,967.45</u>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAUTO)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, 13 December 2018 10:46 AM
To: Poh Kin (LKKAUTO); Admin A
Cc: Irene Tay; Alfred Toh; Hsiao Tong (LKKAUTO); KKLau
Subject: RE: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving SLK 3256J (CTI: SNM18D00765C02/6) and SGH 2237X (TP : LKK REF - CC6/CTI18002642/Amb3) on 07/02/2018

LKK REF - CC6/CTI18002642/Amb3
CTI REF - SNM18D00765C02/6 (SLK3256J)

Dear Poh Kin

We refer to your email of even date pertaining to the above matter.

Please proceed to resolve the property damage claim at \$11,967.45.

We await your payment advice to enable Irene to act accordingly.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Thursday, December 13, 2018 9:11 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>
Subject: <Urgent><Seek Mandate> Direct Settlement - Accident Involving SLK 3256J (OI: SNM18D00765C02/6) and

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 13 December 2018 9:11 AM
To: 'Claims Dept of CTI'
Cc: 'irene.tay@sg.cntaiping.com'; 'alfred.toh@sg.cntaiping.com'; Admin A
Subject: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving SLK 3256J (OI : CTI - SNM18D00765C02) and SGH 2237X (TP : LKK REF - CC6/CTI18002642/Amb3) on 07/02/2018
Attachments: LKK Adjustment Report.pdf; LKK Inspection Report.pdf; LKK RESURVEY PHOTO-AFTER REPAIR.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; TP LOD_SGH 2237X.pdf
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/CTI18002642/Amb3
Your Ref: SNM18D00765C02

Dear Sir/madam,

ROAD TRAFFIC ACCIDENT INVOLVING SLK 3256J (OI), SGH 2237X (TP) AND OTHERS ALONG TPE TOWARDS PUNGGOL ROAD ON 07/02/2018

We refer to the above matter.

Liability: The said chain collision involved FOUR vehicles whereby our insured was the SECOND vehicle was push forward by behind vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured(Mr Song) the nature of the accident and he's aware that NCD (if any) would be withheld for the time being.

We seek your approval to offer Third Party repairer "New Hock Teck Motor Pte Ltd" at \$ 11,967.45(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$29,076.35	\$ 11,000.00
2. Loss of Use	\$ 1,200.00 (12 days x \$120.00)	\$ 960.00 (12 days x \$80.00)
3. LTA search fee	\$ 7.45	\$ 7.45
Total	\$30,283.80	<u>\$11,967.45</u>

****10 days recommendation for repair + 2 day weekend = 12 days**

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 28 November 2018 6:21 PM
To: Claims Dept of CTI
Cc: 'irene.tay@sg.cntaiping.com'; Lucas Lee; Admin A
Subject: RE: Direct Settlement - Accident Involving SLK3256J (OI : CTI - SNM18D00765C02) and SGH2237X (TP : LKK REF -CC6/CTI18002642/Ayb3) on 07.02.2018
Attachments: LKK RESURVEY PHOTO.pdf, LKK SURVEY PHOTO.pdf, PRAF and COE rebate form.pdf, Preliminary Advice.pdf, TP Estimate-Marked.pdf

Importance: High

Our Ref: CC6/CTI18002642/Amb3
Your Ref: SNM18D00765C02

Dear Sir/Madam,

We refer to the above matter and below E-mail.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 12 February 2018 9:48 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving SLK3256J (OI : CTI - SNM18D00765C02) and SGH2237X (TP : LKK REF -CC6/CTI18002642/Ayb3) on 07.02.2018

Dear Shu Pei,

Kindly refer to the above attachment.

Thank you.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18002642/Afb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 18-12-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 3256J	Veh. Inspected	SGH 2237X	
Policy No.	DMPCSN1704531801	Coverage (\$)	0.00	
Claim No.	SNM18D00765/C02/6	Excess (\$)	0.00	
Assign From		Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ZNE100298397	Colour	WHITE	
Odometer	167108	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2018	Inspection Date	08/02/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 2237X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DISTORTED	1,315.20	1,248.00
2	REAR BOOT LID HINGE @\$141.40	NOT NECESSARY	282.80	-
2	REAR BOOT LID SHOCK ABSORBER @\$371.85	BENT	743.70	743.70
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	51.10	51.10
1	REAR BOOT LID CENTRE CHROME MOULDING	CRACKED	274.45	274.45
4	REAR BOOT LID CENTRE CHROME MOULDING CLIP @\$6.50	NECESSARY	39.00	10.00
1	REAR BOOT LID NUMBER PLATE	BENT	50.00	50.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$105.10	NOT NECESSARY	210.20	-
1	REAR BOOT LID OUTER LOCK SWITCH	DAMAGED	238.60	238.60
1	REAR BOOT LID INNER LOCK	DAMAGED	374.45	374.45
1	REAR BOOT LID INNER RUBBER	CUT	381.90	381.90
1	REAR BOOT LID INNER TRIM BOARD	DEFORMED	781.45	385.10
1	REAR BOOT LID WIPER LINK	NOT NECESSARY	122.25	-
1	REAR BOOT LID WIPER ARM	NOT NECESSARY	181.90	-
1	REAR BOOT LID WIPER ARM COVER	NOT NECESSARY	122.35	-
1	REAR BOOT LID WIPER MOTOR	NOT NECESSARY	389.20	-
1	REAR BOOT LID WINDSCREEN	CUT	971.80	971.80
1	REAR BOOT LID WINDSCREEN TOP SEAL	NECESSARY	125.00	125.00
2	REAR BOOT LID WINDSCREEN SIDE MOULDING @\$65.00	NECESSARY	130.00	130.00
2	REAR TAIL LAMP @\$387.40	CRACKED	774.80	774.80
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
1	REAR L/H TAIL LAMP PANEL	DENTED	378.85	378.85
1	REAR L/H TAIL LAMP INNER PANEL	TO REPAIR SEE LABOUR	477.60	-
1	REAR BUMPER	DISTORTED	625.20	625.20
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER BRACKET @\$88.60	DENTED	177.20	177.20
2	REAR BUMPER SIDE RETAINER @\$132.10	NECESSARY	264.20	136.20
2	REAR BUMPER SIDE REFLECTOR @\$141.45	N/S CUT	282.00	85.50
1	REAR L/H BUMPER MUD SHIELD	NOT NECESSARY	172.25	-

Report Ref No. CC6/CTI18002642/Afb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR L/H BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	26.00	-
1	REAR L/H FENDER	BUCKLED	972.45	972.45
1	REAR L/H FENDER AIR DUCT	NOT NECESSARY	100.40	-
1	REAR L/H FENDER GLASS ASSY	NOT NECESSARY	396.20	-
2	REAR FENDER INNER TRIM BOARD @\$471.45	DEFORMED	942.90	942.90
1	REAR END PANEL OUTER	DISTORTED	519.80	519.80
1	REAR END PANEL INNER	DISTORTED	780.50	496.50
1	REAR END PANEL TOP GARNISH	DEFORMED	374.45	374.45
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	980.30	-
2	REAR FLOOR PANEL TOP COVER @\$282.10	DEFORMED	564.20	282.10
2	REAR FLOOR PANEL SIDE COVER @\$168.40	N/S DEFORMED	336.80	168.40
1	REAR FLOOR PANEL INNER GARNISH	DEFORMED	291.40	291.40
1	REAR EXHAUST	BENT	961.20	961.20
2	REAR EXHAUST MOUNTING @\$67.60	NOT NECESSARY	135.20	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,714.20	-
1	REAR SPARE TYRE LOCK REGULATOR	DAMAGED	388.90	388.90
	LESS 25% DISCOUNT		-	-3,155.49
			19,506.35	9,466.46
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT LID CAMERA (SN)	DAMAGED	550.00	380.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	REAR FLOOR PANEL & END PANEL SEALANT (SN)	NECESSARY	450.00	60.00
			1,380.00	640.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION .		280.00	80.00
	TO REMOVE & REFIT ROOF LINNING.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT PETROL TANK .		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT CAMERA.		180.00	50.00
	TO REMOVE & REFIT FENDER GLASS.		120.00	60.00
	GUM.		50.00	30.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	100.00

Report Ref No. CC6/CT118002642/Afb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	GUM.		50.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .		380.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR L/H TAIL LAMP INNER PANEL AND REAR FLOOR PANEL.		3,500.00	1,500.00
	SPRAY PAINTING.		2,400.00	1,400.00
			8,190.00	3,630.00
GRAND TOTAL			29,076.35	13,736.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CC6/CT118002642/Afb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.