

REF:

CC3 / ALG18002657 / Adon2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

148055525156

Sum Insured:

Excess:

04/2/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

148K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 8/5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH2006X

Yr Regn:

2017 Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A5 SB

C.C 1984

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

3856

T/Radio: Insured / Std / NI / NA

Eng/No:

WAUZZZF51JA034333

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/02/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

08A19

SGH 2006X - X

26/2/18 @ 11.19am Informed Tony EX: 807 by email.

18/5/18 @ 3.44pm Confirmed with Mr Bos final Ag 8 5166-80, 4 days by email.

Utd 67363.20, 31.7

RECEIVED 25 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

user-00

Lump Sum / I.B.I. (\$

5166.80

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18002657/Aqb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 09-02-2018		
		Code : AIG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SGH 2006X	
Policy No.	1700062189	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	07/02/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 18 May 2018 3:24 PM
To: 'Boo seng yak'; SUR; Carrine Leong; Nora Khai
Subject: RE: FINALR EVISION SGH2006X - OD AIG - SURVEYED 7 FEB 18

Dear Mr Boo,

Confirm final fig \$5,166.80 before excess \$0 & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Saturday, 28 April 2018 5:06 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINALR EVISION SGH2006X - OD AIG - SURVEYED 7 FEB 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5166.80 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 26 February 2018 11:19 AM
To: Claims; 'Nora Khai'; SUR
Subject: RE: SGH 2006 X Own Damage Claims

Dear Tony,

Please be informed that the excess of above vehicle is \$0/-.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 20 February 2018 11:32 AM
To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SGH 2006 X Own Damage Claims

Dear Shiau Chan,

Attached is of police report of DL missing.

Thank you and wish you a happy and prosperous chinese new year.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9625I
Vehicle Details	
Vehicle No.:	SGH2006X
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVK047191
Chassis No.:	WAUZZZF51JA034333
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$38,865.00
Original Registration Date:	13 Oct 2017
First Registration Date:	13 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$41,411.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2027
PARF Rebate Amount:	\$31,058.00
Intended COE Rebate Details	
COE Expiry Date:	12 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$46,544.00
Total Rebate Amount:	\$77,602.00

The information contained herein is correct as at 09 Feb 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1459625I



Name

LEE KHENG HOCK

李 庆 福

Race

CHINESE

Date of birth

03-03-1961

Sex

M

S1459625I

Country/Place of birth

SINGAPORE

5770012



NRIC No. S1459625I



Date of issue

18-07-2017

Address

29 KEPPEL BAY VIEW

#20-87

SINGAPORE 098417



**SINGAPORE
POLICE FORCE**

**TRAFFIC POLICE
SINGAPORE POLICE FORCE**
10, UBI AVENUE 3
SINGAPORE 408865
Tel : 65470000
www.police.gov.sg

Private & Confidential

LEE KHENG HOCK

BLK 29 KEPPEL BAY VIEW UNIT 20-87
SINGAPORE 098417

Ans 3 09 OCT 1985



You will receive your photocard driving licence by registered post within 10 to ~~14~~ working days from the date of application unless you made a special request to collect at Traffic Police at the time of application

You can drive while awaiting the delivery of your photocard driving licence

Please turn overleaf for important notes.

S1459625I
(3)

C001333730

\$25/-

(Please do not detach)

**YOU CAN DRIVE WHILE AWAITING THE
DELIVERY OF YOUR PHOTOCARD
DRIVING LICENCE**

07/02/2018



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE KHENG HOCK
Period of Insurance : 13 Oct 2017 To 12 Oct 2018
Engine No. : CVK047191
Chassis No. : WAUZZZF51JA034333

Vehicle No. : SGH2006X
Policy No. : 1700062189
Endorsement No. :
Issued Date : 30 Oct 2017

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE KHENG HOCK - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125251

PREMIUM LEASING -LES
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Stefany Loh



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE KHENG HOCK
Period of Insurance : 13 Oct 2017 To 12 Oct 2018
Engine No. : CVK047191
Chassis No. : WAUZZZF51JA034333

Vehicle No. : SGH2006X
Policy No. : 1700062189
Endorsement No. :
Issued Date : 30 Oct 2017

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE KHENG HOCK - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125251

PREMIUM LEASING -LES

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Stefany Loh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0153/2018/GW
Date	:	3-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Teck Wei, Adrian
Address	:	29 Keppel Bay View #20-87 Singapore 098417
Telephone	:	HP +65 91919434
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SGH 2006 X
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	Oct-17
Engine No	:	CVK047191
Chassis No	:	WAUZZZF51JA34333
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Jan-18
Place of Accident	:	Traffic Junc & Lower Delta Road & Telok Biangahway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGH 2006 X.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door's multi lock system and power window devices.	S/N \$ 280.00	✓
2	To dismantle and renew rhs front door and wing mirror assy. Align to position. Reinstall all parts removed.	\$ 1,200.00	750, ✓
3	To respray rhs front door and wing mirror cover.	\$ 1,200.00	700, ✓ = 550 + 150
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGH 2006 X.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR -RH <i>Dented</i>	\$ 2,692.00 ✓	7153.60
2	FRONT OUTER DOOR SEAL-RH <i>new</i>	\$ 192.00 ✓	153.20
3	BONDING AGENT <i>new</i>	\$ 43.00 ✓	34.16 ✓
4	FRONT DOOR CATCH-RH <i>new</i>	\$ 105.00 X.	
5	FRONT EXTERIOR MIRROR MOUNTING-RH <i>combined</i>	\$ 959.00 ✓	767.20
6	FRONT MIRROR CAP-RH <i>Ryis</i>	\$ 217.00 X.	
7	FRONT DOOR TRIM -RH <i>new</i>	\$ 138.00 -	110.40
8	SIGN " CAUTION " <i>new new</i>	\$ 12.00 -	X
11	SUNDRIES <i>new</i>	\$ 300.00 ?	26.74 ✓
TOTAL SPARE PARTS CHARGES		\$ 4,658.00	
TOTAL LABOUR CHARGES		\$ 2,872.00	
GRAND TOTAL		\$ 7,530.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Lin
: 07/02/18

: Authorised Period, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: _____

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Restrictions

Illustration

SG

MG

Year

Model

857-042

57

8

2017

A5CO

16:38

07.02.2018


UPD

1210

ETKA

Audi

86H2006X



Pos	Part Number	Description	Remark	Qty	Model
(1)	8W8 857 410 M	Exterior mirror Interior mirror see illustration:	857-045 right	1	PR-K8R
(1)	11/16 989	Exterior mirror mounting with electric adjusting unit	right	1	PR-6XF, 6XL, KA0, KA2
(1)	8W8 857 410 N	Satin black	right	1	PR-6XE, 6XK, KA6
(1)	11/16 989	Exterior mirror mounting with electric adjusting unit	right	1	PR-6XF, 6XL, KA6
2	8T0 959 578	Adjusting unit with motor for exterior mirror	left	1	PR-6XC, 6XD, 6XE, 6XK
(2)	8T0 959 578	Adjusting unit with motor for exterior mirror	left	1	PR-6XC, 6XD
(2)	8T0 959 578 A	Adjusting unit with motor for exterior mirror	left	1	PR-6XF, 6XL, 6XM
(2)	8T0 959 578 A	Adjusting unit with motor for exterior mirror	left	1	PR-6XE, 6XK, 6XF, 6XL
(2)	8T0 959 577	Adjusting unit with motor for exterior mirror	right	1	PR-6XC, 6XD
(2)	8T0 959 577	Adjusting unit with motor for exterior mirror	right	1	PR-6XC, 6XD, 6XK, 6XE
(2)	8T0 959 577 A	Adjusting unit with motor for exterior mirror	right	1	PR-6XE, 6XF, 6XK, 6XL, 6XM

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0153/2018/GW
Date	:	3-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - Jb - 28 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Teck Wei, Adrian
Address	:	29 Keppel Bay View #20-87 Singapore 098417
Telephone	:	HP +65 91919434
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SGH 2006 X
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	Oct-17
Engine No	:	CVK047191
Chassis No	:	WAUZZZF51JA34333
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Jan-18
Place of Accident	:	Traffic Junc & Lower Delta Road & Telok Biangahway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGH 2006 X.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door's multi lock system and power window devices.	S/N \$ 280.00	\$ 280.00
2	To dismantle and renew rhs front door and wing mirror assy. Align to position. Reinstall all parts removed.	\$ 1,200.00	\$ 750.00
3	To respray rhs front door and wing mirror cover.	\$ 1,200.00	\$ 700.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,872.00	\$ 1,922.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGH 2006 X.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR -RH	\$ 2,692.00	\$ 2,153.60
2	FRONT OUTER DOOR SEAL-RH	\$ 192.00	\$ 153.20
3	BONDING AGENT	\$ 43.00	\$ 34.16
4	FRONT DOOR CATCH-RH	\$ 105.00	
5	FRONT EXTERIOR MIRROR MOUNTING-RH	\$ 959.00	\$ 767.20
6	FRONT MIRROR CAP-RH	\$ 217.00	
7	FRONT DOOR TRIM -RH	\$ 138.00	\$ 110.40
8	SIGN " CAUTION "	\$ 12.00	
11	SUNDRIES	\$ 300.00	\$ 26.24
TOTAL SPARE PARTS CHARGES		\$ 4,658.00	\$ 3,244.80
TOTAL LABOUR CHARGES		\$ 2,872.00	\$ 1,922.00
GRAND TOTAL		\$ 7,530.00	\$ 5,166.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGH 2006 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0153/2018/MAS

23 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SGH 2006 X, Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SGH 2006 X**, claimant, **Mr. Lee Kheng Hock**, please find the related document per attached.

1. A copy of the Original invoice no. 85012530 – S\$5,528.48
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGH 2006 X

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		09 Feb 2018 13:25 Edit Adj Rpt	S\$5,166.80 Edit Estimates	S\$5,166.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	LEE KHENG HOCK, ID: S1459625I, Tel: +6591919434, Email: leekhenghock@singhealth.com.sg																							
Vehicle Reg. No.:	SGH2006X	Date of Loss:	31/01/2018 18:00 - :59 [3 Months and 18 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	OD / 1480555251SG	Policy/Cover Note No.:	(Comprehensive)																					
		Excess:	S\$0.00																					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911																							
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/02/2018]																							
Driver/Custodian:	LEE KHENG HOCK (56 / Male), NRIC: S1459625I, Tel: +6591919434																							
			View All	Compose Case Mail																				
ASSOCIATED MAIL RECEIVED																								
AIG_SG (26/02/2018): SGH2006X / OD / 31/01/2018 / Coverage & Excess update																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SGH2006X (1480555251SG)
 OD
 Jan 31 2018 6:40PM
 [LEE KHENG HOCK]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
															1 per page		
Video															Thumbnail Print		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													1 Load MP4		
1	01/02/18 22:45	Video - Accident [Linked Accident Report Documents]													3 per page		
Photos/Images															Thumbnail Print		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													1 Load JPG		
1	16/05/18 01:41	General View													1 Load JPG		
2	16/05/18 01:41	General View													1 Load JPG		
3	16/05/18 01:41	General View													1 Load JPG		
4	16/05/18 01:41	General View													1 Load JPG		
5	16/05/18 01:41	General View													1 Load JPG		
6	16/05/18 01:41	General View													1 Load JPG		
7	16/05/18 01:41	General View													1 Load JPG		
8	16/05/18 01:41	General View													1 Load JPG		
9	16/05/18 01:41	General View													1 Load JPG		
10	16/05/18 01:41	General View													1 Load JPG		
11	16/05/18 01:41	General View													1 Load JPG		
12	16/05/18 01:41	General View													1 Load JPG		
Documentation															1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail Print		
1	09/02/18 14:38	Singapore Accident Statement													1 Load PDF		
2	09/02/18 14:38	Certificate of Insurance													1 Load PDF		
3	09/02/18 14:38	WORKSHOP ESTIMATE													1 Load PDF		
4	23/02/18 17:22	TRAFFIC POLICE LETTER													1 Load PDF		
5	30/05/18 16:08	WORKSHOP INVOICE													1 Load PDF		
6	30/05/18 16:09	DISCHARGE VOUCHER													1 Load PDF		

Linked Accident Report Documents

			View Use Viewer		
			1 per page		
Video			Thumbnail Print		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 Load MP4		
1	01/02/18 22:45	Video - Accident			
Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail Print		
1	01/02/18 22:45	Accident Statement	1 Load HTM		
Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail Print		
1	01/02/18 22:34	Accident Photo	1 Load JPG		
2	01/02/18 22:34	Accident Photo	1 Load JPG		
3	01/02/18 22:34	Accident Photo	1 Load JPG		
4	01/02/18 22:34	Accident Photo	1 Load JPG		
5	01/02/18 22:34	Accident Photo	1 Load JPG		
6	01/02/18 22:34	Accident Photo	1 Load JPG		
7	01/02/18 22:34	Accident Photo	1 Load JPG		
8	01/02/18 22:34	Accident Photo	1 Load JPG		

9	01/02/18 22:34	Accident Photo		Load JPG	☒
10	01/02/18 22:34	Accident Photo		Load JPG	☒
11	01/02/18 22:34	Accident Photo		Load JPG	☒
12	01/02/18 22:34	Accident Photo		Load JPG	☒
					1 per page ☒
Documentation					
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	01/02/18 22:38	Sketch Plan		Load JPG	☒
2	01/02/18 22:38	Sketch Plan #2		Load JPG	☒

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18002657/AQBN2
Date: 30/05/2018

REFERENCE

Insured/Claimant: LEE KHENG HOCK Policy No:
Date of Loss: 31/01/2018 Nature of Claim: OD Claim No: 1480555251SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH2006X Engine No: CVK047191
Make & Model: AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A) Chassis No: WAUZZZF51JA034333
Reg. Date: 13/10/2017 (Man. Year: 2017) Odometer: 3856 km
Colour: White
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$198,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,658.00	3,244.80	1,413.20	30.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,872.00	1,922.00	950.00	33.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,530.00	5,166.80	2,363.20	31.38
+ GST 7.00/7.00% (S\$)	527.10	361.68	165.42	31.38
Nett Amount (S\$)	8,057.10	5,528.48	2,528.62	31.38

INSPECTION

Date of Assignment: 09/02/2018
Date Inspected: 07/02/2018

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Dented	2,692.00 FS	*2,153.60 FS
2	1		*FRONT OUTER DOOR SEAL-RH	Necessary	192.00 FS	*153.20 FS
3	1		*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
4	1		*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
5	1		*FRONT EXTERIOR MIRROR MOUNTING-RH	Cracked	959.00 FS	*767.20 FS
6	1		*FRONT MIRROR CAP-RH	Repair	217.00 FS	*- FS
7	1		*FRONT DOOR TRIM-RH	Necessary	138.00 FS	*110.40 FS
8	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
9	1		*SUNDRIES	Necessary	300.00 FS	*26.24 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,658.00	3,244.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND WING MIRROR ASSY.ALIGN TO POSITION.REINSTALL ALL PARTS REMOVED	New	1,200.00	750.00
3	TO RESPRAY RHS FRONT DOOR AND WING MIRROR COVER	New	1,200.00	700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,872.00	1,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >