

方 商 昭 喷 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.

Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Not Authorite
11 by 8 14 od
Busing Afte Pains
3day,

Evergreen Rent A Car Pte Ltd Blk 159 Sin Ming Road #01-07 Amtech Building Singapore 575825

Dear sir Estimate cost of repair to vehicle no. SGV 9939J To supply

- 1. Rear bumper
- 2. Rear bumper Conner
- 3. Rea bumper sensor
- 4. Rear bumper reflector
- 5. Rear bumper mudflat
- 6. Rear panel
- 7. Rear exhaust box
- 8. Tail gate garish
- 9. Tail gate rubber

Rear panel top garish

Labour charges Rust proofing Panel beating Spray painting Total Bu 508.20 — Bu 153.10 — \$\frac{1}{2}\$ 350.00 \$\times\$ \$\frac{1}{2}\$ 40.00 — \$\frac{1}{2}\$ 65.00 \$\times\$ \$\frac{1}{2}\$ 607.90 \$\times\$ \$\frac{1}{2}\$ 106.00 \$\times\$ \$\frac{1}{2}\$ 128.00 \$\times\$

208

80.00 × 890.00 409 680.00 559

Your faitfully

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: