

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0621/2018
DATE : 06-FEB-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : NG CHOON SIONG
ADDRESS : 26 JALAN REBANA

S(576996)
TELEPHONE NO : 97997222

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100505472
VEHICLE NO : SFV12D
MODEL CODE : BS9CKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y602147
CHASSIS NO : JF1BS9KC2HG058923
MILEAGE : 1 KM
DATE IN : 06/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 06/02/2018

Print Date : 08/02/2018
Print Time : 11:46:44

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFV12D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:CTE EXIT TO ANG MO KIO AVE 1 DATE:06/02/2018 TIME:0725H		
3	ZZ/002	REMOVE/REFIX RR BUMPER,RR PANEL,TAILGATE	1680.00	? (1120)?
4	ZZ/003	RESPRAY RR BUMPER,RR PANEL,TAILGATE	1260.00	1260
5	ZZ/004	DISMENTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	na 300.00	X
6	ZZ/005	TO CONDUCT WATER SEEPAGE TEST	100.00	50
7	ZZ/006	TRANSFER(TAILGATE)MECHANISM	150.00	✓
8	ZZ/007	REMOVE&INSTALL(REAR)WINDSCREEN	300.00	250
9	ZZ/008	CONDUCT(REAR)LIGHTING TEST	50.00	25
10	ZZ/009	TO SUPPLY&INSTALL REVERSE SENSOR-2 EYES	na 300.00	✓
11	ZZ/10	SUNDRIES	100.00	30
TOTAL LABOUR CHARGES			4240.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFV12D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	EXH PIPE ASSY R	44200AL031	720.00	7			
2	MUFFLER ASSY LH	44300AL020	540.00	✓			
3	FLOOR PAN R R CP	52129AL0119P	342.00	X			
4	SKIRT COMPL R OBK	52401AL0319P	259.20	7			
5	BUMPER FACE R OBKFHI	57704AL130	594.00	✓			
6	BRKT SD R OBK RH	57707AL320	36.00	7			
7	BRKT SD R OBK LH	57707AL330	36.00	7			
8	BRKT CORNER R OBKRH	57707AL360	21.60	7			
9	BRKT CORNER R OBK LH	57707AL370	21.60	7			
10	BEAM COMPL R OBK EU	57719AL020	396.00	7			
11	COVER HOOK R OBK FHI	57731AL390NN	10.80	✓			
12	REAR RESIN UNDER GUARD OBK	57734AL050	270.00	✓			
13	PANEL COMPL R GAT	60809AL0109P	1072.80	X			
14	GLASS ASSY R G	LV5B9 3PC 63019AL140	1861.20	X			
15	RUBBER DAM GLS	63232AL020	7.20	✓			
16	SEAL GLS RG A	63242AL000	4.40	✓			
17	WSTR DR R G	63516AL000	111.60	X			
18	LENS & BODY COMPLRRH	84913AL120	129.60	X			
19	LENS & BODY COMPLRLH	84913AL140	64.20	X			
20	GARNISH	91111AL000NN	262.80	X			
21	PROTECTOR-REAR GARNISH	91713AG040	14.10	X			
22	PROTECTOR UPR	91713AL000	21.60	X			
23	PROTECTOR LWR SD	91713AL150	2.20	X			
24	PROTECTOR SD A	91713AL160	2.20	X			
25	PROTECTOR SD	91713SG020	8.80	X			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFV12D

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	PROTECTOR LWR	91713VA040	2.20	7		
27	ORNAMENT R OBK 6KA	93033AL040	72.00	✓		
28	LETTER MK "OUTBACK"	93079AL000	50.40	✓		
29	LETTER MK HOYO	93079AL020	72.00	✓		
30	CARGO STEP S/S BS9 OBK E7710AL000 SAME	E7717AL000	560.00	✓		
SUB TOTAL			7566.50	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1513.30	0.00	0.00	0.00
GRAND TOTAL			6053.20	0.00	0.00	0.00
OVERALL TOTAL			6053.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFV12D

TOTAL LABOUR CHARGES	4240.00
TOTAL SPARE PARTS CHARGES	6053.20
GRAND TOTAL	10293.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Wharw
1-B1
Survey B4 pain
4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: