

ASS. REC. BY:

REF: CS/CTI18002671/TIRD302

Special Instruction:

Surveyor: Taukikh
Menmen

ASSIGNMENT (Office)

From (Person): Joel Goh

of CTI

Date/Time: 9/2/18 @ 11:09am

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 2984Z

Insured:

YN 4238K

at Workshop m/s

Vermogen Ace

Tel:

6904 4596

of

1 Bukit Batok Crescent #05-23

Policy No:

DMEVS N3057581702

Claim No:

SNM18D00763C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11:35am @ 9/2/18

Person Contacted:

Innoko

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLF 2984Z - X</u>
	<u>YN 4238K -</u>
	<u>Confirm L/S \$3200, @ 5 days</u>
	<u>Red: \$10768.23, 77%</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18002671/T1rd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 09-02-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 4238K	Veh. Inspected	SLF 2984Z
Policy No.	DMCVSN3057581702	Coverage (\$)	0.00
Claim No.	SNM18D00763C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	09/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/02/2018	Inspection Date	08/02/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2018		09 Feb 2018 11:09 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	THE WINE GALLERY PTE LTD , Co. Reg. No.: 201120555N		
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLF2984Z	Date of Loss:	07/02/2018 10:00 - :59
Claim Type:	TP / SNM18D00763C02	Policy/Cover Note No.:	DMCVSN3057581702 (Comprehensive)
Vehicle Reg. No. (Insured):	YN4238K	Policy No. (Claimant):	999995056
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2018]		
Driver/Custodian (Insured):	PEH BENG HWEE (BAI MINGHUI) (44 / Male), NRIC: S7346775F, Tel: +6596848921		
Adj Asg. Remarks:	NO EST, CASE WITH SJE		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: pila.vermogenace@gmail.com
Sent: Wednesday, 7 February, 2018 1:54 PM
To: Claims Dept of CTI; Jowyn Tay; Joel Goh; Lucas Lee
Cc: 'Minoko'; 'ezel tejano'; 'Eric Glorioso'; 'juan paulo baldoz';
vermogenace@gmail.com; 'Luis Tan'
Subject: PLEASE ARRANGE TP SURVEY FOR (OUR REF: SLF2984Z) YR REF: YN4238K DOA:
07/02/2018
Attachments: SLF2984Z.PDF

Dear Arrange survey dept,

Kindly arrange TP survey on **08/02/2018 (Thursday)** following detail & attach here GIA report:

Survey before repair

Your Vehicle: YN4238K

Our Vehicle: SLF2984Z

DOA : 07/02/2018

AOL : CHANGI BUSINESS PARK VISTA TOWARDS CHANGI SOUTH AVE 3

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank You.

Best Regards,

PILA
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Janice Lee (LKKAuto)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Saturday, April 21, 2018 10:27 AM
To: Asher Sng (LKKAuto); Vic (LKKAuto); Guo Qiang (LKKAuto); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Taufikh (LKKAuto); Rasul (LKKAuto)
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Minoko Chan; Edmond Lim; Quantum Risk; Lina Rosli; Luis Tan; Paul Tan
Subject: SLF2984Z DOA: 07/02/2018 TO FINALISE (CHINA TAIPING TP)
Attachments: 9b8e64eb-b7ab-4123-b2a7-68f618ed18bf.jpg;
25ebd919-3bb0-45df-89e4-9b379d740f56.jpg; 789d8d0a-4250-403a-abaf-819390a59db2.jpg; 4612f371-d890-4af3-871c-849e7407f4b5.jpg; 665796e3-d875-4acb-b702-b4a99b6ad1c6.jpg; 02920390-863e-4d16-b95c-db091b070ad7.jpg; d5482fd7-701e-45ba-a505-059e8958051c.jpg; eeac1ffc-9981-41bc-8ebe-e5224493f124.jpg; SLF2984Z FINALISE.pdf

Hi Taufikh,

Please check and confirm finalise COR @ **\$3,200** bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2018 13:29
Date Of Accident	07/02/2018 10:40
Exact Location Of Accident	CHANGI BUSINESS PARK VISTA TWDS CHANGI SOUTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF2984Z
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995056
Cover Note Number	

Driver

Name of Driver	OMAR KHAN
NRIC No	S1709113A
Date Of Birth	02/11/1965
Occupation	OUTDOOR
Date Of Driving Pass	12/03/2010
Driving Experience	7 YEARS AND 10 MONTHS

Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	44 BENOI ROAD BLOCK B (ENTRANCE 6 BENOI SECTOR)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : UNKNOWN Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS AND VIDEO. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4238K
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (POPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: NIKO





Car A: SLF2984Z

Car B: YN4238K

Location:

Changi Business Park Vista
(Towards Changi South
Ave 3)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/02/18 at 10:40 am, my vehicle A was approaching to stationary at the slip road along Changi Business Park Vista (Towards Changi South Ave 3) and wait for the major road vehicles to be cleared before proceeding out. While my vehicle A has stationary suddenly I felt a impact on my vehicle A. I then went down and assess the accident scene and photo taking. I wish to state that I have in-car camera in my vehicle. A.

DECLARATION

I/We declare the foregoing particulars are true in every respects.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



NIKO

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1709113A



Name
OMAR KHAN

Race
INDIAN

Date of birth
02-11-1965

Sex
M

Country of birth
SINGAPORE

S1709113A



REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number **S1709113A**

Name
OMAR KHAN

Birth Date **02 Nov 1965**

Issue Date **12 Mar 2010**

0018385391

VMG USE ONLY

4890813



NRIC No. **S1709113A**



Date of issue
08-03-2011

APT BLK 873C EDGEFIELD PLAINS #05-823
SINGAPORE 823673

NRIC No. S1709113A Date: 28/11/2015


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE **12 Mar 2010**

Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg

NP 428A

Licence No: S1709113A





SLF2984Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 7/2/2018

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22-Aug-2016
Make / Model : SIENTA 1.5X A
Engine No. : 2NR8640227
Chassis No. : NSP1707040464

COST OF CLAIMS

Parts Cost / List Items : \$ 12,844.30
Plus/Less 25% \$ 3,211.08
Total Cost / List : \$ 9,633.23
Special Nett Items : \$ 585.00
Total Parts Amount : \$ 10,218.23
Total Labour Amount : \$ 3,750.00
Gross Total : \$ 13,968.23
GST % : 7% \$ 977.78
Nett Amount : \$ 14,946.00

Surveyor Name and Company :

Tanjun 97495749

Date of survey : 7/2/18 @ 1720

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkkauto.com

Fax No : _____

HP No : _____

Edmond
13/2/18

This claim is handled by : EDMOND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z
 Vehicle Reg. Date: 22/8/2016
 Make / Model : SIENTA 1.5X A
 Engine No. : 2NR8640227
 Chassis No. : NSP1707040464

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	all	\$ 168.40	/	
2	1	Rear number plate lamp assy	X	\$ 158.00	XNN	
3	1	Rear bumper	Ry	\$ 838.80	XNN	
4	1	Rear bumper cover center	at	\$ 182.40	/	
5	2	Rear bumper cover LH/RH	LH-side ✓, RH X old damage	\$ 391.00	195.50	
6	1set	Rear bumper clips	nei	\$ 50.00	/	
7	2	Rear bumper side retainer LH/RH	LH nei ✓, RH XNN	\$ 164.00	82	
8	2	Rear bumper bracket LH/RH	LH nei ✓, RH XNN	\$ 164.00	82	
9	1	Rear bumper sponge	?	\$ 98.00		
10	2	Rear bumper reflector LH/RH	X	\$ 216.00	XNN	
11	2	Rear bumper splash shield LH/RH	X	\$ 340.00		
12	1	Tail gate	bt	\$ 1,360.00	/	
13	1	Tail gate lock	X	\$ 246.60		
14	1	Tail gate striker	Ry	\$ 48.00	XNN	
15	2	Tail gate stay LH/RH	X	\$ 320.00		
16	1	Tail gate logo	nei	\$ 50.00	/	
17	1	Tail gate emblem RH	nei	\$ 59.40	/	
18	1	Tail gate outer garnish	Ry	\$ 84.50	X R	
19	1	Tail gate weatherstrip	cut	\$ 145.00	/	
20	2	Tail gate lamp LH/RH	LH-crad ✓, RH XNN	\$ 720.00	360	
21	1	Tail door trim	X	\$ 280.00		
22	1	Rear end panel outer	Ry	\$ 498.20	XNN	
23	1	Rear end panel inner	Ry	\$ 498.20	XNN	
24	1	Rear end panel garnish	?	\$ 195.20		
25	1	Tail gate inner side trim RH	X	\$ 750.00		
26	2	Tail lamp LH/RH	LH-cra ✓, RH XNN	\$ 780.00	390	
27	1	Spare tyre well panel	X	\$ 822.60		
28	1	Spare tyre board	X	\$ 256.00		
29	1	Spare tyre bracket	X	\$ 60.00		
30	1	Exhaust muffler	X	\$ 700.00	XNN	
31	1	Exhaust muffler mounting	X	\$ 70.00		
32	1	Rear fender RH	X	\$ 1,676.00		
33	1	Rear fender garnish RH	X	\$ 94.00		
34	1set	Tail door trim clips	X	\$ 40.00		
35	1set	Tail gate inner side trim RH clips	X	\$ 40.00		
36	1	Tail gate seal	nei		\$ 80.00	/
37	1	Rear end panel sealant	X		\$ 80.00	
38	1	Spare tyre panel sealant	X		\$ 80.00	XNN
39	1	Reverse sensor	X	200	\$ 300.00	
40	1	Rear number plate	X		\$ 45.00	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z
 Vehicle Reg. Date: 22/8/2016
 Make / Model : SIENTA 1.5X A
 Engine No. : 2NR8640227
 Chassis No. : NSP1707040464

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR LOCK ANTENNA SENSOR	h n K	\$ 280.00		
42	0	0				
43	0	0				
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				



SLF2984Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 7/2/2018

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22-Aug-2016
Make / Model : SIENTA 1.5X A
Engine No. : 2NR8640227
Chassis No. : NSP1707040464

COST OF CLAIMS

Parts Cost / List Items : \$ 12,844.30
Plus/Less 25% \$ 3,211.08
Total Cost / List : \$ 9,633.23
Special Nett Items : \$ 585.00
Total Parts Amount : \$ 10,218.23
Total Labour Amount : \$ 3,750.00
Gross Total : \$ 13,968.23
GST % : 7% \$ 977.78
Nett Amount : \$ 14,946.00

Surveyor Name and Company :

Tanjim 97495749
Date of survey : 7/2/18 @ 1720
Part by Part / Lump Sum : 5 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@kkauto.com
Fax No :
HP No :

This claim is handled by : EDMOND

Handwritten calculations: P= 3124.70 -25% = 2343.53, SN= 80, L= 1620, 4043.53 -20% = 3234.82, L/S= 3200

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22/8/2016
Make / Model : SIENTA 1.5X A
Engine No. : 2NR8640227
Chassis No. : NSP1707040464

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	new	\$ 168.40		
2	1	Rear number plate lamp assy	X	\$ 158.00		
3	1	Rear bumper	Ry	\$ 838.80		
4	1	Rear bumper cover center	at	\$ 182.40		
5	2	Rear bumper cover LH/RH	LH - new ✓, RH X old damage	\$ 391.00	195.50	
6	1set	Rear bumper clips	new	\$ 50.00		
7	2	Rear bumper side retainer LH/RH	LH new ✓, RH - X	\$ 164.00	82	
8	2	Rear bumper bracket LH/RH	LH new ✓, RH - X	\$ 164.00	82	
9	1	Rear bumper sponge	? X	\$ 98.00		
10	2	Rear bumper reflector LH/RH	X	\$ 216.00		
11	2	Rear bumper splash shield LH/RH	X	\$ 340.00		
12	1	Tail gate	bt	\$ 1,360.00		
13	1	Tail gate lock	X	\$ 246.60		
14	1	Tail gate striker	Ry	\$ 48.00		
15	2	Tail gate stay LH/RH	X	\$ 320.00		
16	1	Tail gate logo	new	\$ 50.00		
17	1	Tail gate emblem RH	new	\$ 59.40		
18	1	Tail gate outer garnish	Ry	\$ 84.50		
19	1	Tail gate weatherstrip	cut	\$ 145.00		
20	2	Tail gate lamp LH/RH	LH - good ✓, RH - X	\$ 720.00	360	
21	1	Tail door trim	X	\$ 280.00		
22	1	Rear end panel outer	Ry	\$ 498.20		
23	1	Rear end panel inner	Ry	\$ 498.20		
24	1	Rear end panel garnish	? X	\$ 195.20		
25	1	Tail gate inner side trim RH	X	\$ 750.00		
26	2	Tail lamp LH/RH	LH - good ✓, RH - X	\$ 780.00	390	
27	1	Spare tyre well panel	X	\$ 822.60		
28	1	Spare tyre board	X	\$ 256.00		
29	1	Spare tyre bracket	X	\$ 60.00		
30	1	Exhaust muffler	X	\$ 700.00		
31	1	Exhaust muffler mounting	X	\$ 70.00		
32	1	Rear fender RH	X	\$ 1,676.00		
33	1	Rear fender garnish RH	X	\$ 94.00		
34	1set	Tail door trim clips	X	\$ 40.00		
35	1set	Tail gate inner side trim RH clips	X	\$ 40.00		
36	1	Tail gate seal	new		\$ 80.00	
37	1	Rear end panel sealant	X		\$ 80.00	
38	1	Spare tyre panel sealant	X		\$ 80.00	
39	1	Reverse sensor	X	200	\$ 300.00	
40	1	Rear number plate	X		\$ 45.00	

P = 3124.70
SN = 80

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z
 Vehicle Reg. Date: 22/8/2016
 Make / Model : SIENTA 1.5X A
 Engine No. : 2NR8640227
 Chassis No. : NSP1707040464

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR LOCK ANTENNA SENSOR	✓	\$ 280.00		
42	0	0				
43	0	0				
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18002671/T1RD3N2

Date: 23/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3057581702
Claimant Vehicle No :	SLF2984Z	Insured Vehicle No :	YN4238K
Date of Loss:	07/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D00763C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2984Z	Engine No:	2NR8640227
Make & Model:	TOYOTA SIENNA, 1.5 (A)	Chassis No:	NSP1707040464
Reg. Date:	22/08/2016 (Man. Year: 2016)	Odometer:	111349 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Achilles 6 mm	Rear Left Side:	Achilles 6 mm
Front Right Side:	Achilles 6 mm	Rear Right Side:	Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,218.22	2,423.52	7,794.70	76.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,620.00	2,130.00	56.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,968.22	4,043.52	9,924.70	71.05
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	13,968.22	3,200.00	10,768.22	77.09
+ GST 7.00/7.00% (\$\$)	977.78	224.00	753.78	77.09
Nett Amount (\$\$)	14,946.00	3,424.00	11,522.00	77.09

INSPECTION

Date of Assignment:	09/02/2018	Inspected At:	Vermogen Ace Pte Ltd (HQ)
Date Inspected:	07/02/2018		Blk B, 44 Benoi Rd
			Singapore 629904

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2018)	
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLF2984Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	168.40 FL	*168.40 FL
2	1		*REAR NUMBER PLATE LAMP ASSY	Not Necessary	158.00 FL	*- FL
3	1		*REAR BUMPER	Repair	838.80 FL	*- FL
4	1		*REAR BUMPER COVER CENTER	Cut	182.40 FL	*182.40 FL
5	1		*REAR BUMPER COVER LH/RH (O/S NOT NECESSARY)	N/s Deformed/O/s Old Damage	391.00 FL	*195.50 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH/RH	Ns Necessary/Os Not Necessary	164.00 FL	*82.00 FL
8	1		*REAR BUMPER BRACKET LH/RH	Ns Necessary/Os Not Necessary	164.00 FL	*82.00 FL
9	1		*REAR BUMPER SPONGE	Not Necessary	98.00 FL	*- FL
10	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	216.00 FL	*- FL
11	2		*REAR BUMPER SPLASH SHIELD LH/RH	Not Necessary	340.00 FL	*- FL
12	1		*TAIL GATE	Bent	1,360.00 FL	*1,360.00 FL
13	1		*TAIL GATE LOCK	Not Necessary	246.60 FL	*- FL
14	1		*TAIL GATE STRIKER	Repair	48.00 FL	*- FL
15	2		*TAIL GATE STAY LH/RH	Not Necessary	320.00 FL	*- FL
16	1		*TAIL GATE LOGO	Necessary	50.00 FL	*50.00 FL
17	1		*TAIL GATE EMBLEM RH	Necessary	59.40 FL	*59.40 FL
18	1		*TAIL GATE OUTER GARNISH	Repair	84.50 FL	*- FL
19	1		*TAIL GATE WEATHERSTRIP	Cut	145.00 FL	*145.00 FL
20	1		*TAIL GATE LAMP LH/RH	N/s Cracked/O/s Not Necessary	720.00 FL	*360.00 FL
21	1		*TAIL DOOR TRIM	Not Necessary	280.00 FL	*- FL
22	1		*REAR END PANEL OUTER	Repair	498.20 FL	*- FL
23	1		*REAR END PANEL INNER	Repair	498.20 FL	*- FL
24	1		*REAR END PANEL GARNISH	Not Necessary	195.20 FL	*- FL
25	1		*TAIL GATE INNER SIDE TRIM RH	Not Necessary	750.00 FL	*- FL
26	1		*TAIL LAMP LH/RH	N/s Cracked/O/s Not Necessary	780.00 FL	*390.00 FL
27	1		*SPARE TYRE WELL PANEL	Not Necessary	822.60 FL	*- FL
28	1		*SPARE TYRE BOARD	Not Necessary	256.00 FL	*- FL
29	1		*SPARE TYRE BRACKET	Not Necessary	60.00 FL	*- FL
30	1		*EXHAUST MUFFLER	Not Necessary	700.00 FL	*- FL
31	1		*EXHAUST MUFFLER MOUNTING	Not Necessary	70.00 FL	*- FL
32	1		*REAR FENDER RH	Not Necessary	1,676.00 FL	*- FL
33	1		*REAR FENDER GARNISH RH	Not Necessary	94.00 FL	*- FL
34	1		*SET TAIL DOOR TRIM CLIPS	Not Necessary	40.00 FL	*- FL
35	1		*SET TAIL GATE INNER SIDE TRIM RH CLIPS	Not Necessary	40.00 FL	*- FL
36	1		*REAR LOCK ANTENNA SENSOR	Not Necessary	280.00 FL	*- FL
37	1		*TAIL GATE SEAL	Necessary	80.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
38	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
39	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
40	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS	
41	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS	
					Sub Total (S\$)	13,429.30	3,204.70
					- List Item Discount on L Items 25.00/25.00% (S\$)	3,211.08	781.18
					Total Parts (S\$)	10,218.22	2,423.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA	New	1,400.00	700.00
2	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
3	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	30.00
4	TO REMOVE AND REFIT INNER TRIM, INNER SEAT, TRIM BOARD, TO ASSIST REPAIR	New	200.00	60.00
5	TO RUSTPROOF ACCIDENT REPAIR AREA	New	200.00	40.00
6	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	150.00	60.00
7	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA	New	1,600.00	700.00
Gross Labour Cost (S\$)			3,750.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >