

12/03/2002

ASS. REC. BY:

REF: CS/MSG 18002675 / Avd3nz Special Instruction:

Survivor: Adrian ASSIGNMENT (Office)From (Person): Merimen Christina Wong of MSIG Date/Time: 8/2/18 @ 5:00pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJ25849E Insured: FBD2767Mat Workshop m/s: 1st Autoworks Tel: 68441985of 23 Kaki Bkt Ave 4 #04-01Policy No: MSD/VMT/17-984886 Claim No: msc/v/18-000221

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement: _____

Date/Time: 11:24am @ 9/2/18 Person Contacted: syhaimi Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|----------------|---|
| | <u>SJ25849E - X</u> |
| | <u>FBD2767M - X</u> |
| | |
| <u>12/2/18</u> | <u>Informed christing pending workshop est by merimen</u> |
| <u>23/4/18</u> | <u>Adrian Confirmed \$5893.80 (Red 12,10170, 67M) (NO LS)</u> |
| <u>24/4/18</u> | <u>Send preli revised by merimen</u> |

(OR Scan) 24/04/18

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJ25849E - Yr Regn: 2010 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Cruze .cc 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

159577.

T/Radio: Insured / Std / NI / NA

Eng/No:

KL1JA6961BK054469.

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16.

R:

205/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

09/04/18.

Survey held at

1st Autowork.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MS16.

RECEIVED 24 APR 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 24/4 - Typist

Report Format :

merimen

Lump Sum / I.B.I: (\$

5893.80

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others:

TOTAL

300
10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002675/Avd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 09-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------------|----------------|------------|
| Insured Veh. | FBD 2767M | Veh. Inspected | SJZ 5849E |
| Policy No. | MSD/VM/17-984886 | Coverage (\$) | 0.00 |
| Claim No. | MSC/V/18-000221 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (CHRISTINA WONG) | Assign Date | 09/02/2018 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | - | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 03/02/2018 | Inspection Date | 09/02/2018 |
| Survey held at | 1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933 | | |

5a. Remarks

| |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

| | |
|--|---|
| To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 | From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
| Attn: Christina Wong | Date: 24 Apr 2018 |
| <u>Preliminary Advice</u> | |

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : FBD2767M | Accident Date | : 03/02/2018 |
| TP Vehicle No | : SJZ5849E | Assignment Date | : 08/02/2018 |
| Make | : CHEVROLET CRUZE | Est. Duration of Repair | : 3.00 |
| Date of Inspection | : 09/02/2018 | | |
| Inspection At | : 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,995.50 |
| Revised Amount | :S\$ | 5,893.80 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 5,893.80 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/18002675/Avcl3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assignment Form

| | | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | ✓ | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | | | | |
| C | Insurance Authorisation (CA /REV/REP) | ✓ | | | |
| C | Report Type | | | | |
| C | Weekend Charges | ✓ | | | |
| N | Survey held at/Repairer | | | | |
| C | Excess | | | | |

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

| | | | | | |
|---|------------------------|---|--|--|--|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By:

VERON

Case Handler

24/4/18
Date

*C: Critical *N: Non-Critical

21/05/20

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|---|
| Main | 03 Feb 2018 | | 08 Feb 2018 17:00 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | MOHD ALI BIN A S SHAHUL HAMEED, ID: S1465065B | | |
| Main Claimant: | ANG KAH HIN, ID: S0200683I | | |
| Vehicle Reg. No.: | SJZ5849E | Date of Loss: | 03/02/2018 00:00 - :59 |
| Claim Type: | TP / MSC/V/18-000221 | Policy/Cover Note No.: | MSD/VMT/17-984886 Coverage: 07/08/2017 - 06/08/2018 |
| Vehicle Reg. No. (Insured): | FBD2767M | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 09/02/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 03 Feb 2018 | | 08 Feb 2018 17:00 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | MOHD ALI BIN A S SHAHUL HAMEED, ID: S1465065B | | |
| Main Claimant: | ANG KAH HIN, ID: S02006831 | | |
| Vehicle Reg. No.: | SJZ5849E | Date of Loss: | 03/02/2018 00:00 - :59 |
| Claim Type: | TP | Policy/Cover Note No.: | MSD/VMT/17-984886 Coverage: 07/08/2017 - 06/08/2018 |
| Vehicle Reg. No. (Insured): | FBD2767M | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/02/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

View Sent Message

This mail is associated with :

***SJZ5849E (MSC/V/18-000221)**
[FBD2767M]

TP

ANG KAH HIN

Feb 3 2018 12:00AM

[MOHD ALI BIN A S SHAHUL HAMEED]

1st Autoworks Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/02/2018 12:34 PM.
To MSIG_CWSF1
Subject TP SURVEY SJZ 5849E

Dear Christina,

Please be informed that we have inspected the vehicle SJZ 5849E on 9/2/2018

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Hasrianah Binte Hassan

From: Suhaimi <suhaimi@firstautoworks.com.sg>
Sent: Thursday, 8 February, 2018 3:00 PM
To: Hasrianah Binte Hassan
Cc: Tan Jin Hao; Elaine Ngu
Subject: fw: re: FW: Accident vehicle between our insured SJZ5849E and your insured FBD2767M on 03/02/2018
Attachments: SAS2353450.pdf

Dear Hasrianah,
Any news on the appointment of the single joint expert on this accident case?

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

From: "Suhaimi" <suhaimi@firstautoworks.com.sg>
Sent: Thursday, 8 February, 2018 12:00 PM
To: "Hasrianah Binte Hassan" <hasrianah@sg.msig-asia.com>
Subject: re: FW: Accident vehicle between our insured SJZ5849E and your insured FBD2767M on 03/02/2018

Hi Hasrianah,
Any news on the appointment of the single joint expert on this accident case?

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

From: "Tan Jin Hao" <jinhao_tan@sg.msig-asia.com>
Sent: Thursday, 8 February, 2018 10:43 AM
To: "Hasrianah Binte Hassan" <hasrianah@sg.msig-asia.com>
Cc: "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>
Subject: FW: Accident vehicle between our insured SJZ5849E and your insured FBD2767M on 03/02/2018

Hi Has,

Fya,

Have A Great Week Ahead!

Tan Jin Hao
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2583 | Direct fax +65 6225 7402 | jinhao_tan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Suhaimi [mailto:suhaimi@firstautoworks.com.sg]
Sent: Thursday, 8 February, 2018 10:39 AM
To: Tan Jin Hao <jinhao_tan@sg.msig-asia.com>
Cc: Elaine Ngu <elaine_ngu@sg.msig-asia.com>
Subject: fw: Accident vehicle between our insured SJZ5849E and your insured FBD2767M on 03/02/2018

Hi Jin Hao,
I've sent this claim over to claims@sg.msig-asia.com yesterday afternoon and am awaiting for the list of surveyors to be appointed for this accident case.

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

From: "Suhaimi" <suhami@firstautoworks.com.sg>

Sent: Wednesday, 7 February, 2018 2:13 PM

To: claims@sg.msig-asia.com

Subject: Accident vehicle between our insured SJZ5849E and your insured FBD2767M on 03/02/2018

Dear Sirs,

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

- 1)
- 2)
- 3)

Take Notice : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Please note that this notification does not in any way prejudice our client(s) rights nor shall it be deemed as a waiver of any of their rights, as such our client(s) rights are expressly reserved.

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

| | |
|------------------|---|
| Policy Number | : 5095686100 |
| The Policyholder | : ANG KAH HIN 459 UPPER EAST COAST RD #03-02 THE SUMMIT SINGAPORE 466504 |

| | |
|-------------------------|---|
| Period of Insurance | : 09 Dec 2017 To 08 Dec 2018 |
| Sum Insured | : Market Value of Insured Vehicle at Time of Loss |
| Premium (inclusive GST) | : S\$820.21 |

Interest Insured

| | | | |
|--------------------------------------|--|-------------------|----------|
| Cover Type | : drive CLASSIC | Capacity | : 1600cc |
| Primary Driver | : ANG KAH HIN | Registration Year | : 2010 |
| Named Driver (1) | : ANG LILING JANE | Off-peak Car | : No |
| Named Driver (2) | : N/A | Insure with COE | : Yes |
| Make/Model | : CHEVROLET/CRUZE | NCD Entitlement | : 50% |
| Registration Number | : SJZ5849E | NCD Protection | : Yes |
| Chassis Number | : KL1JA6961BK054469 | Loyalty Discount | : 5% |
| Repair at Owner's Preferred Workshop | : No | | |
| Excess (Section 1) | : S\$600 | | |
| Excess (Section 2) | : N/A | | |
| Windscreen Excess | : S\$100 | | |
| Additional Excess | : N/A | | |
| Unnamed Driver Excess | : Please refer to Terms and Conditions | | |
| Hire Purchase Company | : N/A | | |

Optional Cover

| | |
|---------------------|------|
| Transport Allowance | : No |
| Excess Waiver | : No |

Memo A : N/A

Endorsement Operative : M4

| | |
|---------------|---------------------------------------|
| Agency | : ALPINE CREDIT PTE LTD (00000610144) |
| Date of Issue | : 09 Nov 2017 15:18 hrs |

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S02006831

Name
ANG KAH HIN
洪加兴

Race
CHINESE

Date of Birth
02-09-1954

Sex
M

Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE
S02006831

ANG KAH HIN

Birth Date: 02 Sep 1954
Issue Date: 30 Apr 2010



Repair Estimate

Date : 8/2/2018

Reference: SJZ5849E
CHEVROLET
Make: CRUZE 1.6L

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SJZ5849E
CHASSIS NO.: KL1JA6961BK054469
ENGINE NO.: F16D37816971

Name of insured : Ang Kah Hin
Date of accident : 03/02/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

| No. | Qty | Part Description | Price (SGD) |
|-----|-----|----------------------------------|-------------|
| 1 | 1 | Boot lid | \$ 1,800.00 |
| 2 | 1 | Bootlid Moulding | \$ 280.00 |
| 3 | 1 | Boot lid Emblem | \$ 85.00 |
| 4 | 1 | Boot lid lettering 'CHEVROLET' | \$ 65.00 |
| 5 | 1 | Boot lid lettering 'CRUZE' | \$ 45.00 |
| 6 | 1 | RHR Bootlid Lamp | \$ 454.00 |
| 7 | 1 | LH Bootlid hinge | \$ 75.00 |
| 8 | 1 | RH Bootlid hinge | \$ 75.00 |
| 9 | 1 | Boot lid lock mechanism | \$ 250.00 |
| 10 | 1 | Boot lid weatherstrip | \$ 189.00 |
| 11 | 1 | RHR Tail lamp | \$ 650.00 |
| 12 | 1 | RHR Tail lamp panel | \$ 310.00 |
| 13 | 1 | RHR Fender | \$ 1,957.00 |
| 14 | 1 | RHR Lower Fender Extension Panel | \$ 156.00 |
| 15 | 1 | RHR Bumper Air Ventilator | \$ 60.00 |
| 16 | 1 | RHR Fender Quarter Moulding | \$ 98.00 |
| 17 | 1 | Rear Windscreen Moulding | \$ 120.00 |
| 18 | 1 | RHR Fender Liner | \$ 115.00 |
| 19 | 1 | RHR Fender Inner Trim | \$ 299.00 |
| 20 | 1 | Rear bumper | \$ 1,536.00 |
| 21 | 1 | Rear bumper tow hook cover | \$ 30.00 |
| 22 | 1 | Centre Bumper Guide | \$ 75.00 |
| 23 | 1 | RHRC Bumper Guide | \$ 65.00 |
| 24 | 1 | LHRC Bumper Guide | \$ 65.00 |
| 25 | 1 | RHR Bumper Guide | \$ 65.00 |
| 26 | 1 | LHR Bumper Guide | \$ 65.00 |
| 28 | 1 | Rear bumper reinforcement | \$ 736.00 |
| 29 | 1 | Reverse sensor wire harness | \$ 239.00 |
| 30 | 1 | Rear end panel | \$ 978.00 |
| 31 | 1 | Rear end panel trim | \$ 139.00 |
| 32 | 1 | Rear Spare Tyre Panel | \$ 1,384.00 |

Parts Total: \$ 12,460.00

3482
3133.80

Less 10%: \$ 1,246.00

Total : \$ 11,214.00

LabourLabour Description

| No. | | Price (SGD) |
|-----|--|-------------|
|-----|--|-------------|

Rear portion

| | | | |
|---|---|-------------|------|
| 1 | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day) | \$ 2,750.00 | 1100 |
| 2 | Carry out spray painting on accident affected area (\$450 per panel) | \$ 2,250.00 | 1350 |
| 3 | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair | \$ 30.00 | ✓ |
| 4 | To remove and refix reverse sensor and conduct test | \$ 220.00 | 50 |
| 5 | To remove and refix reverse camera and conduct test | \$ 220.00 | x |
| 6 | To conduct transfer of parts from old bootlid to new bootlid | \$ 220.00 | x |
| 7 | To conduct water leakage test after repairs of vehicle | \$ 110.00 | x |
| 8 | To remove and refit rear windscreen due to replacement of rear fender | \$ 120.00 | x |

2530

Labour Total : \$ 5,920.00

OthersOther Description

| No. | Qty | | Price (SGD) |
|-----|-----|--|-------------|
|-----|-----|--|-------------|

Rear portion

| | | | | |
|---|----|--|-----------|-----|
| 1 | 1 | Rear number plate <i>NE NE</i> | \$ 45.00 | + |
| 2 | 10 | Rear bumper clip <i>2x</i> | \$ 65.00 | 30 |
| 3 | 6 | Rear fender liner clips <i>3x</i> | \$ 39.00 | + |
| 4 | 5 | Rear end panel trim clip | \$ 32.50 | + |
| 5 | 1 | Reverse sensor (1 set) <i>2x</i> | \$ 440.00 | 200 |
| 6 | 1 | Rear end panel insulation seal <i>3x</i> | \$ 120.00 | x |
| 7 | 1 | Rear windscreen sealant <i>2x</i> | \$ 120.00 | 2x |

230

Other Total: \$ 861.50

GRAND TOTAL: \$ 17,995.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Suhaimi

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 09/02/18

03 days.

total: 5893.80

Finalisation.

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

MSIG INSURANCE

16 RAFFLES QUAY, #24-01,

HONG LEONG BUILDING, S'PORE 048581

GST Ref. No: 20-0000274-Z

Vehicle No: SJZ5849E

Invoice No:

Chasis No: KL1JA6961BK054469

Engine No: F16D37816971

Invoice Date:

| DESCRIPTION | AMOUNT | SGD |
|-------------|--------|-----|
|-------------|--------|-----|

Parts

| No. | Qty. | Description | Price (SGD) |
|-----------|------|--------------------------------|-------------|
| <u>1</u> | 1 | Boot lid Emblem | \$ 85.00 |
| <u>2</u> | 1 | Boot lid lettering 'CHEVROLET' | \$ 65.00 |
| <u>3</u> | 1 | Boot lid lettering 'CRUZE' | \$ 45.00 |
| <u>4</u> | 1 | RHR Tail lamp | \$ 650.00 |
| <u>5</u> | 1 | Rear bumper | \$ 1,536.00 |
| <u>6</u> | 1 | Rear bumper tow hook cover | \$ 30.00 |
| <u>7</u> | 1 | Centre Bumper Guide | \$ 75.00 |
| <u>8</u> | 1 | RHRC Bumper Guide | \$ 65.00 |
| <u>9</u> | 1 | LHRC Bumper Guide | \$ 65.00 |
| <u>10</u> | 1 | RHR Bumper Guide | \$ 65.00 |
| <u>11</u> | 1 | LHR Bumper Guide | \$ 65.00 |
| <u>12</u> | 1 | Rear bumper reinforcement | \$ 736.00 |

Total: \$ 3,482.00

Less 10%: \$ 348.20

Parts Total : \$ 3,133.80

Labour

| No. | Description | Price (SGD) |
|----------|---|-------------|
| <u>1</u> | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day) | \$ 1,100.00 |
| <u>2</u> | Carry out spray painting on accident affected area (\$450 per panel) | \$ 1,350.00 |
| <u>3</u> | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair | \$ 30.00 |
| <u>4</u> | To remove and refix reverse sensor and conduct test | \$ 50.00 |

Labour Total : \$ 2,530.00

Other

| <u>No.</u> | | <u>Other Description</u> | <u>Price (SGD)</u> |
|------------|----|--------------------------|--------------------|
| 1 | 10 | Rear bumper clip | \$ 30.00 |
| 2 | 1 | Reverse sensor (1 set) | \$ 200.00 |



Other Total : \$ 230.00

Total : \$ 5,893.80

GST (7%) \$ 412.57

Grand Total: \$ 6,306.37

Yours Faithfully,



Suhaimi Ong

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice



CHEVROLET

INVOICE

To : SJZ5849E

Invoice Date :

08/02/2018

| S/N | Description | U/PRICE | QTY | DISCOUNT | Amount SGD \$ |
|-----------------------|--------------------------------|----------|-----|----------|------------------|
| 1 | Boot lid Emblem | \$ 85 | 1 | 10% | \$ 76.5 |
| 2 | Boot lid lettering 'CHEVROLET' | \$ 65 | 1 | 10% | \$ 58.5 |
| 3 | Boot lid lettering 'CRUZE' | \$ 45 | 1 | 10% | \$ 40.5 |
| 4 | RHR Tail lamp | \$ 650 | 1 | 10% | \$ 585.0 |
| 5 | Rear bumper | \$ 1,536 | 1 | 10% | \$ 1,382.4 |
| 6 | Rear bumper tow hook cover | \$ 30 | 1 | 10% | \$ 27.0 |
| 7 | Centre Bumper Guide | \$ 75 | 1 | 10% | \$ 67.5 |
| 8 | RHRC Bumper Guide | \$ 65 | 1 | 10% | \$ 58.5 |
| 9 | LHRC Bumper Guide | \$ 65 | 1 | 10% | \$ 58.5 |
| 10 | RHR Bumper Guide | \$ 65 | 1 | 10% | \$ 58.5 |
| 11 | LHR Bumper Guide | \$ 65 | 1 | 10% | \$ 58.5 |
| 12 | Rear bumper reinforcement | \$ 736 | 1 | 10% | \$ 662.4 |
| E & O E SUB-TOTAL | | | | | \$ 3,133.80 |
| ADD 7.00% GST | | | | | \$ 219.37 |
| TOTAL WITH GST AMOUNT | | | | | \$ 3,353.17 |

ALPINE MOTORS PTE LTD



Signature

(Personnel Name)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002675/AVD3N2

Date: 25/04/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|------------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/MT/17-984886 |
| Claimant Vehicle No : | SJZ5849E | Insured Vehicle No : | FBD2767M |
| Date of Loss: | 03/02/2018 | Nature of Claim: | TP |
| | | Claim No: | MSCN/18-000221 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SJZ5849E | Engine No: | F16D37816971 |
| Make & Model: | CHEVROLET CRUZE, 1.6 L (A) | Chassis No: | KL1JA6961BK054469 |
| Reg. Date: | 09/12/2010 (Man. Year: 2010) | Odometer: | 159577 km |
| Colour: | Silver | | |
| Engine Capacity: | 1598 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/60R16 | Rear Tyre Size: | 205/60R16 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 12,075.50 | 3,363.80 | 8,711.70 | 72.14 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,920.00 | 2,530.00 | 3,390.00 | 57.26 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 17,995.50 | 5,893.80 | 12,101.70 | 67.25 |
| + GST 7.00/7.00% (\$\$) | 1,259.69 | 412.57 | 847.12 | 67.25 |
| Nett Amount (\$\$) | 19,255.19 | 6,306.37 | 12,948.82 | 67.25 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 08/02/2018 | Inspected At: | 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933 |
| Date Inspected: | 09/02/2018 | | |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|---------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 25 Apr 2018) |
| Parts: | 143 | CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJZ5849E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *BOOT LID | Repair | 1,800.00 FL | *- FL |
| 2 | 1 | | *BOOTLID MOULDING | Not Necessary | 280.00 FL | *- FL |
| 3 | 1 | | *BOOT LID EMBLEM | Necessary | 85.00 FL | *85.00 FL |
| 4 | 1 | | *BOOT LID LETTERING CHEVROLET | Necessary | 65.00 FL | *65.00 FL |
| 5 | 1 | | *BOOT LID LETTERING CRUZE | Necessary | 45.00 FL | *45.00 FL |
| 6 | 1 | | *RHR BOOTLID LAMP | Not Necessary | 454.00 FL | *- FL |
| 7 | 1 | | *LH BOOTLID HINGE | Not Necessary | 75.00 FL | *- FL |
| 8 | 1 | | *RH BOOTLID HINGE | Not Necessary | 75.00 FL | *- FL |
| 9 | 1 | | *BOOT LID LOCK MECHANISM | Not Necessary | 250.00 FL | *- FL |
| 10 | 1 | | *BOOT LID WEATHERSTRIP | Not Necessary | 189.00 FL | *- FL |
| 11 | 1 | | *RHR TAIL LAMP | Cut | 650.00 FL | *650.00 FL |
| 12 | 1 | | *RHR TAIL LAMP PANEL | Not Necessary | 310.00 FL | *- FL |
| 13 | 1 | | *RHR FENDER | Repair | 1,957.00 FL | *- FL |
| 14 | 1 | | *RHR LOWER FENDER EXTENSION PANEL | Not Necessary | 156.00 FL | *- FL |
| 15 | 1 | | *RHR BUMPER AIR VENTILATOR | Not Necessary | 60.00 FL | *- FL |
| 16 | 1 | | *RHR FENDER QUARTER MOULDING | Not Necessary | 98.00 FL | *- FL |
| 17 | 1 | | *REAR WINDSCREEN MOULDING | Not Necessary | 120.00 FL | *- FL |
| 18 | 1 | | *RHR FENDER LINER | Not Necessary | 115.00 FL | *- FL |
| 19 | 1 | | *RHR FENDER LINER TRIM | Not Necessary | 299.00 FL | *- FL |
| 20 | 1 | | *REAR BUMPER | Distorted | 1,536.00 FL | *1,536.00 FL |
| 21 | 1 | | *REAR BUMPER TOW HOOK COVER | Missing | 30.00 FL | *30.00 FL |
| 22 | 1 | | *CENTRE BUMPER GUIDE | Necessary | 75.00 FL | *75.00 FL |
| 23 | 1 | | *RHRC BUMPER GUIDE | Necessary | 65.00 FL | *65.00 FL |
| 24 | 1 | | *LHRC BUMPER GUIDE | Necessary | 65.00 FL | *65.00 FL |
| 25 | 1 | | *RHR BUMPER GUIDE | Necessary | 65.00 FL | *65.00 FL |
| 26 | 1 | | *LHR BUMPER GUIDE | Necessary | 65.00 FL | *65.00 FL |
| 27 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 736.00 FL | *736.00 FL |
| 28 | 1 | | *REVERSE SENSOR WIRE HARNESS | Not Necessary | 239.00 FL | *- FL |
| 29 | 1 | | *REAR END PANEL | Repair | 978.00 FL | *- FL |
| 30 | 1 | | *REAR END PANEL TRIM | Not Necessary | 139.00 FL | *- FL |
| 31 | 1 | | *REAR SPARE TYRE PANEL | Not Necessary | 1,384.00 FL | *- FL |
| 32 | 1 | | *REAR NUMBER PLATE | Not Necessary | 45.00 FS | *- FS |
| 33 | 10 | | *REAR BUMPER CLIP | Necessary | 65.00 FS | *30.00 FS |
| 34 | 6 | | *REAR FENDER LINER CLIPS | Not Necessary | 39.00 FS | *- FS |
| 35 | 5 | | *REAR END PANEL TRIM CLIP | Not Necessary | 32.50 FS | *- FS |
| 36 | 1 | | *SET REVERSE SENSOR | Damaged | 440.00 FS | *200.00 FS |
| 37 | 1 | | *REAR END PANEL INSULATION SEAL | Not Necessary | 120.00 FS | *- FS |
| 38 | 1 | | *REAR WINDSCREEN SEALANT | Not Necessary | 120.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,321.50 3,712.00
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,246.00 348.20

Total Parts (\$\$) 12,075.50 3,363.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS | New | 2,750.00 | 1,100.00 |
| 2 | CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA | New | 2,250.00 | 1,350.00 |
| 3 | TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR | New | 30.00 | 30.00 |
| 4 | TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST | New | 220.00 | 50.00 |
| 5 | TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST | New | 220.00 | - |
| 6 | TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID | New | 220.00 | - |
| 7 | TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE | New | 110.00 | - |
| 8 | TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER | New | 120.00 | - |
| Gross Labour Cost (S\$) | | | 5,920.00 | 2,530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >