

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD917P - AIG

AAD1802-076

*Not Authored
Resurvey By print*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD917P - CANDY
VF1ABL15AUC283422
RENAULT
LATITUDE
06.02.2018
AIG

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>CRA/BU</i> 1,108.46	—
2	1	BUMPER LOWER REAR	\$	<i>BT10.1</i> 768.84	—
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>By</i> 777.52	—
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1	BOOT REAR	\$	<i>BT</i> 2,872.68	—
14	1	BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>MR</i> 225.36	—
19	1	BOOT BADGE	\$	<i>MR</i> 225.36	✓
20	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1	BOOT INNER TRIM	\$	<i>SL</i> 586.45	} X
25	1	BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>SL</i> 671.45	
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
32	1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i> 671.45	
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-076

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD917P - AIG

35	1	WHEELARCH REAR RH	\$	Sm	543.47	X
36	1	TAILLAMP RH	\$	Sm	552.55	X
37	1	TAILLAMP PANEL RH	\$	N	986.70	X
38	1	TAILLAMP LH	\$	Sm	552.55	X
39	1	TAILLAMP PANEL LH	\$	N	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	B	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
44	1	EXHAUST REAR	\$	N	7,489.05	X
45	1	EXHAUST CAP REAR	\$	N	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	Sm	700.00	X
2	1SET	REAR BUMPER CLIP	\$	Nn	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	Nn	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	Nn	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	Nn	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	Nn	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	Nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	Nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	Nn	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	Nn	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	Nn	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	Nn	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	Nn	45.00	} X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	Nn	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	Nn	35.00	
17	1	FENDER INNER TRIM CLIP LH	\$	Nn	28.00	
18	1	FENDER INNER TRIM CLIP LH	\$	Nn	28.00	
19	1	TAILLAMP CLIP RH	\$	Nn	5.00	
20	1	TAILLAMP CLIP LH	\$	Nn	5.00	
21	2	REAR WINDSCREEN SELANT	\$	Nn	80.00	
22	1	WINDSCREEN MOULDING	\$	Nn	100.00	} X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Nn	100.00	
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm	385.00	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-076

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD917P - AIG

	\$	330.00
TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	} x
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees	\$	nn 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

(PARTS BY PARTS)

Repair Days

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental item(s) must be resurveyed and its price to final approval from Insurance Company

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

15 Days
5 days