

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 346S

MAKE :

MODEL : HYUNDAI i40

DATE 2/8/2018 12:05

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid X			\$ 1,681.40
	Boot Lid Rubber X			\$ 115.80
	Boot Lid Lock Upper ✓			\$ 137.90
	Boot Lid Lock Lower X			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Boot Lid Lamp (LH) ✓			\$ 556.80
	Bootlid Moulding ✓			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✓			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 180.00	\$ 360.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH/RH) ✓		\$ 32.00	\$ 64.00
	Rear Bumper Clips 10 pcs ✓			\$ 22.00
	Tail Lamp (LH) ?			\$ 565.60
	Rear Panel ✓			\$ 592.30
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Inner Panel X ✓			\$ 495.50
	Exhaust Pipe Insulator ?		\$ 58.55	\$ 117.10
	Exhaust Silencer ?		\$ 954.00	\$ 1,908.00
	Exhaust Pipe Hanger ?		\$ 58.55	\$ 117.10
	Exhaust Pipe Centre ?			\$ 1,150.30
	SUB TOTAL			\$ 19,041.75
	LESS 20% DISCOUNT			\$ 3,808.35
	DISCOUNTED TOTAL			\$ 15,233.40
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear No. Plate ✓			\$ 25.00 Nett
	Acknowledged by Repairer			\$ 190.70
	Labour Charge			\$ 600.00
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00 5%
	Wiring Charge			\$ 30.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 20
	Remove/Refix Exhaust Pipe			\$ 150.00 50?
	TOTAL LABOUR			\$ 1,800.00
	ESTIMATE TOTAL			\$ 10,024.10

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.