

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 8625J

MAKE :

MODEL : HYUNDAI i40

DATE 2/8/2018 14:49

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Radiator Grille H Emblem ✕			\$ 290.80
	Radiator Grille Chrome Moulding ✕			\$ 395.50
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Retainer Mounting (LH) ?			\$ 9.20
	Headlamp (LH) ✓			\$ 1,388.00
	<b>SUB TOTAL</b>			<b>\$ 5,306.40</b>
	<b>LESS 20%</b>			<b>\$ 1,061.28</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,245.12</b>
	<b>Labour Charge</b>			<b>2.00</b>
	Panel Beating			\$ <del>350.00</del> 180
	Spray Painting Charge			\$ <del>200.00</del>
	Wiring Charge			\$ <del>30.00</del> 20
	<b>TOTAL LABOUR</b>			<b>\$ 580.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,825.12</b>

Kalvin 16/6/14  
 8/2/13 1520hr.  
 2 Days  
 P/P  
 Before Paint & P/Ltd

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.