

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CQ/GST REG NO. 201019626G

SHD9263H - CHINA TAIPING**AAD1802-079***Not Authorized*
1/1/2018

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9263H - CANDY

KL1LA69RJBB064745

CHEVROLET

CHEVROLET EPICA 2.0

07.02.2018

CHINA TAIPING

PART			LIST	
1	1	Front Bumper	\$	<i>R</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1	Front Bumper Retainer LH	\$	<i>Di</i> 102.00 X
5	1	Bumper Fog Lamp Cover LH	\$	<i>Sn</i> 32.40 X
6	1	Front Fender LH	\$	<i>R</i> 837.60 ✓
7	1	Front Fender Liner LH	\$	<i>Sn</i> 47.00
8	1	Front Shock Absorber Assy LH	\$	<i>Sn</i> 216.17
9	1	Front Lower Arm LH	\$	<i>Sn</i> 283.00
10	1	Front Knuckle Arm LH	\$	<i>Sn</i> 230.00
11	1	Front Door LH	\$	<i>R</i> 1,133.00
12	1	Front Door Glass Guide LH Chrome Moulding	\$	<i>Sn</i> 60.00
13	1	Front Door Outer Handle LH	\$	<i>Sn</i> 125.00
14	1	Front Door Hinge Upper LH	\$	<i>R</i> 65.00
15	1	Front Door Hinge Lower LH	\$	<i>R</i> 65.00
16	1	Front Side View Mirror LH	\$	<i>Sn</i> 939.00
17	1	Side Rocker Panel Garnish LH	\$	<i>Sn</i> 236.40
18	1	Rear Door LH	\$	<i>R</i> 1,133.00
19	1	Rear Door Guide LH Chrome Moulding	\$	<i>Sn</i> 60.00
20	1	Rear Door Outer Handle LH	\$	<i>Sn</i> 125.00
21	1	Rear Door Weatherstrip LH	\$	<i>Sn</i> 138.79
22	1	Rear Fender LH	\$	<i>R</i> 1,145.00
23	1	Rear Fender Inner Cowling LH	\$	<i>Sn</i> 298.00
24	1	Rear Tail Lamp LH	\$	<i>Sn</i> 479.30
25	1	Rear Bumper	\$	<i>Sn</i> 1,202.00
26	1	Rear Bumper Beam	\$	<i>R</i> 239.94
27	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00
28	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76
29	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74
30	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9263H - CHINA TAIPING**AAD1802-079**

TOTAL	\$	11,472.10
10%	\$	1,147.21
	\$	10,324.89

Special Nett

1	1 Set Front Fender Liner Clip LH	\$	<i>nn</i>	30.00	} X
2	1 Door Sticker "Trans-cab" LH	\$	<i>nn</i>	80.00	
3	1 Door Sticker "6555-3333" LH	\$	<i>nn</i>	80.00	
4	1set Side Rocker Panel Garnish Clip LH	\$	<i>nn</i>	60.00	
5	1 Rear Tyre LH	\$	<i>nn</i>	360.00	
6	1 Rear Wheel Rim LH	\$	<i>nn</i>	254.00	
7	2 Rear Windscreen Sealant	\$	<i>nn</i>	80.00	
8	1 Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1Set Rear Bumper Parking Sensor	\$	<i>nn</i>	300.00	
10	1Set Rear Bumper Fastener Clip	\$	<i>nn</i>	30.00	
11	1Set Rear Fender inner cowling clip LH	\$	<i>nn</i>	30.00	

TOTAL	\$	1,404.00
TOTAL PARTS	\$	11,728.89

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *4000*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected
Portion.

\$ 2,800.00 *4000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ *nn* 380.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9263H - CHINA TAIPING**AAD1802-079**

Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X

TOTAL	\$	7,290.00
Over All Total	\$	19,018.89

REPAIR DAYS~~10~~ DAYS*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: