

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 4317K

MAKE :

MODEL : HYUNDAI SONATA

DATE 2/8/2018 16:11

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (RH) ✓			\$ 230.20
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>LH repair RH ✓</i>		\$ 38.00	\$ 76.00
	Rear Panel ✕			\$ 391.80
	Rear Panel Garnish ✕			\$ 95.80
	SUB TOTAL			\$ 3,940.10
	LESS 20%			\$ 788.02
	DISCOUNTED TOTAL			\$ 3,152.08
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70 Nett
				\$ 165.70
	Labour Charge			
	Panel Beating			\$ 850.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>360</i>
	Wiring Charge			\$ 30.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 1,650.00
	ESTIMATE TOTAL			\$ 4,967.78
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				