

15/5/2018

INS. CASE OWNER:

Gerald

CC 4 / LPC180 02692 16WSE 02

LKK:

IDAC:

Surveyor:

XLD

DOI:

X13/18

Date / Time:

03/02/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 8222X

Name of Insured:

TAN CHONG LUANG

Insured Tel No.:

HP: 922 9118

Excess Sec II :SS

D.O.A: 06/02/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: NA MENG ANN

Driver Tel No.: 9230 9118

(V/L: ☒ YES / NO)

Claim No.:

17/13/18/UP05/020383

Policy No.:

217UP05013703

Make / Model:

TOYOTA HARRIER - 2.0 CAT

Place of Accident:

ALONG RICE TOWARDS SLB SLIP ROAD

OI GIA REPORT: ☒ YES / NO: TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final? Yes / No

SLJ 17043



INSRS:

WSP: Borneo Motors (S) Pte Ltd

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

09/02/18 Curian?

SLJ 17043 - X, SLB 8222X - X

14/2/18

Email workshop liability clear.

17/4/18

File pass to typist type report

26/6/18

Email to LPC to seek mandate

27/6/18

Email from LPC approve mandate

RECEIVED 27 JUL 2018

RECEIVED 17 APR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

S\$

100

(Agreed / Assessed) BOLA S/N No.:

27.

Repair Cost:

S\$

9797.97

Loss of Rental (LOR):

S\$

500.00

(S x days) x100

Loss of Use (LOU):

S\$

(S x days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

10299.97

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

10299.97

Name 1:

Borneo Motors (S) Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18002692/Gws3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 09-02-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 8222X	Veh. Inspected	SLJ 1704B
Policy No.	Z17VP05013703	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020383	Excess (\$)	0.00
Assign From		Assign Date	09/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/02/2018	Inspection Date	05/03/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 409611		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto.
Consultants
Pte Ltd

Company Registration No. 199607198R

51 BLAYE L, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020383
Our ref: CC4/LPC18002692/Gws3

Date: 07/03/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLJ 1704B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.03.2018 at the M/s Borneo Motors (S) Pte Ltd (Ubi) have the following to report:-

Workshop Estimate Amount	: S\$	14,636.28
Revised Estimate Amount	: S\$	9,156.98
"Check" Items Amount	: S\$	1,638.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Thursday, 8 February, 2018 5:16 PM
To: SuraidahB.Saidi@inchcape.com.sg; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: Our Ref: 17/18/18/VP05/020383 Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018
Attachments: img-180208081309-0001.pdf; DSC08210.JPG; DSC08211.JPG; DSC08212.JPG; DSC08213.JPG; DSC08214.JPG

Dear Suraidah,

We will be appointing LKK Auto Consultants Pte Ltd to survey SLK 1704B.

Dear Catherine,

FYA.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

08-02-2018 @ 5:26pm
Sam veh not in

From: Suraidah B Saidi PTCBC [mailto:SuraidahB.Saidi@inchcape.com.sg]
Sent: Thursday, 8 February, 2018 10:25 AM
To: GERALD POH WEE BIN; ONG LI LI
Subject: Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SLB8222X thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Sam Joi @ 9847 6209 / 6631 1687** is located at **17 Ubi Road 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,
SURAIDAH
TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLJ1704B
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	WISH 1.8 CVT
Chassis No. :	JTDGG20W80J006052
Propellant :	Petrol
Engine No. :	2ZR1859832
Engine Capacity :	1798 cc
Maximum Power Output :	105.0 kW (140 bhp)
Maximum Laden Weight :	1935 kg
Unladen Weight :	1360 kg
Year Of Manufacture :	2016
Original Registration Date :	30 Nov 2016
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$56,206.00
COE Expiry Date :	29 Nov 2026
Road Tax Expiry Date :	29 Nov 2018
PARF Eligibility Expiry Date :	29 Nov 2026
Inspection Due Date :	29 Nov 2019
Intended Transfer Date :	06 Mar 2018
CO2 Emission :	159.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable	

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 Road Transport Act. 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2013281 Account No. : 14888
Coverage : Comprehensive (SmartDrive Toyota Prestige)
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : CHENG TECK SOON
Vehicle Registration No. : SLJ1704B
Period of Insurance : From 30/11/2017 To 29/11/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any other person who is driving on the Policyholder's order or with his permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes. (01)

Basic Own Damage Excess : SGD 500.00

An Additional Excess is applicable as follows:
S\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOAGPH on 31/10/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6848573H



CHENG TECK SOON

莊德順

CHINESE

Date of Birth

29-12-1968

Country of Birth

SINGAPORE

Sex

M

S6848573H

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6848573H
Name:

CHENG TECK SOON

Birth Date: 29 Dec 1968

Issue Date: 06 Oct 2003



000893359D



NRIC No. S6848573H



Blood Group

O

Date of Issue

09-12-1993

APT BUK 201D COMPASSVALE DRIVE #10-02

SINGAPORE 541201

NRIC No. S6848573H

Date:

27-06-2000

No. 3351387

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class:

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

29 Nov 1996

NP 428A



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-021044
Date of Request: 07/02/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd
33 Leng Kee Road
Singapore 159096

Dear Sir/Madam,

Enquiry Date: 07/02/2018
Enquiry By: Angela Tan Hong Choo
TP Vehicle No: SLB8222X
Accident Date: 06/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLB8222X	Lonpac Insurance Bhd	23/05/2017-22/05/2018	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-021044
Date of Request: 07/02/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd
33 Leng Kee Road
Singapore 159096

Dear Sir/Madam,

Enquiry Date 07/02/2018
Enquiry By Angela Tan Hong Choo
TP Vehicle No. SLB8222X
Accident Date 06/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574	
		Document No		
		Document Date		
		0		
		08/02/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	2GE2OR	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLB8222X ACC DATE:06/02/2018 DRIVE IN:07/02/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	BP-SUBLET REAR NUMBER PLATE				80.00
3	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				169.50
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				169.50
5	S	BP-SUBLET SEALANT - REAR TAILGATE				80.00
6	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				339.00
7	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER				115.26
8	S	BP-SUBLET REPLACE REAR WINDSCREEN GLASS				436.00
9	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA R FILM				480.00
10	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				339.00
11	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				339.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607193

TO SECURITY GUARD

3607193

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007/ICLPI1	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574	
		Document No		
		Document Date		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	2GE20R	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE TAILGATE, REAR WINDSCREEN, EMBLEM, ETCSTRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1356 3390.00/
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				1668 2780.00 /
14	1	T52159-68907 REAR BUMPER COVER, <i>re</i>	1.00	574.90		574.90/
15	2	T52576-68020 L/R SIDE BPR RETAINER, <i>- 1/2 pc</i>	1.00	44.40		44.40/
16	3	T52575-68020 R/R SIDE BPR RETAINER <i>- 1/2 pc</i>	1.00	44.40		44.40/
17	4	S52161-0K040 CLIPS <i>1/2 pc</i>	10.00	3.90		39.00/
18	5	T58307-68031 REAR LOWER FLR PANEL, <i>1/2 pc</i>	1.00	520.00		520.00 X
19	6	T67935-68020 B0 PLATE BACK DOOR <i>1/2 pc</i>	1.00	288.70		288.70 X
20	7	T67005-68041 PANEL ASSY, BACK DOOR <i>1/2 pc</i>	1.00	1428.40		1428.40/
21	8	T67881-68030 WEATHERSTRIP, BACK <i>1/2 pc</i>	1.00	325.80		325.80 X
22	9	T68105-68071 REAR BACK DOOR GLASS, <i>1/2 pc</i>	1.00	1009.20		1009.20/
23	0	T67750-68020 B1 REAR BACK DOOR BOARD, <i>1/2 pc</i>	1.00	352.40		352.40 X
24	1	T69350-28151 LOCK ASSY, BACK DOOR <i>X</i>	1.00	399.60		399.60 X
25	2	T90975-02086 FRONT BONNET EMBLEM, <i>1/2 pc</i>	1.00	72.20		72.20/
26	3	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MATI <i>- 1/2 pc</i>	1.00	39.70		39.70/
27	4	T76811-68130 GARNISH, BACK DOOR, <i>X</i>	1.00	281.00		281.00 X
28	5	T76817-50010 CLIP, BACK DOOR <i>X</i>	4.00	1.90		7.60 X
29	6	T75819-33010 CLIP, LUGGAGE <i>X</i>	2.00	3.30		6.60 X
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607194

TO SECURITY GUARD

3607194

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingapore.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!


Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
	Document No 0	
	Document Date 08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	2GE20R	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Jo1	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T08826-08609 SUPER FAST URETHANE BLACK / <i>4 MLC</i>	1.00	90.08		90.08 /
31	8	T08826-08682 SINGLE STEP PRIMER /	1.00	173.44		173.44 /
32	9	SP2061-12010 16 070 SENSOR <i>RNN</i>	1.00	151.60		151.60 x
33	0	T75443-ELGAN ELEGANCE EMBLEM / <i>MLC</i>	1.00	40.00		40.00 /

*5 Days.
before paint photos.
Guo Qiao - 82880282
05/3/18*

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
 Please acknowledge receipt of vehicle and parts of the following: • To survey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Parts	5,889.02	14,636.28
	Labour	30.00	GST 7.00%
	Materials	8,717.26	1,024.54
	Lubrication/Fluid	0.00	Less
	Others	0.00	0.00
			Amount Due
			15,660.82

3607195**3607195**

TO SECURITY GUARD

Acknowledged by Repairer

 Signature: _____ DATE **08/02/2018**
 TIME **08:14**

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO **SLJ1704B**

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Lonpac Insurance Berhad
100 Beach Road
#19-00 Shaw Tower
Singapore 189702
Attn: Ms Lily Koh/Mr Chia

S1000007/ICLP11

39006403

05/04/2018

Mr Cheng Teck Soon
201D Compassvale Drive
#10-557
Singapore 544201

Mobile: 96218574

16	HPXNP S6	ZGE20R	30/11/2016	SLJ1704B	22937	16017	7DS/SLJ1704B/06021	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	09/03/2018	9.00	09/03/2018	9.00	
1	Z	BP-SUNDRY	SUNDRIES	TP-DIRECT SETTLEMENT				30.00
		TP-SLB8222X		ACC DATE:06/02/2018				
		DRIVE IN:07/02/2018						
		DATE-IN:05/03/2018		DATE SURVEY:05/03/2018				
		NO OF REPAIR DAYS:5 DAYS						
		BY:GUO QIANG(LKK)						
2	S	BP-SUBLET	REAR NUMBER PLATE	E33				80.00
3	S	BP-SUBLET	DRILL HOLE & INSTALL REVERSE SENSOR	A45				169.50
4	S	BP-SUBLET	CHECK LIGHTING & CONDUCT WATER LEAK TEST	A45				169.50
5	S	BP-SUBLET	SEALANT - REAR TAILGATE	A45				80.00
6	S	BP-SUBLET	REMOVE & INSTALL REAR COMPARTMENT CARPET	A45				339.00
		GARNISH A	TRIMMING TO ASSIST REPAIR					
7	S	BP-SUBLET	REMOVE & INSTALL TAILGATE TOP SPOILER	A45				115.26
8	S	BP-SUBLET	REPLACE REAR WINDSCREEN GLASS	A45				436.00
9	S	BP-SUBLET	SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA	M30				480.00
		R FILM						
10	S	BP-SUBLET	TRANSFER & INSTALL COMPONENTS TO NEW TAI	A45				339.00
		LGATE						
11	S	BP-SUBLET	REMOVE & INSTALL REAR REVERSE CAMERA	A45				339.00

05/04/2018
14:19

SLJ1704B

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1189

Lonpac Insurance Berhad
100 Beach Road
#19-00 Shaw Tower
Singapore 189702
Attn: Ms Lily Koh/Mr Chia

S1000007 / ICLPI1

39006403

05/04/2018

Mr Cheng Teck Soon
201D Compassvale Drive
#10-557
Singapore 544201
Mobile: 96218574

16 HPXNP S6 ZGE20R 30/11/2016 SLJ1704B 22937 16017 7DS/SLJ1704B/060211
JTDGG20W80J006052 2ZR1859832 60 Sam San Joi 09/03/2018 9.00 09/03/2018 9.00

12	S	BP-SUBLET	REPLACE TAILGATE, REAR WINDSCREEN, EMBLEM, A45			1356.00
			ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS			
13	S	BP-SUBLET	RESPRAY JOB ON REAR ACCIDENT AFFECTED AR A45			1668.00
			EAS			
14	1	T52159-68907	COVER RR BUMPER	1.00	574.90	574.90
15	2	T52576-68020	RETAINER RR BUMPER	1.00	44.40	44.40
16	3	T52575-68020	RETAINER RR BUMPER	1.00	44.40	44.40
17	4	S52161-0K040	PIECE, RR BUMPER	10.00	3.90	39.00
18	5	T67005-68041	PANEL ASSY, BACK DOOR	1.00	1428.40	1428.40
19	6	T68105-68071	GLASS BACK DOOR	1.00	1009.20	1009.20
20	7	T90975-02086	EMBLEM, SYMBOL	1.00	72.20	72.20
21	8	T75444-68010	PLATE, LUGGAGE COMPT	1.00	39.70	39.70
22	9	T08826-08609	SUPER FAST URETHANE BLACK	1.00	90.08	90.08
23	0	T08826-08682	SINGLE STEP PRIMER	1.00	173.44	173.44
24	1	T75443-ELGAN	ELEGANCE EMBLEM	1.00	40.00	40.00

9,156.98

3,555.72 GST 7.00% 640.99

30.00 0.00

5,571.26

0.00

0.00

9,797.97

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

05/04/2018

14:19

SLJ1704B

Shirley Hiew (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 9 February 2018 3:52 PM
To: Shirley Hiew (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020383 Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018 *** LKK REF - CC4/LPC18002692/ws3 09022018154857.pdf
Attachments:

Dear Shirley,

We attached a copy of insured's GIA report for your attention.

The premium for the policy has been settled.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 9 February, 2018 3:44 PM
To: 'mt_claim@lonpac.com'; Vic (LKKAuto)
Cc: ERIC WOO JUN KIAT; 'llong@lonpac.com'; GERALD POH WEE BIN; Admin A; Joy Irene (LKKAuto)
Subject: FW: Our Ref: 17/18/18/VP05/020383 Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018 *** LKK REF - CC4/LPC18002692/ws3

Your ref: 17/18/18/VP05/020383
LKK ref: CC4/LPC18002692/ws3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Borneo Motors (S) Pte Ltd - Ubi.

Enclosed for your perusal is:

- TP's GIA report
- TP estimated cost of repair

We have not authorized repairs.

We will revert preliminary advice in due course.

Meanwhile, Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 8 February 2018 5:27 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: Our Ref: 17/18/18/VP05/020383 Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Thursday, 8 February, 2018 5:16 PM

To: SuraidahB.Saidi@inchcape.com.sg; assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: Our Ref: 17/18/18/VP05/020383 Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018

Dear Suraidah,

We will be appointing LKK Auto Consultants Pte Ltd to survey SLK 1704B.

Dear Catherine,

FYA.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]

Sent: Thursday, 8 February, 2018 10:25 AM

To: GERALD POH WEE BIN; ONG LI LI

Subject: Direct Settlement (SM) - Accident Involving SLJ1704B & SLB8222X DOA 07.02.2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SLB8222X thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Sam Joi @ 9847 6209 / 6631 1687** is located at **17 Ubi Road 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18002692/Gwa3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 01-08-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 8222X	Veh. Inspected	SLJ 1704B	
Policy No.	Z17VP05013703	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020383	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W80J006052	Colour	WHITE	
Odometer	28950	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2018	Inspection Date	05/03/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 409611			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1704B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	80.00	80.00
1	REAR BUMPER COVER , (SN)	DEFORMED	574.90	574.90
1	L/R SIDE BPR RETAINER , (SN)	NECESSARY	44.40	44.40
1	R/R SIDE BPR RETAINER , (SN)	NECESSARY	44.40	44.40
10	CLIPS @\$3.90 (SN)	NECESSARY	39.00	39.00
1	REAR LOWER FLR PANEL, (SN)	NOT NECESSARY	520.00	-
1	PLATE BACK DOOR (SN)	NOT NECESSARY	288.70	-
1	PANEL ASSY ,BACK DOOR (SN)	BUCKLED	1,428.40	1,428.40
1	WEATHERSTRIP ,BACK (SN)	NOT NECESSARY	325.80	-
1	REAR BACK DOOR GLASS (SN)	NECESSARY	1,009.20	1,009.20
1	REAR BACK DOOR BOARD (SN)	NOT NECESSARY	352.40	-
1	LOCK ASSY ,BACK DOOR (SN)	NOT NECESSARY	399.60	-
1	FRONT BONNET EMBLEM , (SN)	NECESSARY	72.20	72.20
1	PLATE ,LUGGAGE COMPT (VALVE MATI) (SN)	NECESSARY	39.70	39.70
1	GARNISH ,BACK DOOR , (SN)	NOT NECESSARY	281.00	-
4	CLIP ,BACK DOOR (SN)	NOT NECESSARY	7.60	-
2	CLIP ,LUGGAGE (SN)	NOT NECESSARY	6.60	-
1	SUPER FAST URETHANE BLACK (SN)	NECESSARY	90.08	90.08
1	SINGLE STEP PRIMER (SN)	NECESSARY	173.44	173.44
1	070 SENSOR (SN)	NOT NECESSARY	151.60	-
1	ELEGANCE EMBLEM (SN)	NECESSARY	40.00	40.00
			5,999.02	3,665.72
LABOUR				
DRILL HOLE & INSTALL REVERSE SENSOR .			169.50	169.50
CHECK LIGHTING & CONDUCT WATER LEAK TEST.			169.50	169.50
SEALANT -REAR TAILGATE .			80.00	80.00
REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH A TRIMMING TO ASSIST REPAIR .			339.00	339.00
REMOVE & INSTALL TAILGATE TOP SPOILER .			115.26	115.26
REPLACE REAR WINDSCREEN GLASS .			436.00	436.00

Report Ref No. CC4/LPC18002692/Gwa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM .		480.00	480.00
	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE .		339.00	339.00
	REMOVE & INSTALL REAR REVERSE CAMERA.		339.00	339.00
	REPLACE TAILGATE ,REAR WINDSCREEN EMBLEM ,ETCSTRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS.		3,390.00	1,356.00
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS.		2,780.00	1,668.00
			8,637.26	5,491.26
	GRAND TOTAL		14,636.28	9,156.98
RECOMMENDED COST OF REPAIRS				9,156.98

Report Ref No. CC4/LPC18002692/Gwa3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.