

22/03/2001

ASS. REC. BY:

REF: CS/FCI18002694/Ttfd3n4 Special Instruction:

Surveyor:

Tau fitch

ASSIGNMENT (Office)

CWS

From (Person): joanne yang

of FCI

Date/Time: 8/2/18 @ 4:58 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLJ 3990C

Insured: SHA 36872

at Workshop m/s

World Auto

Tel: 6362 1776

of

No. 1 Kranji loop

Policy No.:

Claim No: D18000837MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time:

9:20am @ 9/2/18

Person Contacted:

Daniel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 3990C-X

SHA 36872 - CC3 KA114015653/Hluy3q)

D.O.A: 13/8/14

Part by Part \$1794.24 (Red: 3087.60: 63%)

Tanjin

12/18

SLT 3990C

20/6 Dec.

Estimate No.

① TO WS TO RES CORRES EVAL INV M.

To Report Ref No.

at Reference No.

to - carrying change -

Report

Policy No.

Diamond

Summary


Excess

Dental Record

Name of car

Policy Condition

Remarks: The Van had commenced its repair at the time of inspection



Est. or Market Value

CAC Accident Report Consistent? Yes or No

CAC Rep. Report Consistent? Yes or No

Est. Report days Rep. Yes or No

Est. Report days Rep. Yes or No

CAC / REP / REP / 24 HRS Lwr

Date Person Contacted

Vehicle IN / OUT

①

Honda Vezel

1496

Black

124822

RU 31214812

Car Dent Good Fair Poor Burnt

Cracking Moderate Latched Latched Burnt

Brake Moderate Latched Latched Burnt

Mod. Nil Burn STD A/R

Tyre Size 205/60R16

BS / DUN / EXNOVA GH / PS / U24 / MIC / GTS / RB / SUM

TOYO / YOKO

6.1

Rep.

Rep.

Rep.

Rep.

Surveyor

World Auto

Des. of Damages: Fr. Rear. DB. N.B. U.C. Roofing

Fut o/s.

The U.C. Chassis frame Body Structure affected due to collision

Date Time Action Instruction SLG 229413 Resurvey.

RECEIVED 06 MAR 2018

Costing Refused



Prelim. Report

GB Typist



Final Report

Costing Refused

Days Of Repair 3

Resurvey No. of Time

Add Fee



Cost Fee



Cost Fee



Cost Fee



Cost Fee

135
50
32

TP

17914-24

217



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002694/M1td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3687Z	Veh. Inspected	SLJ 3990C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000837MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/01/2018	Inspection Date	09/02/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	26-01-2018	Our Ref No. D18000837MFSH
Accident Date	24-01-2018	Claim Type. Third Party
Insured Vehicle	SHA3687Z	Third Party Vehicle. SLJ3990C
Survey Location	47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG	
Contact Person.	DANIEL	
Contact No.	64513933/ 0	Fax No. 64557576
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234365)



PRI Documents



Close



PRI Header Details

Claim No	D18000837MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WORLD A
Workshop Name	WORLD AUTO PTE LTD (Contact Person : DANIEL)	Survey Location & Contact Details	47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG Mobile: 0 , Phone: 64513933 , Fax: 64557576 EmailId: DANIEL@WORLDAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3687Z	TP Vehicle No	SLJ3990C
PRI Recieved Date	08-02-2018 01:58:26 PM	Surveyor Appointed Date	08-02-2018 04:57:02 PM	Surveyor Accept Date	09-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-02-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

Surveyor Job Remarks

Remarks

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201823

Date : 25/01/2018

Vehicle Num. : SLJ 3990C (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/01/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | | | |
|-----|---|-------------------------------------|----------|-----|
| 1. | 1 | FRONT BUMPER | 495.00 | de |
| 2. | 1 | FRONT BUMPER SIDE RETAINER R/H | 75.00 | de |
| 3. | 1 | FRONT FENDER WHEEL ARCH MOULDING RH | 152.80 | de |
| 4. | 1 | HEADLAMP ASSY RH | 1,850.00 | X |
| 5. | 1 | HEADLAMP TOP BRACKET RH | 68.00 | X |
| 6. | 1 | HEADLAMP LOWER BRACKET RH | 78.00 | X |
| 7. | 1 | FOG LAMP ASSY - RH | 315.00 | cro |
| 8. | 1 | FOG LAMP COVER RH | 68.00 | X |
| 9. | 1 | FOG LAMP BRACKET RH | 65.00 | X |
| 10. | 1 | FRONT GRILLE | 380.00 | cro |
| 11. | 1 | FRONT GRILLE MOULDING | 368.00 | X |

List Total S\$:

20.00% Discount S\$:

3,914.80

782.96

3,131.84

SPECIAL NETT ITEMS :

- | | | | | |
|----|------|-------------------|-------|----|
| 1. | 1SET | FRONT BUMPER CLIP | 30.00 | de |
|----|------|-------------------|-------|----|

Special Nett Total S\$:

30.00

LABOUR :

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

120.00 30

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS

800.00 300

PUTTY AND SPRAY PAINT ALL AFFECTED AREAS

800.00 300

Labour Total S\$:

1,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed

for WORLD AUTO PTE LTD

is subject to confirmation from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

E. & O.E.

Total S\$:

4,881.84

Tanpin 97495749 / 62563561
WP' 9/2/18
3days.
Resurvey before paint
sur @ lkkauto.com

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED
 80 ROBINSON RD #09-02/03
 068898

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201823

Date : 25/01/2018
 Vehicle Num. : SLJ 3990C (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 24/01/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER	495.00	de
2.	1	FRONT BUMPER SIDE RETAINER R/H	75.00	ne
3.	1	FRONT FENDER WHEEL ARCH MOULDING RH	152.80	de
4.	1	HEADLAMP ASSY RH	1,850.00	X } un
5.	1	HEADLAMP TOP BRACKET RH	68.00	X }
6.	1	HEADLAMP LOWER BRACKET RH	78.00	X }
7.	1	FOG LAMP ASSY - RH	315.00	cro
8.	1	FOG LAMP COVER RH	68.00	X un
9.	1	FOG LAMP BRACKET RH	65.00	X un
10.	1	FRONT GRILLE	380.00	X cro
11.	1	FRONT GRILLE MOULDING	368.00	X un
List Total S\$:			3,914.80	
20.00% Discount S\$:			782.96	
			3,131.84	

1.	1SET	SPECIAL NETT ITEMS :		
		FRONT BUMPER CLIP	30.00	ne
Special Nett Total S\$:			30.00	
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			120.00	30
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS			800.00	300
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS			800.00	300
Labour Total S\$:			1,720.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed

for WORLD AUTO PTE LTD
 is subject to the terms and conditions of the Insurance Policy

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 4,881.84

Tanjin 97495749 / 62563561
 WP' 9/2/18
 3 days.
 * Resurvey before paint
 suv@lkkauto.com

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED
80 ROBINSON RD #09-02/03
068898

Attention : Motor Claim Department
Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201823

Date : 25/01/2018
Vehicle Num. : SLJ 3990C (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 24/01/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER	495.00	de
2.	1	FRONT BUMPER SIDE RETAINER R/H	75.00	ne
3.	1	FRONT FENDER WHEEL ARCH MOULDING RH	152.80	de
4.	1	HEADLAMP ASSY RH	1,850.00	X
5.	1	HEADLAMP TOP BRACKET RH	68.00	X
6.	1	HEADLAMP LOWER BRACKET RH	78.00	X
7.	1	FOG LAMP ASSY - RH	315.00	no
8.	1	FOG LAMP COVER RH	68.00	X
9.	1	FOG LAMP BRACKET RH	65.00	X
10.	1	FRONT GRILLE	380.00	X
11.	1	FRONT GRILLE MOULDING	368.00	X
List Total S\$:			3,914.80	1417.80
20.00% Discount S\$:			782.96	283.56
			3,131.84	1134.24
SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP	30.00	ne
Special Nett Total S\$:			30.00	30
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			120.00	30
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS			800.00	300
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS			800.00	300
Labour Total S\$:			1,720.00	630

Parts -	1417.80	E. & O.E.	Total S\$:	4,881.84
-20%	283.56			
	1134.24			
sn	30.00			
labour	630.00			
net	1794.24			

for WORLD AUTO PTE LTD

Tanpin 97495749 / 62563561
WP' 9/2/18
3 days.
Resuming before paint
3 days.
suo@lkkauto.com

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002694/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3687Z	Veh. Inspected	SLJ 3990C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000837MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31214812	Colour	BLACK	
Odometer	124822	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	6 mm	
L/H Front Tyre	215/60 R16	GITI	6 mm	
R/H Rear Tyre	215/60 R16	GITI	6 mm	
L/H Rear Tyre	215/60 R16	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2018	Inspection Date	09/02/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3990C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	495.00	495.00
1	FRONT BUMPER SIDE RETAINER R/H	NECESSARY	75.00	75.00
1	FRONT FENDER WHEEL ARCH MOULDING RH	DEFORMED	152.80	152.80
1	HEADLAMP ASSY RH	NOT NECESSARY	1,850.00	-
1	HEADLAMP TOP BRACKET RH	NOT NECESSARY	68.00	-
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	78.00	-
1	FOG LAMP ASSY-RH	CRACKED	315.00	315.00
1	FOG LAMP COVER RH	NOT NECESSARY	68.00	-
1	FOG LAMP BRACKET RH	NOT NECESSARY	65.00	-
1	FRONT GRILLE	CRACKED	380.00	380.00
1	FRONT GRILLE MOULDING	NOT NECESSARY	368.00	-
	LESS 20% DISCOUNT		-782.96	-283.56
			3,131.84	1,134.24
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			30.00	30.00
LABOUR				
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		120.00	30.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		800.00	300.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		800.00	300.00
			1,720.00	630.00
GRAND TOTAL			4,881.84	1,794.24
RECOMMENDED COST OF REPAIRS				1,794.24

Report Ref No. CS/FCI18002694/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.