

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Feb-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1486 J


1 pc	Emblem I30	\$	27.80
1 pc	Emblem CRDI	\$	29.40
1 pc	Emblem Hyundai	\$	29.40
1 pc	Rear bumper	\$	811.11
1 pc	Rear bumper sponge	\$	79.20
1 pc	Rear bumper reinforcement	\$	815.64
1 pc	Rear bumper reinforcement centre	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40
1 pc	Tailgate lower garnish	\$	362.61
		\$	2,338.76
	Less 20%	\$	467.75
		\$	1,871.01

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
1 set	Tailgate sticker	\$	100.00
	Sundry	\$	50.00 20
	To dismantle and replace reverse sensor and test system	\$	80.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc	\$	750.00 300
	To putty and spray painting on the rear bumper, tailgate lower garnish, end panel	\$	600.00 360
	To apply rustproofing on the repaired and replaced panels	\$	120.00 X
	Total	\$	3,899.01

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



Ka Wei (LKK)
 11 9/2/18 1600hr.
 3 days.
 PIP
 Before paint + photo