

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3550T

DATE 9/2/2018 11:37

MAKE :

MODEL : HYUNDAI i40

PbyP
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement X			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) X		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket X			\$ 49.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge X			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 380.00 200	
	Spray Painting Charge			\$ 200.00 150	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,461.58	
<p>Kahr '16/16/1</p> <p>M 9/2/18 1620 hrs</p> <p>2 Days</p> <p>P/P</p> <p>Before Paint photo</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					