

22/02/2018

ASS. REC. BY:

REF: CS/FCI18002709/Uqds/v

Special Instruction:

Surveyor: MercusASSIGNMENT (Office)

CWS

From (Person): Sitharaof FCIDate/Time: 9/2/18 @ 10.28am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 4233 G

Insured:

SHC 7391 P

at Workshop m/s

Pegasus

Tel:

83388418

of

SMESTO Deh Fene TO Keler, Bulup Ave 6.

Policy No:

D-18088937 MFSH

Claim No:

D18001231 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2018

CA / REV / REP. / REV 24 HRS

lwpSME @ Kaki Bkt

H.O.D. Endorsement:

Date/Time:

10.34am @ 9/2/18

Person Contacted:

GanyVehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 4233 G-XSHC 7391 P-CS/FCI16021778/Kltbn2D.O.A: 9/11/1612/2/18 @ 5.20pm revised to Sithara by email

Form 101

REP: FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: 9/2/18  
 Estimated Cost: \_\_\_\_\_  
 OO (TP) / WS / TP RES / CO RES / EVA / INV / MV \_\_\_\_\_  
 To inspect Vehicle No: SLR 12336  
 at Worksite no: SME Motor  
 of: \_\_\_\_\_  
 Insured: SH/C 7391P  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	O/S

Bas. or Market Value: \_\_\_\_\_  
 I/OAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 G/F PR Seen: ✓ Consistent? Yes or No  
 Est. Repair: 9 days Pass: Yes or No  
 Lum Sum: 1.31 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS / w/p  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLR 42336 In Reg: 8 17  
 Type: C M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover  
 Truck / Trailer or CA /  
 Make: Mercedes / Hybrid 1496  
 Colour: Black Insured / Std / Nil / NA  
 Sp Reading: 37595 T-Ratio Insured / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 C/Vo: RN 31254275  
 Gen. Cond: Good Fair / Poor / Burnt  
 Steering: Good Jammed / Leaked / Burnt or  
 Brakes: Good Jammed / Leaked / Burnt or  
 Mod: Nil S/Rim / STD A/Rim or  
 Tyre Size: P \_\_\_\_\_  
R 215/60R16  
 BS / SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: 6 Rear: 6  
 R/Bal: \_\_\_\_\_ L/Bal: \_\_\_\_\_  
 D/OA: 8/2/18 D/OI: 9/2/18  
 Surveyed at: Kelantan  
 Des. of Damages: Frt. / Rear / O/S / NS / U/C / Roof-top or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision

CMY 16-17 Feb SME  
4448 confirmed final by \$10867.28 with ADYing.  
(Bad to 1632.64, 13/1)

RECEIVED 6 APR 2018

Desk/Time File Pass to: ☐ Prel. Report  
06/11/18 ☐ Final Report  
 Date/Time File Return to: \_\_\_\_\_  
 Report Format: 7P  
 Lum Sum / LB: 10867.28

Days Of Repair: 9  
 Resurvey No. of Trip: 2  
 Add Fee: ☐ Site Insp. \$  
☐ Intensive \$  
☐ Tech \$  
☐ Clean up \$  
 Sum. Fee: 245.30  
170+30  
50  
50+50  
148  
498

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002709/Uqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-02-2018



Code : FCI2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHC 7391P	Veh. Inspected	SLR 4233G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001231MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	09/02/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	08/02/2018	Inspection Date	09/02/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**MOTOR SURVEY ASSIGNMENT**

Date	08-02-2018	Our Ref No.	D18001231MFSH
Accident Date	08-02-2018	Claim Type.	Third Party
Insured Vehicle	SHC7391P	Third Party Vehicle.	SLR4233G
Survey Location	51 DEFU LANE 10		
Contact Person.	GARY SEAH		
Contact No.	68581846/ 83388418	Fax No.	64876070
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234859)



PRI Documents



Close



PRI Header Details

Claim No	D18001231MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PEGASUS EN PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : GARY SEAH)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 83388418 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS2@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO E		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7391P	TP Vehicle No	SLR4233G
PRI Recieved Date	08-02-2018 10:04:33 PM	Surveyor Appointed Date	09-02-2018 10:27:28 AM	Surveyor Accept Date	09-02-2018 10:4

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/> No 1
-----------------------------	--	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 12 February 2018 5:20 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001231MFSH/1  
**Attachments:** CSFCI18002709Uqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLR 4233G.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 9 February 2018 1:03 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18001231MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 9 February 2018 10:28 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001231MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001231MFSH

Date: 12 February 2018

Our Ref: CS/FCI18002709/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 4233G**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/02/2018 at the premises of M/s PEGASUS, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 11,773.52</u>
Revised Estimate Amount	: <u>S\$ 9,895.84</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLR4233G
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5954292
Chassis No.:	RU31254275
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,756.00
Original Registration Date:	15 Aug 2017
First Registration Date:	15 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$45,189.00
<b>Total Rebate Amount:</b>	<b>\$48,939.00</b>

The information contained herein is correct as at 09 Feb 2018



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/02/2018 14:47
Date Of Accident	08/02/2018 09:10
Exact Location Of Accident	ALONG SLE TOWARD WOODLAND
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR4233G
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

#### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

#### Driver

Name of Driver	RAKESKUMAR PANDEY S/O BIKRAMA DITYA PANDEY
NRIC No	S8436847D
Date Of Birth	18/11/1984
Occupation	OUTDOOR
Date Of Driving Pass	03/05/2005
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91686784
Fax Number	
Contact Number	
Email Address	RPCHUPARUSTAM6@GMAIL.COM

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

5

#### DETAILS OF INJURED PERSON 1

Name RAKESKUMAR PANDEY S/O BIKRAMA DITYA PANDEY  
Approximate Age  
Injuries Sustain BACKLASH  
Injured person in which vehicle? SLR4233G  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name AMELIA TAN  
Approximate Age  
Injuries Sustain BACKLASH  
Injured person in which vehicle? SLR4233G  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name PASSENGER  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SHC7391P  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

ACCIDENT STATEMENT (2000 characters)

I'M N THE DATE AND TIME MENTIONED I WAS TRAVELLING ALONG THE SAID MENTIONED ROAD FOLLOWING VEHICLE INFRONT AT A DISTANCE. WHEN THE VEHICLE IN FRONT OF ME MADE A SUDDEN BARKING. I FOLLOWED SUIT AND MANAGED TO STOP IN TIME, WHEN MY VEHICLE WAS ABOUT TO STOP, IT WAS HIT FROM THE REAR BY VEHICLE B. MY PASSENGER AND ME HAD NO PHYSICAL INJURY BUT BOTH OF US WILL BE SEEING A DOCTOR DUE TO THE BACKLASH WE HAD SUSTAINED IN THE ACCIDENT. I WILL MAKE A POLICE REPORT AND FORWARD TO MARS HQ AS REQUESTED.

ONE OF THE PASSENGER IN VEHICLE B WAS CONVEYED TO HOSPITAL BY AMBULANCE.

STATEMENT WAS READ TO ME AND I ACKNOWLEDGED

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 February 2018 at 12:54 PM

Date/Time:

8 February 2018 at 12:54 PM



Claims Department  
FIRST CAPITAL INS PTE L  
6 Raffles Quay #21-00  
CITY HOUSE  
Singapore 048580

Not Submit  
rek  
Taking photo before party.  
9 day.  
9/2/18

Cover Note No : A29069766MKF

Date of accident : 08/02/18

Date: 08/02/18

Estimate To Repair: Honda Vezel Hybrid 1.5X Auto  
Vehicle No : SLR4233G  
Chassis No : RU3-1254275

Pages : 1 of 1

S/No	Quantity		Description	Amount
<b>SPARE PARTS ITEMS</b>				
1	1	pc	REAR GATE <i>rod 3 ad</i>	\$1,010.00
2	1	SET	REAR WINDSCREEN MOULDING <i>nee</i>	\$160.00
3	1	pc	REAR GATE "VEZEL" EMBLEM <i>nee</i>	\$45.00
4	1	pc	REAR GATE "HYBRID" EMBLEM <i>nee</i>	\$60.00
5	1	pc	REAR GATE LOCK <i>twi/shld</i>	\$105.00
6	1	pc	REAR GATE INNER TRIM BOARD <i>de/uegub</i>	\$225.00
7	8	PCS	REAR GATE INNER TRIM BOARD CLIPS <i>nee</i>	\$44.00
8	1	pc	REAR GATE INNER RUBBER <i>twi</i>	\$120.00
9	1	pc	REAR GATE INNER HANDLE <i>mis</i>	\$35.00
10	1	pc	REAR BUMPER (CENTRE) <i>25+03</i>	\$810.00
11	2	PCS	REAR BUMPER RETAINER <i>17</i>	\$70.00
12	10	PCS	REAR BUMPER CLIPS <i>nee</i>	\$55.00
13	2	PCS	REAR BUMPER SIDE (CORNER) <i>20/twi</i>	\$370.00
14	2	PCS	REAR BUMPER REFLECTOR <i>1/5 cra</i>	\$70.00
15	2	PCS	REAR TAIL LAMP <i>one</i>	\$980.00
16	2	PCS	REAR GATE LAMP <i>one</i>	<del>\$870.00</del>
17	1	pc	REAR END PANEL <i>rod 3 ad</i>	\$550.00
18	1	pc	REAR END PANEL TOP GARNISH <i>twi</i>	\$95.00
19	4	PCS	TOP GARNISH CLIPS <i>nee</i>	\$23.60
19	1	pc	REAR SPARE TYRE BOARD COVER <i>uegub/12</i>	\$370.00
20	1	pc	REAR SPARE TYRE TOOLS TRAY <i>one</i>	\$310.00
21	2	PCS	REAR FENDER INNER TRIM <i>de/10.1</i>	\$260.00
22	12	PCS	REAR FENDER INNER TRIM CLIPS <i>nee</i>	\$70.80
23	1	pc	REAR SPARE TYRE FLOOR PANEL <i>Buc/rod 3 ad</i>	\$900.00
24	1	pc	REAR SPARE TYRE FLOOR PANEL UNDER COVER <i>10.1</i>	\$160.00
25	8	PCS	REAR SPARE TYRE FLOOR PANEL UNDER COVER CLIPS <i>nee</i>	\$63.20
26	1	pc	REAR EXHAUST BOX <i>10/10.1</i>	\$550.00
27	1	pc	REAR EXHAUST BOX CHROME FINISHER <i>but</i>	\$175.00
28	2	PCS	REAR EXHAUST BOX RUBBER HOLDER <i>nee</i>	\$70.00
29	1	pc	REAR EXHAUST BOX HEAT SHIELD <i>2</i>	\$65.00
30	2	PCS	REAR FENDER PROTECTOR <i>de/10.1</i>	\$225.00
31	12	PCS	REAR FENDER PROTECTOR CLIPS <i>17</i>	\$70.80
Less 20% (LIST LESS %)				\$8,704.40
				\$1,740.88
				\$6,963.52

9246.60

Please conduct the survey at

Pegasus Engineering @ SME Motor Pte Ltd c/o No.1 Kaki Bukit Ave 6 #02-15, Autnbav @ Kaki Bukit, Singapore 539216

P 9371.60  
202  
7497.28  
10867.28



Claims Department  
FIRST CAPITAL INS PTE L  
6 Raffles Quay #21-00  
CITY HOUSE  
Singapore 048580

Cover Note No : A29069766MKF  
Date of accident : 08/02/18

Date: 08/02/18

Estimate To Repair: Honda Vezel Hybrid 1.5X Auto  
Vehicle No : SLR4233G  
Chassis No : RU3-1254275

Pages : 1 of 1

S/No	Quantity		Description	Amount	
<b>MISC ITEMS</b>					
1	1	pc	REAR NUMBER PLATE <i>sent</i>	\$50.00	40
2	1	pc	REAR WINDSCREEN SEALANT <i>sent</i>	\$60.00	40
3	1	SET	REVERSE SENSOR <i>sent</i>	\$250.00	200
4				\$360.00	
<b>LABOUR &amp; MISC. CHARGES</b>					
1			TO CHECK WIRING	\$50.00	30
2			TO REMOVE & REFIX REAR WINDSCREEN	\$120.00	✓
3			TO REMOVE & REFIX CUSHION AND SEATS	\$180.00	
4			TO REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	\$150.00	300
5			CAVITY PROTECTION ON ALL AFFECTED AREAS	\$120.00	80
6			TO REMOVE & REFIX EXHAUST BOX	\$150.00	60
7			TO REMOVE & REFIX HYBRID	\$280.00	200
8			TO CUT, WELD, STRAIGHTEN & REALIGN ALL AFFECTED PARTS	\$1,800.00	1400
9			TO SPRAY PAINT ON ALL AFFECTED AREAS	\$1,600.00	1200
			Total	\$4,450.00	1200
					3370

Please conduct the survey at

Pegasus Engineering @ SME Motor Pte Ltd c/o No.1 Kaki Bukit Ave 6 #02-15, Autobay @ Kaki Bukit, Singapore 539216

LKK Auto Consultants hereby notify  
the Respondent that the survey  
is conducted on a "Without Prejudice" basis  
and the Respondent is allowed  
complementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

1299.92

Please conduct the survey at  
Pegasus Engineering @ SME Motor Pte Ltd c/o No.1 Kaki Bukit Ave 6 #02-15, Autobay @ Kaki Bukit, Singapore 539216




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002709/Uqd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-04-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7391P	Veh. Inspected	SLR 4233G	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001231MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	09/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31254275	Colour	BLACK	
Odometer	37595	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/02/2018	Inspection Date	09/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4233G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR GATE	BADLY DENTED	1,010.00	1,010.00
1	SET REAR WINDSCREEN MOULDING	NECESSARY	160.00	160.00
1	REAR GATE 'VEZEL' EMBLEM	NECESSARY	45.00	45.00
1	REAR GATE 'HYBRID' EMBLEM	NECESSARY	60.00	60.00
1	REAR GATE LOCK	TWISTED / SHORTED	105.00	105.00
1	REAR GATE INNER TRIM BOARD	DEFORMED / WARPED	225.00	225.00
8	REAR GATE INNER TRIM BOARD CLIPS	NECESSARY	44.00	44.00
1	REAR GATE INNER RUBBER	TWISTED	120.00	120.00
1	REAR GATE INNER HANDLE	MISSING	35.00	35.00
1	REAR BUMPER (CENTRE)	DISTORTED	810.00	810.00
2	REAR BUMPER RETAINER	NOT NECESSARY	70.00	-
10	REAR BUMPER CLIPS	NECESSARY	55.00	55.00
2	REAR BUMPER SIDE (CORNER)	DENTED / TWISTED	370.00	370.00
2	REAR BUMPER REFLECTOR	N/S CRACKED	70.00	35.00
2	REAR TAIL LAMP	CRACKED	980.00	980.00
2	REAR GATE LAMP	CRACKED	870.00	870.00
1	REAR END PANEL	BADLY DENTED	550.00	550.00
1	REAR END PANEL TOP GARNISH	TWISTED	95.00	95.00
4	TOP GARNISH CLIPS	NECESSARY	23.60	23.60
1	REAR SPARE TYRE BOARD COVER	WARPED / DEFORMED	370.00	370.00
1	REAR SPARE TYRE TOOLS TRAY	CRACKED	310.00	310.00
2	REAR FENDER INNER TRIM	DEFORMED / TORN	760.00	760.00
12	REAR FENDER INNER TRIM CLIPS	NECESSARY	70.80	70.80
1	REAR SPARE TYRE FLOOR PANEL	BUCKLED / BADLY DENTED	900.00	900.00
1	REAR SPARE TYRE FLOOR PANEL UNDER COVER	TORN	160.00	160.00
8	REAR SPARE TYRE FLOOR PANEL UNDER COVER CLIPS	NECESSARY	63.20	63.20
1	REAR EXHAUST BOX	DENTED / BENT	550.00	550.00
1	REAR EXHAUST BOX CHROME FINISHER	BENT	175.00	175.00

Report Ref No. CS/FCI18002709/Uqd3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST BOX RUBBER HOLDER	NECESSARY	70.00	70.00
1	REAR EXHAUST BOX HEAT SHIELD	TO REPAIR SEE LABOUR	65.00	-
2	REAR FENDER PROTECTOR	DEFORMED / TORN	225.00	225.00
12	REAR FENDER PROTECTOR CLIPS	NOT NECESSARY	70.80	-
1	REAR GATE LOCK ACTUATOR (ADDITIONAL)	SHORTED	125.00	125.00
	LESS 20% DISCOUNT		-1,922.48	-1,874.32
			7,689.92	7,497.28
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			360.00	280.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE & REFIX REAR WINDSCREEN .		120.00	120.00
	TO REMOVE & REFIX CUSHION AND SEATS.)		180.00	80.00
	TO REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR .)		150.00	-
	CAVITY PROTECTION ON ALL AFFECTED AREAS.		120.00	80.00
	TO REMOVE & REFIX EXHAUST BOX .		150.00	60.00
	TO REMOVE & REFIX HYBRID .		280.00	120.00
	TO CUT ,WELD ,STRAIGHTEN & REALIGN ALL AFFECTED PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX HEAT SHIELD .		1,800.00	1,400.00
	TO SPRAY PAINT ON ALL AFFECTED AREAS.		1,600.00	1,200.00
			4,450.00	3,090.00
<b>GRAND TOTAL</b>			<b>12,499.92</b>	<b>10,867.28</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>10,867.28</b>

Report Ref No. CS/FCI18002709/Uqd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.