



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
 TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE KIM CHWEE
 BLK 192 BISHAN STREET 13
 #10-495
 SINGAPORE 570192

Estimate No: MCS1102291
 Date: 09 Feb 2018
 Policy No: 10702658
 Veh Reg No: SKW8633U
 Make/Model: HONDA MOBILIO SV
 1.5CVT

ATTN:

Your Ref No: SKW8633U
 Claim Type: Third Party
 Accident Date: 08/02/2018
 TP Veh Reg No: MID34804

*Not withstanding
 1.B.1
 Reserving 4 days*

Estimate Repair Cost to Vehicle No :SKW8633U

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BONNET	1 PC	634.80	—
2 FRONT BONNET INSULATOR CLIP	6 PC	22.80	—
3 FRONT BONNET SIDE RUBBER SEAL - LH & RH	2 PC	32.00	?
4 FRONT BONNET HINGE - LH & RH	2 PC	69.60	?
5 RADIATOR TOP PANEL	1 PC	363.10	—
6 HEADLAMP - LH & RH	2 PC	2,138.20	?
7 RADIATOR GRILLE	1 PC	196.20	—
8 RADIATOR GRILLE CHROME	1 PC	189.20	—
9 RADIATOR GRILLE TOP COVER	1 PC	67.10	—
10 RADIATOR TOP COVER CLIP	8 PC	48.00	—
11 FRONT GRILLE LOGO	1 PC	23.50	—
12 FRONT BUMPER	1 PC	459.80	?
13 FRONT BUMPER SIDE RETAINER - LH & RH	2 PC	27.00	X
14 FRONT BUMPER CLIP	15 PC	90.00	?
		4,361.30	
	Less 20%	872.26	3,489.04
LABOUR			
15 TO CHECK WIRING AND REFOCUS HEADLAMP	1 PC	30.00	201
16 TO DISMANTLE ALL DAMAGED PARTS. TO REMOVE & REFIT TOP PANEL. TO ADJUST AND ALIGN HEADLAMP & FRT BUMPER. TO KNOCK & REPAIR FRONT FENDER LH AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	500
17 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL AND EFFECTED AREAS	1 PC	1,000.00	600
		1,830.00	1,830.00



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LEE KIM CHWEE
BLK 192 BISHAN STREET 13
#10-495
SINGAPORE 570192

Estimate No: MCS1102291
Date: 09 Feb 2018
Policy No: 10702658
Veh Reg No: SKW8633U
Make/Model: HONDA MOBILIO SV
1.5CVT

ATTN:

Your Ref No: SKW8633U
Claim Type: Third Party
Accident Date: 08/02/2018
TP Veh Reg No: MID34804

Estimate Repair Cost to Vehicle No :SKW8633U

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 5,319.04
		Add GST @ 7%	372.33
		Total Amount Payable	S\$ 5,691.37

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED NINETY ONE AND CENTS THIRTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE