

ASS. REC. BY:

REF: CS/FCI/8002738/M1rd3

Special Instructions:

Surveyor:

MA

ASSIGNMENT (Office)

CWS

From (Person):

Serene Lur

of

FCI

Date/Time:

9/2/18 @ 4:31pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 8517Z

Insured:

SHA 3219S

at Workshop m/s

Chunni Motor

Tel:

65427162

of

Blk 10, AMK Ind. Prk 2A #03-19

Policy No:

Claim No:

D18001234 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/2/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

9/2/18 @ 4:35pm

Person Contacted:

Lynn

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 8517Z - CS/FCI/7019521 / Agbo

D.O.A: 6/10/17

SHA 3219S - CS/INCO9012141 / Ch

D.O.A: 28/5/2009

4/4/18

Ma confirmed LS \$13000 (Real 12,543.28, 49%)

ASSIGNMENT

From: Date: 09.03.2018

Estimated Cost:

OC / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: SHA 8817Z

at Workshop risk: Churni motor

of: AMK

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA PR Seen: Consistent? Yes or No

Est. Repair: days: Res: Yes or No

Lump Sum: %: 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Date Time Action Instruction

Vehicle: SHA 8817Z Page: NA/2015
Type: M/Cat: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: KYN 1140

Colour: Yellow A.C. Insured / Std / NI / NA

Sp Reading: 397685 T.Recd: Insured / Std / NI / NA

Eng No:

C.No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60/R16

R: we

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or: we

Front:

R.Bal: 8 mm R.Bal: 8 mm

L.Bal: 8 mm L.Bal: 8 mm

D.O.A: 08/02/2018 D.O.A: 9/2/2018

Survey held at: OS

Des. of Damages: Frt / Rear / GS / NS / UIC / Rooftop or

OS Body

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 09.03.2018

Date/Time File Pass to: ☐ Prell. ReportDate/Time File Report to: ☐ Final Report

Date/Time File Report to:

4/4- typist

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: 5☐ Inter Insp: 5☐ Tech Insp: 5☐ Final Insp: 5

Report Format: AWS

Lump Sum / IB / 13000/-

ISAB-225

70725

50

50

91

OS

5/4/18

587

MOTOR SURVEY ASSIGNMENT

Date	08-02-2018	Our Ref No. D18001234MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHA3219S	Third Party Vehicle. SHA8517Z
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE



Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234865)  PRI Documents  Close 

PRI Header Details

Claim No	D18001234MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHUNNI M [CITYCAB PTE
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE - 65421726)	Survey Location & Contact Details	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPO Mobile: 0 , Phone: 65427162 , Fax: 65426039 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: QUANTUM TO BE AGREED		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3219S	TP Vehicle No	SHA8517Z
PRI Recieved Date	08-02-2018 10:31:42 PM	Surveyor Appointed Date	09-02-2018 04:30:30 PM	Surveyor Accept Date	12-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-02-2018	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	<div>Please Select Make ▾</div>	Model	<div>Please Select Model ▾</div>	Year	<div>Select Year ▾</div>
Chasis No	<div></div>	Engine No	<div></div>	Mileage	<div></div>
Color	<div></div>	Cubic Capacity	<div></div>		

Multiple Documents Upload

Upload Multiple Documents

File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks	<div></div>	<div>Save</div>
---------	-------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002738/M1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3219S	Veh. Inspected	SHA 8517Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18001234MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/02/2018	Inspection Date	12/02/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE**

VEHICLE N: SHA 8517Z

DATE : 08.02.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCL

To Survey by mail LKK

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover		1052.20	\$ 1,052.20
	Front Bumper Bracket (RH)		24.60	\$ 24.60
	Front Bumper Retainer Mounting (RH)		9.20	\$ 9.20
	Headlamp Support Panel Assy		1067.50	\$ 1,067.50
	Headlamp (RH)		1388.00	\$ 1,388.00
	Front Fender (RH)		619.00	\$ 619.00
	Front Fender Apron Panel (RH)		1575.50	\$ 1,575.50
	Front Fender Shield (RH)		169.80	\$ 169.80
	Front Door (RH)		1403.00	\$ 1,403.00
	Front Door Rubber (RH)		290.50	\$ 290.50
	Front Door Gear / Regulator (RH)		785.50	\$ 785.50
	Front Door Hinge Upper (RH)		53.40	\$ 53.40
	Front Door Hinge Lower (RH)		53.40	\$ 53.40
	Front Door Check (RH)		110.15	\$ 110.15
	Front Door Mirror (RH)		980.50	\$ 980.50
	Front Door Power Motor (RH)		950.90	\$ 950.90
	Front Door Trim Board (RH)		1196.90	\$ 1,196.90
	Rocker Panel Outer Garnish (RH)		483.60	\$ 483.60
	Rear Door (RH)		1351.00	\$ 1,351.00
	Front Windscreen Moulding		60.00	\$ 60.00
	Front Windscreen Pillar Outer (RH)		1843.10	\$ 1,843.10
	Front Wheel Rim (RH)		351.90	\$ 351.90
	Front Wheel Hub Cap (RH)		150.70	\$ 150.70
	Front Wheel Bearing (RH)		258.50	\$ 258.50
	Front Shock Absorber (Assy) (RH)		342.20	\$ 342.20
	Front Shock Absorber Mounting (RH)		75.10	\$ 75.10
	Front Drive Shaft (RH)		1069.55	\$ 1,069.55
	Rack & Pinion Assy		2184.00	\$ 2,184.00
	STG Tie End (RH)		69.50	\$ 69.50
	Stabilizer Bar		252.30	\$ 252.30
	Stabilizer Bar Bush (RH)		16.10	\$ 16.10
	Stabilizer Bar Link (RH)		81.70	\$ 81.70
	Stabilizer Bracket (RH)		24.00	\$ 24.00
	Front Suspension Lower Arm (RH)		715.10	\$ 715.10
	Knuckle Arm (RH)		582.95	\$ 582.95
	Engine Under Cover		343.10	\$ 343.10
	Engine Crossmember		2236.90	\$ 2,236.90
	ABS Sensor (RH)		261.50	\$ 261.50
SUB TOTAL				\$ 24,482.85
LESS 20%				\$ 4,896.57
DISCOUNTED TOTAL				\$ 19,586.28

SHA 8517Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (RH)		u2	\$ 100.00	Nett
	Front Door Comfort Logo (RH)		u2	\$ 75.00	Nett
	Front Door Advertisement Logo (RH)		u2	\$ 100.00	Nett
	Rear Door Advertisement Logo (RH)		u2	\$ 100.00	Nett
	Rear Door Tel No. Sticker (RH)		u2	\$ 10.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH)		u2	\$ 80.00	Nett
	Front Windscreen Sealant		u2	\$ 46.00	Nett N/M
	Front Tyre (RH)		u2	\$ 216.00	Nett
				\$ 727.00	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1000
	Spray Painting Charge			\$ 1,500.00	1100
	Wiring Charge			\$ 50.00	30
	Tuff Kote			\$ 100.00	60
	Towing Charge			\$ 50.00	
	Transfer of Door	\$	120.00	\$ 240.00	50/120
	Remove/Refix Undercarriage (FRT)			\$ 400.00	20/250
	FRT Wheel Alignment			\$ 80.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	100X
	Remove/Refix Dashboard			\$ 450.00	280X
	Remove/Refix Front Windscreen Glass			\$ 120.00	100X
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	60
	TOTAL LABOUR			\$ 5,230.00	
	ESTIMATE TOTAL			\$ 25,543.28	
	Not Author HSC After paint Photo HSC Auto (WAS)				Booth
	2/2/2018 7w days				7w days Con

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum v be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

130507

MCD018018436 / ConfortDigiGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 08/02/2018 11:11
 SUBMITTED BY: Huang XianYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/02/2018 11:11
 Date Of Accident 08/02/2018 01:15
 Exact Location Of Accident CHANGI SOUTH AVE 3 X CHANGI SOUTH AVE 4
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA8517Z
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number
 Driver
 Name of Driver LIM HOCK SENG
 NRIC No S1206383J
 Date Of Birth 22/09/1956
 Occupation OUTDOOR
 Date Of Driving Pass 31/01/1978
 Driving Experience 40 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 411 BEDOK NORTH AVENUE 2 #12-104
 Postcode 460411
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA3219S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver KHOR POH HIENG
 NRIC/Passport Number S2010249G
 Contact Number 93659667
 Address
 Postcode
 Insurance Company Name MS FIRST CAPITAL INSURANCE LTD
 Nature Of Damage FRT LEFT
 No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 08.02.2018 @ 10:00 Hrs


Reporting Centre Personnel's Signature
Name: Rubbini
NRIC/FIN No.:



Describe Circumstances of the Accident

On the traffic junction with Changi South Ave 4.I was travelling straight and traffic light was green.I proceeded straight,upon crossing the junction, Suddenly.Veh (B) (SHA 3219S),a comfort taxi,dashed out from my right , and collided onto my right portion.

I had photos taken at scene to support my claims.

Veh (B) (SHA 3219Z). Mr. Khor Poh Hieng. NRIC : S 2010249G. Hp : 9365 9667.

No injury in this accident.

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 1995028300

[Signature]

Rubbini

policyholder's Signature
Date & Time

Driver's Signature (If driver is not the policyholder)
Date & Time 08.02.2018 @ 10:00 Hrs

Reporting Centre Personnel's Signature
Name : Rublini
NRIC/FIN No : -




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC18002738/M1rd3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3219S	Veh. Inspected	SHA 8517Z	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001234MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU080548	Colour	YELLOW	
Odometer	397685	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	8 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	8 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	8 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	09/02/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8517Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (RH)	DISTORTED	24.60	24.60
1	FRONT BUMPER RETAINER MOUNTING (RH)	DISTORTED	9.20	9.20
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	1,067.50	-
1	HEADLAMP(RH)	SERVICEABLE	1,388.00	-
1	FRONT FENDER (RH)	DENTED	619.00	619.00
1	FRONT FENDER APRON PANEL (RH)	TO REPAIR SEE LABOUR	1,575.50	-
1	FRONT FENDER SHIELD (RH)	DISTORTED	169.80	169.80
1	FRONT DOOR (RH)	DENTED	1,403.00	1,403.00
1	FRONT DOOR RUBBER (RH)	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR /REGULATOR (RH)	BENT	785.50	785.50
1	FRONT DOOR HINGE UPPER (RH)	BENT	53.40	53.40
1	FRONT DOOR HINGE LOWER (RH)	BENT	53.40	53.40
1	FRONT DOOR CHECK (RH)	SERVICEABLE	110.15	-
1	FRONT DOOR MIRROR (RH)	CRACKED	980.50	980.50
1	FRONT DOOR POWER MOTOR (RH)	JAMMED	950.90	950.90
1	FRONT DOOR TRIM BOARD (RH)	DISTORTED	1,196.90	1,196.90
1	ROCKER PANEL OUTER GARNISH (RH)	DISTORTED	483.60	483.60
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	1,351.00	-
1	FRONT WINDSCREEN MOULDING	SERVICEABLE	60.00	-
1	FRONT WINDSCREEN PILLAR OUTER (RH)	TO REPAIR SEE LABOUR	1,843.10	-
1	FRONT WHEEL RIM (RH)	BENT	351.90	351.90
1	FRONT WHEEL HUB CAP (RH)	DISTORTED	150.70	150.70
1	FRONT WHEEL BEARING (RH)	BENT	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY) (RH)	BENT	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	DISTORTED	75.10	75.10
1	FRONT DRIVE SHAFT (RH)	BENT	1,069.55	1,069.55
1	RACK & PINION ASSY	BENT	2,184.00	2,184.00
1	STG TIE END (RH)	BENT	69.50	69.50

Report Ref No. CS/FCI18002738/M1rd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR	SERVICEABLE	252.30	-
1	STABILIZER BAR BUSH (RH)	NOT NECESSARY	18.10	-
1	STABILIZER BAR LINK(RH)	BENT	81.70	81.70
1	STABILIZER BRACKET (RH)	SERVICEABLE	24.00	-
1	FRONT SUSPENSION LOWER ARM (RH)	BENT	715.10	715.10
1	KNUCKLE ARM (RH)	BENT	582.95	582.95
1	ENGINE UNDER COVER	DISTORTED	343.10	343.10
1	ENGINE CROSSMEMBER	BENT	2,236.90	2,236.90
1	ABS SENSOR (RH)	SHORTED	261.50	261.50
	LESS 20% DISCOUNT		-4,896.57	-3,359.04
			19,586.28	13,436.16
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR TEL NO. STICKER (RH) (SN)	NECESSARY	10.00	10.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	FRONT TYRE (RH) (SN)	SERVICEABLE	216.00	-
			727.00	465.00
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT FENDER APRON PANEL (RH),REAR DOOR (RH) AND FRONT WINDSCREEN PILLAR OUTER (RH).		2,000.00	1,000.00
	SPRAY PAINTING CHARGE.		1,500.00	1,100.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	60.00
	TOWING CHARGE.		50.00	50.00
	TRANSFER OF DOOR .		240.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	180.00
	FRT WHEEL ALIGNMENT.		80.00	80.00

Report Ref No. CS/FCI18002738/M1rd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX DASHBOARD .	NOT NECESSARY	450.00	-
	REMOVE/REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.		90.00	60.00
			5,230.00	2,620.00
GRAND TOTAL			25,543.28	16,521.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/FCI18002738/M1rd3q2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.