22/03/2002 - ASS, REC, BY:	REF: CS3/EGI (8002752) 71d3 Special lettrustion:
Surveyor:	Taunich ASSIGNMENT (Office)
From (Person):	Yu Pei H of EGI Date/Time 1/3/1808 49am
Estimated Cost:	Bill to:
	tp RES / OD RES / EVA / INV / MV / CS cle No. GBE GO 31 X Insured GBA 6465Z
at Workshop m/	Willy Motor Tel: 92767180/62617873/62680977
of2	7A juning Port Road #01-32
Policy No:	Claim No: DS MCV1800318
Sum Insured:	Excess;
Make of Veh:_ (Client's Record)	D.O.A. 06/02/2018
CA / REV /	REP. / REV 24 HRS (Wp) H.O.D. Endorsement: Sound 3 18 Person Contacted: Ms·Khoo. Vehicle (IN) OUT
Date/Time: 4	66m0 3 18 Person Contacted: Ms·Khoo Vehicle (N) OUT
Date/Time	Action/Instruction (X) Estimate
	\$4000- \$5000 6 days.
	0
1/3/2018	dismonth
5/3/18	After report

\$4000-\$5000 16 days

Action / Instruction

Constinue File Pass to 7	: Prell. Report	Days (Of Repair:		
TopicTime, File Rebusin	: Final Report	Resurvey No. of Trip:		Survey Fee Insepression	
Constitute on Kentham		Add Fee:	(Site Insp. 15	J. SHE 9	
Report Formal	3		Inter = 5 +5		
Lump Sum / LB					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

966		Affiliated to Federation In	ternationale Des Experts En Autor	nobile		
ERG	GO INSURANCE P	TE LTD	Ref : CS3/EGI18002752/T1d3			
#04	EMASEK BOULEV -01 SUNTEC TOW GAPORE 038985		Date: 12-02-2018 Code: EGI			
1.		Policy Partic	ulars :- (THIRD PARTY CLA	IM)		
	Insured Veh.	GBA 6465Z	Veh. Inspected	GBE 6031X		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	DSMCV1800318	Excess (\$)	0.00		
	Assign From	YEE PEI LI	Assign Date	12/02/2018		
2.		Vehicle	Particulars & Condition			
	Make & Model		c.c 0			
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	•	Steering			
	Brakes		Modification			
	General					
3.	a tradition and	C	onditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Des	scription of Damages	WELL WEIGHT		
-						
5.	A saldant Day		eneral Information	ADDONAL S		
	Accident Date	06/02/2018	Inspection Date	13/02/2018		
	Survey neid at	27A JURONG PORT ROAD #01-32 SINGAPORE 619101				
5a.	2111		Remarks	ET SECTION OF THE PARTY.		
			A"WITHOUT PREJUDICE" BAS ONS, WE HAVE NOT AUTHORIS			

Nivitha (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Thursday, 1 March 2018 8:49 AM

To:

'Denise Tay (LKKAuto)'; Admin-D (LKKAuto); assignments

Cc:

SUR

Subject:

Attachments:

RE: GBA6465Z / TP : GBE6031X/LKK / DOA : 06/02/2018 (DSMCV1800318)
RE: Accident case between GBE6031X (AXA) and GBA6465Z (ERGO INS) at DE...

(20 5 (40) 6

(29.5 KB); GBE6031X - PRI NOTICE.pdf

Dear LKK.

Kindly note there's a change of workshop from GOLDBELL ENGINEERING PTE LTD to WILLY MOTOR COMPANY

We have rejected to their PRS list. please assist to conduct this survey C YOGARAJAH LLC.,

ADDRESS

: WILLY MOTOR COMPANY

27A JURONG PORT ROAD

#01-32

SINGAPORE 619101

PERSON TO CONTACT

: MISS KHOO @ 9276 7180 / 6261 7873 / 6268 0977

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Rgds Pei Li

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Wednesday, 14 February, 2018 5:47 PM

To: Admin-D (LKKAuto); Survey Report (ERGO Insurance Pte. Ltd.); assignments

Cc: SUR

Subject: RE: GBA6465Z / TP: GBE6031X/LKK / DOA: 06/02/2018

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBE 6031X

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 12 February 2018 10:45 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments

<assignments@lkkauto.com> Cc: SUR <sur@lkkauto.com>

Subject: RE: GBA6465Z / TP: GBE6031X/LKK / DOA: 06/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Monday, 12 February 2018 9:12 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Subject: OI: GBA6465Z / TP: GBE6031X/LKK / DOA: 06/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from GOLDBELL ENGINEERING PTE LTD (PANDAN).

ADDRESS

: BLK K PANDAN LOOP INDUSTRIAL ESTATE

#01-12

SINGAPORE 128230

PERSON TO CONTACT

: ANDY OOI @ 6458 9596 / 8816 2798

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor) ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



883 North Bridge Road #19-05 Southbank Singapore 198785 T: 8292 5838 F: 6292 5938

(UEN No. 201333127N) (GST Reg No; 201333127N)

Our Ref

CY(WMC)SBD8332U(PF)hh

Your Ref

DSMCV1800318

27 February 2018

Motor Claims Department ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

BY FAX (6829 9247) ONLY

Dear Sira

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION ACCIDENT INVOLVING GBE6031X & GBA6465Z ON 06.02.2018 @ 17:00 HRS ALONG DENHAM CLOSE

We refer to your fax of 27th February 2018.

The owner of vehicle GBE6031X has informed the authorized workshop for cancelling the third party claim. Please call your authorized workshop to confirm.

Kindly confirm that whether you wish to proceed to send your appointed surveyor for PRS/PRI again at Willy Motor Company.

Our client's is proposing motor surveyor, M/s. Precision Appraisal Services to conduct the Pre-Repair Inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop

M/s. Willy Motor Company

Address

27A Jurong Port Road #01-32

Singapore 619101

Contact person

Miss Khoo (92767180)

Telephone no

62617873 / 62680977

Fax no

6265 1726

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deamed to have agreed as a "single joint expert'.

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully.

C. Yogarajah LLC c.c. client

For Surveyor

Please initial here after completion of pre-repair inspection. Thank you.

Name: Signature:

M/s. Teo Landscape And Maintenance

Confidentiality & Privilege: This message is intended for the recipient to who the intended recipient, please notify the sender immediately by replying to this message and then deliber in rom your system. Do not read, copy, use or circuists this communication. Disclaimer: Mell/Faw/Internet communication has been securely transmitted and not been tempered with. C. Yogarajah LLC cannot be responsible for alternations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication or should you require any other form of confirmation of the contents of this message. Please contact the secret. Coinions, conclusions and other information in this message that do not rolete to the official business of the firm shall be message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors, Thank you



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/EGI18002752/T1d3s2 ERGO INSURANCE PTE LTD 27-06-2018 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: FIVESINGAPORE 038985 Code: EGI Policy Particulars :- (THIRD PARTY CLAIM) 1. **GBE 6031X** GBA 6465Z Veh. Inspected Insured Veh. 0.00 Coverage (\$) Policy No. Excess (\$) 0.00 DSMCV1800318 Claim No. Assign From YEE PEI LI Assign Date 01/03/2018 2. Vehicle Particulars & Condition 2982 TOYOTA DYNA Make & Model C.C HIDDEN Engine No. Year of Reg. Chassis No. JTFAT35Y50K205661 Colour SILVER IN ORDER 55167 KM Odometer Steering IN ORDER Modification NIL Brakes General GOOD **Conditions of Tyres** 3. Size Make Balance 195/80R16 YOKOHAMA 5 mm R/H Front Tyre YOKOHAMA 5 mm 195/80R16 L/H Front Tyre 155/60R13 (D) YOKOHAMA 5/5 mm R/H Rear Tyre 155/60R13 (D) YOKOHAMA 5/5 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. 5. General Information 06/02/2018 Inspect Date / Time 13/02/2018 (03:32 PM) **Accident Date** Survey held at WILLY MOTOR COMPANY 27A JURONG PORT ROAD #01-32 SINGAPORE 619101 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000- \$5,000 5b. Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

Report Ref No. CS3/EGI18002752/T1d3s2

Inspected By

brushing

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A Automotive Assessor L

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No hability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.