From (Person): Seren	e ter of _	FC1	Date/Time: 09/2/18
Estimated Cost		Bill to:	
To Inspect Vehicle No:	SHC 6	666D	Insured: SHD 3279 (
at Workshop m/s	Premier A	utumotive	Tel: 62/48880
of 23 char	rgi south Ave	2 # 03-02	
	U88936 N45H	Claim No:	D18001233MFSH
Sum Insured:		Excess:	
Make of Veh:			D.O.A 08 02 20
(Client's Record)	1.2		00100 100
CA / REV / REP. / R	EV 24 HRS WP	0	H.O.D. Endorsement:
Date/Time: 9.30cm	DI2 2 18 Person Con	itacted: Cary	Vehicle (N) UT
	struction () Es-		
SHCC	6660-x	MINERE	
		1	1162
12/1/18@ 2.60	B279c - CC3/1	1XA 11018341/H	19103/c2 D.O.A:
71-100 3 2012	V # VISE4 10)	evere we by	enol.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En Autom	nobile
FIR	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180027	53/K1qd3
	ROBINSON ROAD -01 CITY HOUSES	INGAPORE 068877	Date: 12-02-2018 Code: FCI2	
1.		Policy Particu	lars :- THIRD PARTY CLAI	M
	Insured Veh.	SHD 3279C	Veh. Inspected	SHC 6666D
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18001233MFSH	Excess (\$)	0.00
	Assign From	CWS (SERENE LER)	Assign Date	12/02/2018
2.		Vehicle F	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer		Steering	
	Brakes		Modification	
	General	•		
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damages	
5.		Co	neral Information	
J.	Accident Date	08/02/2018		12/02/2018
		PREMIER AUTOMOTIVE S	Inspection Date	12/02/2010
	Survey neid at		UE 2 #01-02 SINGAPORE 486	3443
5a.		20 OTINIOI GOOTH AVEN	Remarks	
Ju.		ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BAS	



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18001233MFSH

Date: 13 February 2018

Our Ref: CS/FCI18002753/K1qd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6666D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/02/2018 at the premises of M/s PREMIER AUTOMOTIVE. and have the following to report:-

Workshop Estimate Amount	: S\$	3,798.30	
Revised Estimate Amount	: <u>S\$</u>	2,188.50	
"Check" Items Amount	: <u>S\$</u>		- 14
Market Value	: <u>S\$</u>	82	
LTA Reimbursement Value	: <u>S</u> \$		
Nett Value	: <u>S\$</u>	(1-)	

Description of Damage:

<u>The vehicle sustained damages</u>
at the n/s body.



Yours faithfully


Kalvin Ang Automotive Assessor Reference No.: Cy Foll 800773 Mad 3
Policy Type: OD //TP / TP RES / TL / EVA Case Handler Withe): Case handler to make sure all Information created by the assignment team are ACCURATE. Admin (Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C C Customer Code N Assign From C Assign Date Veh No (Inspected) C Veh No (Insured) C C D.O.A Policy No. C Claim No C Insurance Authorisation (CA /REV/REP) C C Report Type C Weekend Charges Survey held at/Repairer Excess C): Case handler to make sure the surveryor completed all required information. Surveyor (CA VIA (1) Assignment Form Vehicle No C Regn Month/Year N . Vehicle Type Make & Model Engine Capacity. (C.C) C N Colour Odometer. (Sp.Reading) C C Chassis No General Condition N Steering N Brake Modification (Modi) C Tyre Size Tyre Make N C Tyre Balance Date of Inspection C Survey held Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair C Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded Check By:

Date

Survey Department Check List (Case Handler)

SHC 66660

Case Handler



MS First Capital Insurance Limited Co.Reg No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 069977 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

08-02-2018

Our Ref No. D18001233MFSH

Accident Date

08-02-2018

Claim Type. Third Party

Insured Vehicle

SHD3279C

Third Party Vehicle. SHC6666D

Survey Location

23 CHANGI SOUTH AVENUE 2 #03-02

Contact Person.

GARY SHI

Contact No.

62148880/65446671

Fax No. 62141511

Survey Type

WITHOUT PREJUDICE: NO EST. PROVIDED (WE ADMIT LIABILITY

QUANTUM TO BE AGREED)

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PREMIER AUTOMOTIVE

SERVICES PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

			PRI Header Details		
	Ÿ	ĭ	PRI Header Details	ř	ı
Claim No	D18001233MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446671 , Phone: 62148880 , Fax: 621415 EmailId: GARY.SHI@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO AGREED)	EST. PROVIDE	D (WE ADMIT
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3279C	TP Vehicle No	SHC6666D
PRI Recieved Date	08-02-2018 10:26:11 PM	Surveyor Appointed Date	09-02-2018 04:09:25 PM	Surveyor Accept Date	12-02-2018
		1	Survey Report Upload		
Surveyor Inspection Date *:		Surveyor Report Date	12-02-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple D	ocuments Upload				
		Upload Multiple	e Documents		
File Nan	ne			Action	
Surveyor	Job Remarks				

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 13 February 2018 3:50 PM

To:

'Claim Workflow System'; assignments

Cc:

SERENELER@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18001233MFSH/1

Attachments:

CSFCI18002753K1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHC 6666D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 12 February 2018 1:04 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001233MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Friday, 9 February 2018 4:10 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001233MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

12 Jan 2015 / 09:05:45

Receipt No.:

AACCK001-AX239-150112-000004

Asset Type:

Vehicle

Transaction Amount:

\$65,919.00

Asset ID:

SHC6666D

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction Reference No.:

01.02 Register New Vehicle (AA)

20150112090545176633

Vehicle No.:

SHC6666D

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: Original Registration

12 Jan 2015

Date:

12 Jan 2015 KIA

Vehicle Make: Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5574977

Engine No.:

D4FDEH313254

Motor No.:

Trailer Chassis No.:

Propellant:

Diesel

Passenger Capacity:

4

Engine Capacity:

Power Rating: Unladen Weight:

1584

1685

Maximum Laden

2050

Weight:

Primary Color:

Silver

Secondary Color: Manufacturing Year:

2014

Open Market Value:

\$20,566.00

Minimum PARF Benefit: \$7,975.00

PARF Eligibility:

No. of Transfer.

Effective Ownership

Date/Time:

12 Jan 2015 09:05:45

COE No .:

2015011201001433N

COE Expiry Date:

COE Bid Category:

Actual QP/PQP Paid Amount:

\$52,486.00

11 Jan 2023

Lifespan Expiry Date:

11 Jan 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

8-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6666 D

	- 11		
1 pc	Rear n/s door	\$	765.00
1 pc	Rear n/s door hinge upper	\$	33.00
1 pc	Rear n/s door hinge lower × 100	\$	33.00
1 pc	Rear n/s fender inner shield 🗡	\$	120.00
1 pc	Rear n/s wheel cover + J	\$	116.00
		\$	1,067.00
	Less 10%	\$	106.70
		\$	960.30
S/NETT			
1 set	n/s door sticker	\$	100.00
1 set	Rear n/s fender inner shield clips × **	\$	38.00
1 pc	Rear n/s fender sticker — we Kahia / Clc/e	\$	60.00
1 pc	Rear bumper top protector × no / p/z/s og 36/5-	\$	80.00
	Sundry 3 Pags	\$	50.00 ≥0 Nec
	To check wheel alignment Affe Ryon plat	. \$	160.00 / 11
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	120.00 50
	To dismantle / refit the rear o/s door inner component into new shell door	\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, rear n/s fender, n/s rocker panel garnish, etc	\$	850.00
	To putty and spray painting on front n/s door, rear n/s door,		770
	n/s rocker panel garnish, rear n/s fender, rear bumper LKK Auto Consultants hence notify		1,000.00
	To apply rustproofing on the repaired and replaced panels. Lowing: To display damaged parties during resurvey Parts prices are subject to resulting	\$	3,798.30
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST) Without Prejudice basis		
	THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE Insurance Company ANY UNFORESEEN DAMAGES. Acknowledged by Repairer Signature: Date:		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

FORE		Affiliated to Federation Intern	ationale Des Experts En Autom	nobile
IRS	CAPITAL INSUF	RANCE LTD	Ref : CS/FCI1800275	53/K1qd3n2
	DBINSON ROAD 1 CITY HOUSES	INGAPORE 068877	Date: 05-03-2018 Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLAI	M
	Insured Veh.	SHD 3279C	Veh. Inspected	SHC 6666D
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D18001233MFSH	Excess (\$)	0.00
	Assign From	SERENE	Assign Date	09/02/2018
	CONTRACTOR OF THE PARTY OF THE	Vehicle Pa	articulars & Condition	
	Make & Model	KIA OPTIMA	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KNAGM414MF5574977	Colour	SILVER
	Odometer	276547	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	ACHILLES	7 mm
	L/H Front Tyre	205/65 R16	ACHILLES	7 mm
	R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
	L/H Rear Tyre	205/65 R16	ACHILLES	7 mm
4.		Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S BODY.	
5.	DAWAGES SEE B		eral Information	
	Accident Date	08/02/2018	Inspection Date	12/02/2018
	Survey held at			
	-		JE 2 #01-02 SINGAPORE 48	6443
5a.			Remarks	
	BITHE INSPECTI	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
5b.			nate Days of Repair	
	ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	3 Working Da	iys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6666D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR N/S DOOR	DENTED	765.00	765.00
1	REAR N/S DOOR HINGE UPPER	SERVICEABLE	33.00	-
1	REAR N/S DOOR HINGE LOWER	SERVICEABLE	33.00	124
1	REAR N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR N/S WHEEL COVER	SERVICEABLE	116.00	-
	LESS 10% DISCOUNT		-106.70	-76.50
			960.30	688.50
	SPECIAL NETT ITEMS			
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SET REAR N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER TOP PROTECTOR (SN)	NOT NECESSARY	80.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			328.00	180.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	160.00	
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		120.00	50.00
	TO DISMANTLE/REFIT THE REAR O/S DOOR INNER COMPONENT INTO NEW SHELL DOOR.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT N/S DOOR, REAR N/S FENDER, N/S ROCKER PANEL GARNISH, ETC.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT N/S DOOR,REAR N/S DOOR,N.S ROCKER PANEL GARNISH,REAR N/S FENDER,REAR BUMPER.		1,000.00	770.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
	TEL EAGED PAREES.		2,510.00	1,320.00
	GRAND TOTAL		3,798.30	2,188.50

Report Ref No. CS/FCI18002753/K1qd3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	Barrie Single	1,750.00
(TO ITS PRE-ACCIDENT CONDITION)	· 网络国人社会 图 图	

Report Ref No. CS/FCI18002753/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.