

22/03/2018

ASS. REC. BY:

REF: CS/FCI18002758/Grd3^{N2}

Special Instruction:

Surveyor:

CWS GQ ASSIGNMENT (Office)

From (Person): Laurence Jaw of FCI

Date/Time: 9/2/18 @ 6.40pm

Estimated Cost: Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 4374C Insured: SHC 7508X

at Workshop m/s Trans Eurokars Tel: 9127 7928

of Subiclose

Policy No: Claim No: D18001145MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 06/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'ds' 13/02/2018 @ 11.45am owner waiting

H.O.D. Endorsement:

Date/Time: 9.09am @ 12/2/18 Person Contacted: Ronald Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 4374C - X
	SHC 7508X - CS/FCI15001289/MHbk3 D.O.A. 21/01/15
22/8/18	confirm \$3110.48, 3 days (Red: \$3379.67, 52%)

Signature

Xhr.

REF: Fci

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s: Trans Turkatz
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SL54374C Yr Regn: 25 Sep 2017
Type: 3 M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mazda 3 c.c. 1496
Colour: Gray A/C: Insured / Std / NI / NA
Sp. Reading: 5267 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JM6BN22A8J0177010
Gen. Cond: 3 Good / Fair / Poor / Burnt
Steering: 3 In order / Jammed / Leaked / Burnt or
Brake: 3 In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60 R16
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
3 TOYO / YOKO or
Front Rear
R/Bal. 8 mm R/Bal. 8 mm
L/Bal. 8 mm L/Bal. 8 mm
D.O.A. _____ D.O.I. 13-02-18
Survey held at w/s 12 pm
Des. of Damages: Frt / 3 Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 AUG 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

) \$ + RS. \$ _____

) Photos _____

) Others _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : TP

Lump Sum / I.B.I. (\$ 3110.48)

TOTAL

145
50
50
13
258



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002758/Grd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7508X	Veh. Inspected	SLS 4374C
Policy No.		Coverage (\$)	0.00
Claim No.	D18001145MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/02/2018	Inspection Date
Survey held at	TRANS EUOKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001145MFSH

Our Ref: CS/FCI18002758/Grd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 4374C .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.02.2018 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,490.15</u> .
Revised Estimate Amount	: S\$ <u>3,110.48</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
XING GUO QIANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-02-2018	Our Ref No. D18001145MFSH
Accident Date	06-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7508X	Third Party Vehicle. SLS4374C
Survey Location	5 UBI CLOSE	
Contact Person.	ERIC PAU	
Contact No.	63958685/ 96185991	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234765)



PRI Documents



Close



PRI Header Details

Claim No	D18001145MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUOKARS PTE LTD (Contact Person : ERIC PAU)	Survey Location & Contact Details	5 UBI CLOSE Mobile: 96185991 , Phone: 63958685 , Fax: 0 EmailId: ERIC.PAU@EUOKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7508X	TP Vehicle No	SLS4374C
PRI Recieved Date	09-02-2018 02:34:49 PM	Surveyor Appointed Date	09-02-2018 06:39:40 PM	Surveyor Accept Date	12-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, August 23, 2018 2:40 PM
To: 'catherinechua@eurokars.com.sg'; Guo Qiang (LKKAUTO)
Cc: ronald.yap@eurokars.com.sg
Subject: RE: SLS4374C - FINALIZATION OF COR

Dear Catherine,

Confirm \$3110.48 @ 3 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Saturday, August 18, 2018 12:21 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: ronald.yap@eurokars.com.sg
Subject: RE: SLS4374C - FINALIZATION OF COR

Thanks Janice

Please note that we need to invoice by 24 August 2018 with/without your confirmation.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Thursday, August 16, 2018 12:02 PM
To: Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: Ronald Yap <ronald.yap@eurokars.com.sg>
Subject: RE: SLS4374C - FINALIZATION OF COR

Hi Catherine,

Enquire Transfer Fee

Vehicle Details		
Vehicle No. :	SLS4374C	
Vehicle Type :	P10 - Passenger Motor Car	
Vehicle Attachment 1 :	With Sun Roof	
Vehicle Scheme :	Revised Off-Peak Car	
Vehicle Make :	MAZDA	
Vehicle Model :	MAZDA3 SEDAN 1.5 AT EU6	
Chassis No. :	JM6BN22A8J0177010	
Propellant :	Petrol	
Engine No. :	P520466778	
Engine Capacity :	1496 cc	
Maximum Power Output :	88.0 kW (118 bhp)	
Maximum Laden Weight :	1835 kg	
Unladen Weight :	1310 kg	
Year Of Manufacture :	2017	
Original Registration Date :	25 Sep 2017	
Lifespan Expiry Date :	-	
COE Category :	A - Car up to 1600cc & 97kW (130bhp)	
Quota Premium :	\$36,001.00	
COE Expiry Date :	24 Sep 2027	
Road Tax Expiry Date :	24 Sep 2018	
PARF Eligibility Expiry Date :	24 Sep 2027	
Inspection Due Date :	24 Sep 2020	
Intended Transfer Date :	13 Feb 2018	
CO2 Emission :	128.00 (g/km)	
CEV/VES Rebate Utilised Amount :	\$5,000.00	
CO Emission :	-	
HC Emission :	-	
NOx Emission :	-	
PM Emission :	-	
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.		
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.		
Amount Payable		
Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Tay Teng Hwee ADDRESS : 1 Sembawang Crescent #09-01 Singapore 757093 TEL : 98272809		WIP : 61942 EXCESS : DATE: 8-Feb-18	
VEH NO :	SLS4374C	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6BN22A8J0177010	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	25-Sep-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	REAR BUMPER / <i>re</i>	1	MBHN1-50-221ABB	1074.80	\$ 1,074.80
2	RETAINER(LHS), REAR BUMPER / <i>LMC</i>	1	MBHN1-50-2J1A	36.10	\$ 36.10
3	RETAINER(RHS), REAR BUMPER / <i>LMC</i>	1	MBHN1-50-2H1A	36.10	\$ 36.10
4	BRACKET(LHS), REAR BUMPER X <i>NA</i>	1	MBHN9-51-077B		\$ 45.60
5	BRACKET(RHS), REAR BUMPER X <i>NA</i>	1	MBHN9-51-067B		\$ 45.60
6	BRACKET CENTER, REAR BUMPER X <i>NN</i>	1	MKD53-50-251		\$ 5.10
7	REFLECTOR LHS X	1	MD350-51-5L0E	X	\$ 50.40
8	REFLECTOR RHS X	1	MD350-51-5M0E		\$ 50.40
9	COVER(LHS), TOWING X	1	MBHN1-50-EL1 BB		\$ 15.70
10	COVER(RHS), TOWING X	1	MBHN1-50-EK1 BB		\$ 16.20
11	REINFORCEMENT REAR X <i>NN</i>	1	MB45A-50-260		\$ 537.30
12	FASTENER, REAR BUMPER /	4	MB45A-56-146A	11.20	\$ 11.20
13	RIVET, REAR BUMPER /	4	MBBM4-50-355	16.80	\$ 16.80
14	GROMMET, REAR BUMPER / <i>MLC</i>	1	M9991-00-501	2.80	\$ 2.80
15	GROMMET, REAR BUMPER /	4	MBHN1-50-0Z1A	10.00	\$ 10.00
16	GASKET(LHS), TAILLAMP /	1	MBHN1-51-163	20.90	\$ 20.90
17	GASKET(RHS), TAILLAMP /	1	MBHN1-51-153	20.90	\$ 20.90
18	FASTENER, TAILLAMP /	2	MKD53-51-146B	7.80	\$ 7.80
19	GROMMET, TAILLAMP /	2	MGJ6A-51-14Y	29.80	\$ 29.80
TOTAL PARTS					\$ 2,033.50
LESS 10%					\$ 203.35
TOTAL PARTS COST					\$ 1,830.15
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			660 / \$ 1,800.00

2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,500.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 4,660.00
TOTAL PARTS	\$ -	\$ 1,830.15
TOTAL	\$ -	\$ 6,490.15
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

3 Days.
before paint photos.
Gino Qiao
13/2/18.

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Mr Tay Teng Hwee	WIP : 61942
36 ROBINSON ROAD		ADDRESS : 1 Sembawang Crescent	EXCESS :
#16-01 CITY HOUSE		#09-01	DATE: 8-Feb-18
SINGAPORE 068877		Singapore 757093	
ATTN. :	MOTOR CLAIMS	TEL : 98272809	
FAX :			
VEH NO :	SLS4374C	DATE IN :	CONTACT PERSON : RONALD 6395 7875
CHASSIS NO :	JM6BN22A8J0177010	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.: 25-Sep-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MBHN1-50-221ABB	\$ 1,074.80	\$ 1,074.80
2	1	MBHN1-50-2J1A	\$ 36.10	\$ 36.10
3	1	MBHN1-50-2H1A	\$ 36.10	\$ 36.10
4	1	MBHN9-51-077B		\$ 45.60
5	1	MBHN9-51-067B		\$ 45.60
6	1	MKD53-50-251		\$ 5.10
7	1	MD350-51-5L0E		\$ 50.40
8	1	MD350-51-5M0E		\$ 50.40
9	1	MBHN1-50-EL1 BB		\$ 15.70
10	1	MBHN1-50-EK1 BB		\$ 16.20
11	1	MB45A-50-260		\$ 537.30
12	4	MB45A-56-146A	\$ 11.20	\$ 11.20
13	4	MBBM4-50-355	\$ 16.80	\$ 16.80
14	1	M9991-00-501	\$ 2.80	\$ 2.80
15	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
16	1	MBHN1-51-163	\$ 20.90	\$ 20.90
17	1	MBHN1-51-153	\$ 20.90	\$ 20.90
18	2	MKD53-51-146B	\$ 7.80	\$ 7.80
19	2	MGJ6A-51-14Y	\$ 29.80	\$ 29.80
TOTAL PARTS			\$ 1,267.20	\$ 2,033.50
LESS 10%			\$ 126.72	\$ 203.35
TOTAL PARTS COST			\$ 1,140.48	\$ 1,830.15

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 630.00	\$ 1,500.00

3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,970.00	\$ 4,660.00
TOTAL PARTS			\$ 1,140.48	\$ 1,830.15
TOTAL			\$ 3,110.48	\$ 6,490.15
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,110.48	
GST 7%			\$ 217.73	\$ -
GRAND TOTAL			\$ 3,328.21	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002758/Grd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7508X	Veh. Inspected	SLS 4374C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001145MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8J0177010	Colour	GREY	
Odometer	5207	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	8 mm	
L/H Front Tyre	205/60 R16	TOYO	8 mm	
R/H Rear Tyre	205/60 R16	TOYO	8 mm	
L/H Rear Tyre	205/60 R16	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2018	Inspection Date	13/02/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 4374C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
1	RETAINER (LHS),REAR BUMPER	NECESSARY	36.10	36.10
1	RETAINER (RHS),REAR BUMPER	NECESSARY	36.10	36.10
1	BRACKET (LHS),REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET (RHS),REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET CENTER,REAR BUMPER	NOT NECESSARY	5.10	-
1	REFLECTOR LHS	NOT NECESSARY	50.40	-
1	REFLECTOR RHS	NOT NECESSARY	50.40	-
1	COVER (LHS),TOWING	NOT NECESSARY	15.70	-
1	COVER (RHS),TOWING	NOT NECESSARY	16.20	-
1	REINFORCEMENT REAR	NOT NECESSARY	537.30	-
4	FASTENER,REAR BUMPER	NECESSARY	11.20	11.20
4	RIVET,REAR BUMPER	NECESSARY	16.80	16.80
1	GROMMET,REAR BUMPER	NECESSARY	2.80	2.80
4	GROMMET,REAR BUMPER	NECESSARY	10.00	10.00
1	GASKET (LHS),TAILLAMP	NECESSARY	20.90	20.90
1	GASKET (RHS),TAILLAMP	NECESSARY	20.90	20.90
2	FASTENER,TAILLAMP	NECESSARY	7.80	7.80
2	GROMMET,TAILLAMP	NECESSARY	29.80	29.80
	LESS 10% DISCOUNT		-203.35	-126.72
			1,830.15	1,140.48
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
<u>LABOUR</u>				
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,800.00	660.00
	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		1,500.00	630.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00

Report Ref No. CS/FCI18002758/Grd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,560.00	1,950.00
GRAND TOTAL			6,490.15	3,110.48
RECOMMENDED COST OF REPAIRS				3,110.48

Report Ref No. CS/FC118002758/Grd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.