

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1802-013
DATE : 10-Feb-2018
POLICY NO. : DIRECTASIA MT/00386324
VEHICLE REG. NO. : SLD6996Z
VEHICLE MAKE : HONDA VEZEL 1.5X (A)

TO Motor Claim Department
EQ Insurance Company Limited
22 Gemmill Lane, Singapore 069257
Tel: 6223 9433
Fax: 6224 3903

FOR SURVEYOR



ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper Center	1	\$ 880.00	\$ PA 880.00
2	Rear Bumper Reflector LH	1	\$ 150.00	\$ 2X 150.00
3	Rear Bumper Upper LH	1	\$ 200.00	\$ PA 200.00
4	Rear Bumper Clip	10	\$ 3.00	\$ PA 30.00
5	Rear Bumper Retainer RH	1	\$ 30.00	\$ PA 30.00
6	Rear Bumper Retainer LH	1	\$ 30.00	\$ PA 30.00
7	Rear Fender Shield LH	1	\$ 150.00	\$ X 150.00
8	Rear Fender Mudguard LH	1	\$ 30.00	\$ X 30.00
9	Rear Fender Guard Garnish (Wheel Arch) LH	1	\$ 150.00	\$ cut 150.00
10	Rear Undercover	1	\$ 220.00	\$ OE 220.00
11	Rear Tail Lamp LH	1	\$ 420.00	\$ X 420.00
12	Rear Tailgate Lamp LH	1	\$ 280.00	\$ scd 280.00
13	Rear Tailgate Door	1	\$ 980.00	\$ PA 980.00
14	Rear Tailgate Door Lock	1	\$ 180.00	\$ PA 180.00
15	Rear Tailgate Door Lock Latch	1	\$ 30.00	\$ X 30.00
16	Rear Tailgate Door Rubber Seal	1	\$ 100.00	\$ PA 100.00
17	Rear Tailgate Door Inner Trim	1	\$ 250.00	\$? 250.00
18	Rear Buzzer	1	\$ 100.00	\$ cut 100.00
19	Rear Antenna	1	\$ 90.00	\$ X 90.00
20	Rear / End Panel Garnish	1	\$ 100.00	\$ OE 100.00
21	End Panel	1	\$ 420.00	\$ PA 420.00
22	Rear Spare Tire Sink Panel	1	\$ 1,130.00	\$ PA 1,130.00
23	Rear Spare Tyre Board	1	\$ 280.00	\$ X 280.00
24	Rear Tool Sponge	1	\$ 280.00	\$ CA 280.00
25	Rear Windscreen Molding	1	\$ 80.00	\$ PA 80.00
26	Rear Exhaust	1	\$ 550.00	\$ X 550.00
27	Rear Exhaust Rubber Mount	2	\$ 30.00	\$ X 60.00
Total Spare Parts				\$ 7,200.00
SPECIAL NETT				
28	Rear License Plate with Frame	1	\$ 40.00	\$ X 40.00
29	Reverse Sensor	1	\$ 200.00	\$ PA 200.00
Total Special Nett				\$ 240.00

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1802-013
DATE : 10-Feb-2018
POLICY NO. : DIRECTASIA MT/00386324
VEHICLE REG. NO. : SLD6996Z
VEHICLE MAKE : HONDA VEZEL 1.5X (A)

TO Motor Claim Department
EQ Insurance Company Limited
22 Gemmill Lane, Singapore 069257
Tel: 6223 9433
Fax: 6224 3903

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	LABOUR			
30	Spray Painting Whole Rear	1	\$ 1,000.00	\$ 600 1,000.00
31	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,200.00	\$ 900 1,200.00
32	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 60 80.00
32	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ X 80.00
33	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 60 80.00
34	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
34	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 80 100.00
35	Check and rectify electrical wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 2,680.00
Amount Before Excess				\$ 10,120.00
Add GST @ 7%				708.40
Total Amount Payable				\$ 10,828.40

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Rasue
Ap 90010068
8 days
48
12/09/18 @ 1250
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-inspected and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: