

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1802-013

DATE : 10-Feb-2018

POLICY NO. : DIRECTASIA MT/00386324

VEHICLE REG. NO. : **SLD6996Z**

VEHICLE MAKE : HONDA VEZEL 1.5X (A)

TO Motor Claim Department
EQ Insurance Company Limited
 22 Gemmill Lane, Singapore 069257
 Tel: 6223 9433
 Fax: 6224 3903

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper Center	1	\$ 880.00	\$ 880.00
2	Rear Bumper Reflector LH	1	\$ 150.00	\$ 150.00
3	Rear Bumper Upper LH	1	\$ 200.00	\$ 200.00
4	Rear Bumper Clip	10	\$ 3.00	\$ 30.00
5	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
6	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
7	Rear Fender Shield LH	1	\$ 150.00	\$ 150.00
8	Rear Fender Mudguard LH	1	\$ 30.00	\$ 30.00
9	Rear Fender Guard Garnish (Wheel Arch) LH	1	\$ 150.00	\$ 150.00
10	Rear Undercover	1	\$ 220.00	\$ 220.00
11	Rear Tail Lamp LH	1	\$ 420.00	\$ 420.00
12	Rear Tailgate Lamp LH	1	\$ 280.00	\$ 280.00
13	Rear Tailgate Door	1	\$ 980.00	\$ 980.00
14	Rear Tailgate Door Lock	1	\$ 180.00	\$ 180.00
15	Rear Tailgate Door Lock Latch	1	\$ 30.00	\$ 30.00
16	Rear Tailgate Door Rubber Seal	1	\$ 100.00	\$ 100.00
17	Rear Tailgate Door Inner Trim	1	\$ 250.00	\$ 250.00
18	Rear Buzzer	1	\$ 100.00	\$ 100.00
19	Rear Antenna	1	\$ 90.00	\$ 90.00
20	Rear / End Panel Garnish	1	\$ 100.00	\$ 100.00
21	End Panel	1	\$ 420.00	\$ 420.00
22	Rear Spare Tire Sink Panel	1	\$ 1,130.00	\$ 1,130.00
23	Rear Spare Tyre Board	1	\$ 280.00	\$ 280.00
24	Rear Tool Sponge	1	\$ 280.00	\$ 280.00
25	Rear Windscreen Molding	1	\$ 80.00	\$ 80.00
26	Rear Exhaust	1	\$ 550.00	\$ 550.00
27	Rear Exhaust Rubber Mount	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 7,200.00
	<u>SPECIAL NETT</u>			
28	Rear License Plate with Frame	1	\$ 40.00	\$ 40.00
29	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1802-013

DATE : 10-Feb-2018

POLICY NO. : DIRECTASIA MT/00386324

VEHICLE REG. NO. : **SLD6996Z**

VEHICLE MAKE : HONDA VEZEL 1.5X (A)

TO Motor Claim Department
EQ Insurance Company Limited
 22 Gemmill Lane, Singapore 069257
 Tel: 6223 9433
 Fax: 6224 3903

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>LABOUR</u>			
30	Spray Painting Whole Rear	1	\$ 1,000.00	\$ 1,000.00
31	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,200.00	\$ 1,200.00
32	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
32	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
33	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
34	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
34	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
35	Check and rectify electrical wiring	1	\$ 20.00	\$ 20.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 2,680.00**Amount Before Excess** \$ 10,120.00**Add GST @ 7%** 708.40**Total Amount Payable** \$ **10,828.40**