



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 32357

DATE : 07/02/2018
CLAIM NO. : 11096
POLICY NO. : AVFMSB0000591702
FROM : RAYMOND

VEHICLE NO. : FBH3390M
MAKE/MODEL : YAM / YBR125

not Aduf LKK
P/P
Take photo After repair
1/2/18 3 day.

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 X
3	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$78.00	78.00
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	105.00
5	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00 X
6	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00	28.00
7	TRANSPORT CHARGES P/N: 07169 - TOWED BACK BIKE FOR ACCIDENT REPAIR.		1.00	\$35.00	35.00

SUB TOTAL
GST @ 7 %

\$594.00
\$41.58

GRAND TOTAL

\$635.58

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Acknowledge & Accepted By



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 RAYMOND				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

