F	MINOUS MINMA From (Person): Estimated Cost			Bill to:	3 02 Special Instruction Date/Time:	912/1801:33	pm
	/	TP RES / OD RE		V 7 CS			
	To Inspect Veh	W - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	SKC 317		Insured:	1 110 "	
	at Workshop m of		ki BK Rd.	0 lytion 4 #03-22 B	11 0	4 1184	2
	Policy No:	M4909	184	Claim No:	MCZOI		
	Sum Insured:			Excess:	7BA 600	W. C.	-
	Make of Veh:					3/02/2018	
(CA / REV /	REP. / REV 241 2/18@3pm	HRS Person Contac	ted. Anna	H.O.D. En	dorsement:	-
1	Date/Time	Action/Instruction	() Estin	rate			
	13/8/18 @	SKC3172X	-cc4/7117800	12476/1963	Morrier.	3/02/2018	
	13/2/186	18:21 -au	monise ver	pair by m	elnachi		
	14/2/18/1	:35am- e	mail to	ACE auth	on'se rep	air urcess	\$ 20
2	30 4 180	4.43M COI	nowned wi	th Anna G	\$3500		
		CRED \$6612	1. 60, 64-6-			19.1	

Interview (S

Tech. Invs (\$

Weekend (S

MER-00

Report Format : Lump Sum / I,D.1: (S Photos

260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ND	IA INTERNATIONA	L INSURANCE PL	Ref : CS/III18002776	S/Gad3			
1140	AINTERNATION	EMODIVATORICE	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
64 (CECIL STREET		Date: 12-02-2018				
#05	-02 IOB BUILDING	SINGAPORE 049711	SS AN ANNO				
			Code: III2				
1.		Policy Parti	culars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKC 3172X			
	Policy No.		Coverage (\$)	0.00			
	Claim No.		Excess (\$)	0.00			
	Assign From	GABRIEL WEE	Assign Date	12/02/2018			
2.		Vehicle P	articulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer -		Steering				
	Brakes		Modification				
	General						
3.		Cor	nditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
4.		Desci	ription of Damages				
5.		Ger	neral Information	[[6] 大山田市 生型形成			
	Accident Date	03/02/2018	Inspection Date	12/02/2018			
	Survey held at	ACE AUTOLUTION PTE LT					
	Jan 10, mond de	13 KAKI BUKIT ROAD 4					
		#03-22 BARTLEY BIZ CEN' SINGAPORE 417807	TRE				
5a.			Remarks				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Date:

13 Feb 2018

Preliminary Advice

Vehicle No

: SKC3172X

Accident Date

: 03/02/2018

Make

: PEUGEOT 508

Policy No.

: M490984

Assignment Date

: 13/02/2018

Excess

: \$\$0.00

Date of Inspection

: 12/02/2018

Est. Duration of Repair

: 3.00

Inspection At

: ACE AUTOLUTION PTE LTD (KAKI BUKIT)

13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE

SINGAPORE 417807

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,048.40
Revised Amount	:S\$	3,420.40
Check Items (Estimated)	:S\$	1,828.00
Total	:S\$	5,248.40

:SS Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	39,349.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,651.00

Remarks

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ly
let us have your authorisation.	

()	The vehicle is uneconomical to be repaired	, you are advised to invite tender for the wreck
---	---	--	--

Other comments:

Shiau Chan (LKKAuto)

From:

Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>

Sent:

Tuesday, 24 April 2018 5:49 PM

To:

Shiau Chan (LKKAuto)

Cc:

SUR

Subject:

RE: KINDLY ASSIST TO CHECK ON THE PARTS PRICES

FYI

From: Shiau Chan (LKKAuto)

Sent: Thursday, 19 April 2018 5:27 PM

To: Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: KINDLY ASSIST TO CHECK ON THE PARTS PRICES

Dear Guo Xiang,

Kindly assist to check on parts prices of SKC 3172X, chassis number: VF38D5FVABL033843 are below:

- 1. Reinforcement Bar 485
- 2. Rear Bumper 1350
- 3. Rear Bumper Skirt 450
- 4. Taillamp LH 543
- 5. Bumper Bracket 80
- 6. Rear Bumper Retainer 102

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Friday, 9 February 2018 1:33 PM

To:

Ace Autolution; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)

Cc:

C Meenachi - III

Subject:

RE: SKC 3172 X PEUGEOT 508 CLAIM OD

Attachments:

OD ACE SKC 3172 X ESTIMATE.XLSX

From: Motor Claim - III

Sent: 09 February, 2018 12:11 PM

To: 'Ace Autolution' <admin@aceauto.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; 'Catherine Chong (LKK

Auto)' <admin-d@lkkauto.com>

Cc: C Meenachi - III < Meenachi@iii.com.sg>
Subject: RE: SKC 3172 X PEUGEOT 508 CLAIM OD

Dear Sir/Mdm,

Please conduct an OD survey on our vehicle SKC3172X and let us have your report urgently.

This claim will be handled by Meena

*Kindly create OD claim & upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Ace Autolution [mailto:admin@aceauto.com.sg]

Sent: 09 February, 2018 11:11 AM

To: Motor Claim - III < motorclaim@iii.com.sg > Subject: SKC 3172 X PEUGEOT 508 CLAIM OD

Dear Sir / Madam,

I'm Anna from Ace Autolution .

Please be informed that Mohamed Nasar S/O Syed Mubarak owner of vehicle SKC 3172 X would like to have his car repaired at my workshop under own damage claim. His policy no is M490984.

Please let us know of your approved to have his car repaired at our workshop. Upon your approved.

The attached file is our estimate and please take noted we are going do Lump Sum for your action .

Regards,

Anna

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Wednesday, 14 February 2018 11:35 AM

To:

Admin-D (LKKAuto); 'Ace Autolution'; SUR

Cc:

assignments

Subject:

RE: SKC 3172 X PEUGEOT 508 CLAIM OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKC 3172X (Excess \$600/-). LUMP SUM REPAIR

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 14 February 2018 10:22 AM

To: 'Ace Autolution' <admin@aceauto.com.sg>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>
Subject: RE: SKC 3172 X PEUGEOT 508 CLAIM OD

Dear Anna,

Thank you for your email.

Dear Denise,

Kindly assist. Our Ref: CS/III18002776/Gqd3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ace Autolution [mailto:admin@aceauto.com.sg]

Sent: Tuesday, 13 February, 2018 6:06 PM
To: Nivitha (LKK Auto) admin-d@lkkauto.com>

View Received Message

This mail is associated with:

*SKC3172X OD Feb 3 2018 11:00AM [MOHAMED NASAR S/O SYED MUBARAK] Ace Autolution Pte Ltd

rom	India International Insurance Pte Ltd (HQ) (III_SG), sent on 13/02/2018 18:21 PM.
То	LKK HO
Subject	Alert - Adj Mandate Approved (\$\$5248.40) - SKC3172X - Claim Handler: C. Meenachi
r.ppioreu.	5248,40:EXCESS \$600.00

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0096J
Vehicle Details	00707
Vehicle Details	SKC3172X
Vehicle to be Exported:	No
Intended De-registration Date:	12 Feb 2018
Vehicle Make:	PEUGEOT
Vehicle Model:	508 1.6A TURBO ALLURE PLUS
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	10FJBX1166071
Chassis No.:	VF38D5FVABL033843
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$33,505.00
Original Registration Date:	12 Aug 2011
First Registration Date:	12 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$33,505.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2021
PARF Rebate Amount:	\$21,778.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,244.00
COE Rebate Amount:	\$17,571.00
Total Rebate Amount:	\$39,349.00

The information contained herein is correct as at 12 Feb 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties,
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	05/02/2018 14:15
Date Of Accident	03/02/2018 11:30
Exact Location Of Accident	ALONG ORCHARD RD BESIDE ORCHARD TOWER
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKC3172X
Insured/Policyholder	
Name Of Registered Owner	MOHAMED NASAR S/O SYED MUBARAK
NRIC No	\$8570096J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90670521
Alternative Phone No	OFFICE-90670521
Vehicle Particulars	
Manufacturer	PEUGEOT

Manufacturer

508 1.6A TURBO ALLURE PLUS Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

Policy Number M490984

Cover Note Number

Driver

MOHAMED NASAR S/O SYED MUBARAK Name of Driver

NRIC No S8570096J Date Of Birth 23/06/1985 Occupation INDOOR Date Of Driving Pass 18/09/2007

10 YEARS AND 4 MONTHS Driving Experience

Gender MALE

Mobile Number (LOCAL) +65-90670521

Fax Number

Contact Number OFFICE-90670521

EMail Address NOEMAIL

BLK 806 TAMPINES AVENUE 4 Address

#03-105

2 NO

YES

NO

3

NAME: GENDER:

NAME: GENDER:

NO

NO

MALE

: MALE

520806 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions

DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

Passenger 2

Details of Police Action Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

PRIVATE CAR

SJC9959R

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicles) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering processing handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

wise

(Inver's Signature (if driver is not the policyholder)

Date & Time.

NRIC/FIN No.

Name:

Reporting Centre P

Accident Sketch Plan

			# stchr	72.X	
	[Za]		B: D(9	a19R	
probable 8 d	A RES				
ESCRIBE CIRCUMSTANCES					
Reder to Hat	e mad .				
		_			-
DECLARATION					
DECLARATION I/We declare the foregoing pa	eticulars are true in every respect.			W.]

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG ORCHARD ROAD BESIDE ORCHARD TOWER. SUDDENLY I FEEL AN IMPACT OF MY VEHICLE, I NOTICED THAT VEHICLE B COLLIDED ONTO MY VEHICLE REAR PORTION.



ACE AUTOLUTION

13 Kaku Bukut Road 4 Bartley Bu: Centre #03-29 Singapore 417807 Tel 6702 4282 Fax 6702 4202

ESTIMATE FOR VEHICLE SKC 3172 X (PEUGEOT 508)

Vehicle No.

SKC 3172 X PEUGEOT 508

QTY	DESCRIPTION	CONDITIO	N		AIRER'S MATE(S\$)	SURVEYORS ADJUSTMENT
1 1 1 1 1 1	PARTS (LIST ITEMS) Taillamp LH Rear Bumper Rear Reflector Lamp Rear Boolit Rear Fender LH X Rear Bumper Skirt Rear Bumper Retainer Rear Bumper Retainer	Repair Repair			1920.00 1650.00 75.00 0.00 0.00 576.00 255.00	1350 1350 450 102
1	SPECIAL NETT ITEMS Reverse Sensor / DM Rear End Panel % Lepuly	TOTAL	less	10%	447.60 4028.40 350.00 100.00 350.00	200 8f

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



ESTIMATE FOR VEHICLE SGQ 7206 E (HONDA VEZEL)

Vehicle No. SKC 3172 X PEUGEOT 508

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts & components	1200.00	200 400
	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (LHS Fender & Bootlid)	1000.00	500.750
	To remove, refix wiring system at accident damaged areas and check for proper function	200.00	30
	To remove and replace reverse sensors and check for proper function	120.00	40
	To perform anti-rust treatment on affected areas (rear end panel	150.00	X NN 1420
	Labour Total :	2670.00	1420
	TOTAL (PARTS & LABOUR):	7048.40	

NOTE; SUPPLEMENTARY PARTS AND LABOUR (IF ANY) WILL BE ADDED TO THIS ESTIMATE AFTER THE DAMAGED PORTION IS DISMANTLED TO DETERMINE THE FULL EXTENT OF DAMAGED VISIBLE INTERNAL PARTS

Uspsin repair

After point photos.

Emo li arg - 82880282

Quo Qi ang @ Ikk auto. com

12/2/18.

Excess: To be advise. Not Authorised.

9729.60



ACE AUTOLUTION 13 Kakı Bukıt Road 4 Bartley Biz Centre =03-29 Singapore 417807 Tel:6702 4282 Fax:6702 4202

SUPPLEMENTARY FOR VEHICLE SKC 3172 X (PEUGEOT 508)

Vehicle No. SKC 3172 X PEUGEOT 508

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYORS ADJUSTMENT	
	PARTS (LIST ITEMS)					
1	Rear End Panel X Repeated			1200.00	X	
1	Reinforcement Bar		487	864.00	436	.5
1	Bumper Bracket /) //(80	420.00	r	
1	bumper Bracket Chrome & NN			384.00	×	
				2868.00		
		less	10%	286.80	10%	

6m. Ceip.
13/2/18

443.5 6.399.15 4011.75



ACE AUTOLUTION

13 Kaki Bukir Road 4 Bartley Biz Centre =03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

ESTIMATE FOR VEHICLE SKC 3172 X (PEUGEOT 508)

Vehicle No. SKC 3172 X PEUGEOT 508

PARTS (LIST ITEMS)	QTY	DESCRIPTION	CONDI	TION		AIRER'S MATE(S\$)	SURVEYOR
SPECIAL NETT ITEMS 350.00 350.00 10% 1	1 1 1 1	Rear Boolit Rear Fender LH	0.0000000000000000000000000000000000000	1650.00 75.00 Repair 0.00 Repair 0.00 576.00		488.7	
1 Reverse Sensor / 350.00		,		less	10%	447.60	10%
TOTAL 350.00		Reverse Sensor /	TOTAL			100.00	

Gebregarly phl. loting 2012/18



ACE AUTOLUTION

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

ESTIMATE FOR VEHICLE SGQ 7206 E (HONDA VEZEL)

Vehicle No.

SKC 3172 X PEUGEOT 508

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts & components	1200.00	200 121
	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (LHS Fender & Bootlid)	1000.00	500 + 20
	To remove, refix wiring system at accident damaged areas and check for proper function	200.00	30
	To remove and replace reverse sensors and check for proper function	120.00	40
	To perform anti-rust treatment on affected areas (rear end panel	150.00	X
	Labour Total :	2670.00	
	TOTAL (PARTS & LABOUR):	7048.40	

NOTE; SUPPLEMENTARY PARTS AND LABOUR (IF ANY) WILL BE ADDED TO THIS ESTIMATE AFTER THE DAMAGED PORTION IS DISMANTLED TO DETERMINE THE FULL EXTENT OF DAMAGED VISIBLE INTERNAL PARTS

48 Days.

lump som repair

After point photos.

Emo &i ong - 82880282

Quo Qiang@ Ikk auto. com

12/2/18.

Excess: To be advise.

Not Authorised.

I KK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd 64 Cecil Street, #04-00 IOB Building Singapore 049711

Our File No:

CS/III18002776/GQD3N2

Date:

08/05/2018

REFERENCE

Insured/Claimant: MOHAMED NASAR S/O SYED MUBARAK

Policy No:

M490984

03/02/2018 Date of Loss:

Nature of Claim: OD

Claim No: MC20182119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKC3172X

Make & Model:

PEUGEOT 508, 1.6 Turbo (A) 12/08/2011 (Man. Year: 2011) Engine No:

10FJBX1166071

69472 km

Reg. Date: Colour:

White

Chassis No: Odometer:

VF38D5FVABL033843

Engine Capacity: Market Value/New Car

1598 cc

Price:

\$\$52,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/45R18

Rear Tyre Size:

235/45R18

Front Left Side:

Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 7,059.60 0.00	Adjuster's 2,976.50 0.00	Difference 4,083.10 0.00	Diff % 57.84
Labour Paintwork Labour	2,670.00 0.00	1,420.00 0.00	1,250.00 0.00	46.82
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	9,729.60	4,396.50 3,500.00	5,333.10	54.81
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	9,129.60	2,900.00	6,229.60	68.24

INSPECTION

Date of Assignment:

09/02/2018

Date Inspected:

12/02/2018 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30 Bartley

Biz Centre

Singapore 417807

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 2 of 3 Adjuster Report

REPAIR DETAILS

Reference

Print Code: (Unsubmitted, no print-code for SKC3172X)

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2018)

PEUGEOT 508 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH	Cracked	1,920.00 FL	*543.00 FL
2	1		*REAR BUMPER	Cracked	1,650.00 FL	*1,350.00 FL
3	1		*REAR REFLECTOR LAMP *REAR BOOTLID (NPA)	Scratched Repair	75.00 FL 0.00 FL	*75.00 FL *- FL
5 6	1		*REAR FENDER LH (NPA) *REAR BUMPER SKIRT	Repair Deformed	0.00 FL 576.00 FL	*- FL *450.00 FL
7 8	1		*REAR BUMPER RETAINER *REAR END PANEL	Necessary Repeated	255.00 FL 1,200.00 FL	*102.00 FL *- FL
9	1		*REINFORCEMENT BAR	Bent	864.00 FL	*485.00 FL
10	1		*BUMPER BRACKET	Bent	420.00 FL	*80.00 FL
11	1		*BUMPER BRACKET CHROME	Not Necessary	384.00 FL	*- FL
12	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
13 F≡Fra	1 anchise	part. S=SpcNe	*REAR END PANEL ett. L=ListItemDisc.	Repair	100.00 FS	*- FS
				Sub Total (S\$)	7,794.00	3,285.00
			- List Item Discount on L	Items 10.00/10.00% (S\$)	734.40	308.50
				Total Parts (S\$)	7,059.60	2,976.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Dage	mm	on	404	1 0	COLIF
Reco	111111	еп	ueu	La	Jour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTIGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS & COMPONENTS	New	1,200.00	600.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED (LHS FENDER & BOOTLID)	New	1,000.00	750.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	200.00	30.00
4	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	40.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS (REAR END PANEL)	New	150.00	. 4
	Gross Labor	ur Cost (S\$)	2,670.00	1,420.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >