

INS. CASE OWNER:		CC 4/EQ1800 288, A 4834		LICK- IDAC:	
Surveyor: <u>Adrian</u>		DOI: <u>9/2/18</u>		Date / Time: <u>9/2/18</u>	
Pre-assign / CCU / FTE		Registered in Merimen: <u> </u>			
	Insured Vehicle No.:	<u>SLS 8656M</u>		Claim No.:	<u> </u>
	Name of Insured:	<u>ROSET UNOUSINE SERVICES P/L</u>		Policy No.:	<u>DRUPHUA-000184</u>
	Insured Tel No.:	HP:	<u> </u>	Make / Model:	<u>TOYOTA</u>
	Excess Sec II :\$	D.O.A.:	<u>2/2/18</u>	Place of Accident:	<u>PAKIR KUS DR 1 OPPA PAKIR</u> <u>KIS WEST PAKIR</u>
	Is driver the owner? (YES/NO)	Nature of Accident:			
If NO, Driver Name / Age: <u>FOO HUI AI</u>		OI GIA REPORT (YES/NO): <u>YES</u>		TP GIA REPORT (YES/NO): <u>YES</u>	
Driver Tel No.:		(V/L YES/NO)		Insured Liability: <u> </u> Final ? Yes/No	
<u>SLS 8656M</u> → → → → →					
	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
					
					
					
					

Date/ Time	<u>19/7/18</u> <u>Adrian</u> <u>200313</u>	STAGE Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI: Documentation Check List: Handler Typist Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:
	RECEIVED 16 APR 2018	

PRELIMINARY ADVICE		Date/Time: <u>14/7/18</u>	Sent By: <u>Adrian</u>
FINALIZATION		Date/Time: <u> </u>	Confirm with: <u> </u>
Repair Cost:	\$	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: <u>10/4/18</u>	Confirm with: <u> </u>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	<u>27</u>
Repair Cost:	\$	<u>6152.5</u>	
Loss of Rental (LOR):	\$	(days)	
Loss of Use (LOU):	\$	<u>640 (\$ 30 x 8 days)</u>	
Loss of Income (LOI):	\$	(\$ x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	\$	<u>36.43</u>	
Medical	\$		
Disbursement:	\$	(e.g. Tow/ Independent)	
Legal Cost	\$		
Total:	\$	<u>6528.95</u>	Global Sum \$:
FINAL PAYMENT		Date/Time: <u> </u>	Confirm with: <u> </u>
Payee 1:	\$	<u>6528.95</u>	Name 1: <u>TORQUE 5 P/L</u>
Payee 2: (Strike if N.A.)	\$		Name 2: <u> </u>
Payee 3: (Strike if N.A.)	\$		Name 3: <u> </u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18002788/Ayb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 12-02-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 8656M	Veh. Inspected	SKS 9249K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018	Inspection Date	09/02/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 190607188R

31 UBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118002788/Ayb3

Date: 14.03.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKS9249K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.02.2018 at the premises of M/s Torque 5 Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	16,952.70
Revised Estimate Amount	: S\$	7,230.03
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

TPEO
JCS

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid <i>vented</i>	1.00	1,339.00	<u>1,339.00</u> <i>685</i>
2	Rear bootlid support garnish (LH) <i>3pc</i>	1.00	0.00	0.00 <i>+</i>
3	Rear bootlid support garnish (RH)	1.00	0.00	0.00 <i>+</i>
4	Rear bootlid lock <i>2pc</i>	1.00	167.00	167.00 <i>—</i>
5	Rear bootlid weather strip <i>1pc</i>	1.00	84.50	84.50 <i>—</i>
6	Rear bootlid logo <i>3pc</i>	1.00	67.00	67.00 <i>—</i>
7	Rear bootlid emblem - Lancer	1.00	68.00	68.00 <i>—</i>
8	Rear bootlid emblem - Cycle & carriage <i>1pc</i>	1.00	68.00	68.00 <i>—</i>
9	Rear bootlid key lock <i>1pc</i>	1.00	165.00	165.00 <i>+</i>
10	Rear bootlid inner trim <i>2pc</i>	1.00	0.00	0.00 <i>—</i>
11	Rear bootlid inner trim clip <i>1pc</i>	10.00	5.00	<u>50.00</u> <i>30</i>
12	Rear bootlid lamp (LH) <i>2pc</i>	1.00	182.00	182.00 <i>2</i>
13	Rear bootlid lamp (RH) <i>2pc</i>	1.00	182.00	182.00 <i>2</i>
14	Rear bumper <i>Discontinued</i>	1.00	1,205.00	<u>1,205.00</u> <i>741</i>
15	Rear bumper clip <i>1pc</i>	10.00	5.00	<u>50.00</u> <i>30</i>
16	Rear bumper retainer (LH) <i>3pc</i>	1.00	52.00	52.00 <i>✓</i>
17	Rear bumper retainer (RH)	1.00	52.00	52.00 <i>✓</i>
18	Rear bumper bracket (LH) <i>3pc</i>	1.00	82.00	82.00 <i>+</i>
19	Rear bumper bracket (RH)	1.00	82.00	82.00 <i>+</i>
20	Rear bumper reinforcement <i>Best</i>	1.00	211.20	211.20 <i>✓</i>
21	Rear bumper towing cap <i>2pc</i>	1.00	50.00	50.00 <i>—</i>
22	Rear bumper reflector (LH) <i>Missing</i>	1.00	68.00	68.00 <i>✓</i>
23	Rear bumper reflector (RH) <i>2pc</i>	1.00	68.00	68.00 <i>✓</i>
24	Rear bumper air duct (LH) <i>1pc</i>	1.00	0.00	0.00 <i>+</i>

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
25	Rear bumper air duct (RH) <i>new</i>	1.00	0.00	0.00 <i>+</i>
26	Tail lamp (LH) <i>cracked</i>	1.00	352.00	352.00 <i>✓</i>
27	Tail lamp (RH) <i>cracked</i>	1.00	352.00	352.00 <i>2</i>
28	Tail lamp clip (LH) <i>new</i>	2.00	5.00	10.00 <i>✓</i>
29	Tail lamp clip (RH) <i>new</i>	2.00	5.00	10.00 <i>2</i>
30	Tail lamp bracket (LH) <i>green</i>	1.00	55.00	55.00 <i>+</i>
31	Tail lamp bracket (RH) <i>green</i>	1.00	55.00	55.00 <i>+</i>
32	Rear end panel <i>cracked</i>	1.00	806.00	806.00 <i>465</i>
33	Rear end panel top garnish <i>cracked</i>	1.00	323.00	323.00 <i>✓</i>
34	Rear end panel top garnish clip <i>new</i>	10.00	5.00	50.00 <i>15</i>
35	Rear fender (LH) <i>green</i>	1.00	850.00	850.00 <i>+</i>
36	Rear fender (RH) <i>green</i>	1.00	850.00	850.00 <i>+</i>
37	Rear fender cowling (LH) <i>green</i>	1.00	135.00	135.00 <i>+</i>
38	Rear fender cowling (RH) <i>green</i>	1.00	135.00	135.00 <i>+</i>
39	Rear fender cowling clip (LH) <i>green</i>	10.00	5.00	50.00 <i>+</i>
40	Rear fender cowling clip (RH) <i>green</i>	10.00	5.00	50.00 <i>+</i>
41	Rear fender inner trim (LH) <i>torn</i>	1.00	267.00	267.00 <i>✓</i>
42	Rear fender inner trim (RH) <i>torn</i>	1.00	267.00	267.00 <i>2</i>
43	Rear fender inner trim clip (LH) <i>new</i>	10.00	5.00	50.00 <i>30</i>
44	Rear fender inner trim clip (RH) <i>new</i>	10.00	5.00	50.00 <i>230</i>
45	Rear windscreen moulding <i>new</i>	1.00	97.00	97.00 <i>+</i>
46	Spare wheel panel <i>Repair</i>	1.00	590.00	590.00 <i>+</i>
47	Spare wheel panel top board <i>new</i>	1.00	345.00	345.00 <i>2</i>
48	Spare wheel panel sponge <i>new</i>	1.00	0.00	0.00 <i>+</i>
49	Exhaust pipe <i>Best</i>	1.00	963.00	963.00 <i>485</i>

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
 CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
50	Exhaust pipe mounting <i>mm</i>	2.00	35.00	70.00 <i>x</i>
51	Exhaust pipe gasket <i>mm</i>	1.00	68.00	68.00 <i>+</i>
52	Exhaust pipe heat shield <i>del</i>	1.00	0.00	55 0.00 <i>2</i>
				Amt S\$ 11,142.70
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 11,142.70

546670
4920.03

Section: Special Nett Items

53	Rear bootlid sticker - asian garage <i>mm</i>	1.00	50.00	50.00 40
54	Rear number plate <i>Bent</i>	1.00	50.00	50.00 <i>✓</i>
55	Rear bumper reverse sensor <i>2</i>	1.00	400.00	400.00 200
56	Rear end panel sealant <i>mm</i>	1.00	80.00	80.00 60
57	Rear fender sealant <i>2</i>	1.00	80.00	80.00 <i>+</i>
58	Rear windscreen sealant <i>set</i>	1.00	80.00	80.00 <i>+</i>
59	Spare wheel panel sealant <i>mm</i>	1.00	80.00	80.00 <i>+</i>
60	Spare wheel panel insulator <i>mm</i>	1.00	100.00	100.00 <i>+</i>
61	Spare wheel <i>✓</i>	1.00	500.00	500.00 <i>1</i>
				Amt S\$ 1,420.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,420.00

350

Section: Labour Items

62	To R&R accident affected areas	1.00	1,750.00	1,750.00 80
63	To putty & respray accident affected areas	1.00	1,500.00	1,500.00 80
64	To rust proof accident affected areas	1.00	90.00	90.00 60
65	To R&R rear boot mechanism	1.00	80.00	80.00 40

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
66	To R&R rear luggage compartment	1.00	200.00	200.00 80
67	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00 50
68	To check wiring layout of tail lamp	1.00	80.00	80.00 30
69	To R&R rear windscreen	1.00	150.00	150.00 +
70	To R&R exhaust pipe assy	1.00	180.00	180.00 100
71	To do wheel alignment	1.00	180.00	180.00 +
72	To check for water seepage	1.00	100.00	100.00 +

Amt S\$ 4,390.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 4,390.00

Adrian Lj
4/s 09/02/18.

07 Pags.

total: 7230.03.

2/s: 5750 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 11,142.70

Special Nett Items S\$ 1,420.00
Subtotal

Labour Items Subtotal S\$ 4,390.00
Total S\$

16,952.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1585M

Vehicle Details

Vehicle No.: SKS9249K

Vehicle to be Exported: Yes

Intended De-registration Date: 09 Feb 2018

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER 2.0L MIVEC GLS 6-CVT

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: 4B11BD2752

Chassis No.: JMYSTCY4A8U003047

Maximum Power Output: 114.0 kW (152 bhp)

Open Market Value: \$17,848.00

Original Registration Date: 14 Aug 2008

First Registration Date: 14 Aug 2008

Transfer Count: 2

Actual ARF Paid: \$17,848.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Aug 2018

PARF Rebate Amount: \$8,924.00

Intended COE Rebate Details

COE Expiry Date: 13 Aug 2018

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$12,889.00

COE Rebate Amount: \$658.00

Total Rebate Amount: \$9,582.00

The information contained herein is correct as at 09 Feb 2018

OK



ANNOUNCING Cosmo Automobiles
as sgCarMart Premium Dealer for the 3rd Consecutive Year



Lancer Price Range Depreciation 2008 Vehicle Type

Advanced Search

Used Car Comparison

— Comparing 3 Vehicles —

Mitsubishi Lancer EX 2.0A GLS

Mitsubishi Lancer EX 2.0A GLS
Sunroof

Mitsubishi Lancer EX 2.0A GLS



NO IMAGE AV

Use search bar above to see to compare.

Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

Price	\$15,800	\$15,800	\$14,800	-
Instalment	\$1,607	\$1,607	\$1,752	-
Registration Date	11-Sep-2008	09-Sep-2008	26-Aug-2008	-
Manufactured	2008	2007	2008	-
Mileage	-	149,623 km	140,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,998 cc	1,998 cc	1,998 cc	-
Road Tax	\$1,210 /yr	\$1,210 /yr	\$1,210 /yr	-
Power	114.0 kW (152 bhp)	114.0 kW (152 bhp)	114.0 kW (152 bhp)	-
Curb Weight	1,427 kg	1,427 kg	1,427 kg	-
Features	2.0L MIVEC Engine, 6 Speed Auto Transmission, SRS Airbags, Multi Function Steering, Cruise Control, Paddle Shifter, Reverse Sensors, Etc.	2.0L MIVEC Engine Producing 152BHP, SRS Airbags, Cruise Control, Keyless Entry/Start, Auto Headlights.	Powerful 2.0L MIVEC Engine Delivering 152Bhp And 199Nm Of Torque Mated To A Reliable 6 Speed Auto CVT Transmission With Paddle Shifters.	-
Accessories	Door Visors, Solar Film, Pioneer DVD Audio System, Upholstery Leather Seats, Side Mirrors With Indicator.	Factory Fitted Audio System, Sports Rims, Leather Seats, Fog Lamps, Solar Film, Reverse Sensors, Keyless Entry, Sun Roof.	Multi Functional Steering With Cruise Control And Volume Control, Evo Inspired Bodykit And Vossen Inspired Rims, Keyless Entry And Start Ignition.	-
Description	No Repair Needed! Good For Private Hire Usage. Call Now For Viewing.	Accident Free! Depreciation \$800 A Month, Cheaper Than Rental! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To View And Discuss.	Road Tax Just Renewed, One Of The Best Sedan In The Market With Ample Space For A Family Of 5 And Powerful Enough To Carry The Family For Long Distance Journey In Comfort. Packaged With Continental Features At Japanese Price.	-
COE	\$5,631	\$13,389	\$13,890	-
OMV	\$17,234	\$18,746	\$16,511	-
ARF	\$15,142	\$18,746	\$16,511	-
Depreciation	\$14,100 /yr	\$11,120 /yr	\$12,120 /yr	-
No. of Owners	3	2	6	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

Seller	William Lee Car Aircon Engineering	Ritz Auto	Supercars Singapore	-
--------	------------------------------------	-----------	---------------------	---

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 8 February, 2018 3:32 PM
To: assignments
Subject: FW: Our ref:DM18HO00348/JT-: Accident Involving SKS9249K & SLS8656M on 03/02/2018 (PRE-REPAIR SURVEY REQUEST)
Attachments: image021.wmz; image024.emz; image012.wmz; image017.wmz; image021.emz; image025.wmz; SKS9249K-GIA REPORT.pdf
Importance: High

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

08-02-2018 @ 4.08pm
Li Yu veh in.

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Thursday, 8 February 2018 2:26 PM
To: Admin A <admin-a@lkkauto.com>
Cc: assessment@torque5.com
Subject: Our ref:DM18HO00348/JT-: Accident Involving SKS9249K & SLS8656M on 03/02/2018 (PRE-REPAIR SURVEY REQUEST)
Importance: High

Without Prejudice
Save As To Costs

Dear Li Yu

As per tele-conversation, liability is clear. We can proceed with direct settlement.

Aside to surveyor, please arrange to attend to the PRS by today. Liability is clear. Proceed to direct settle if possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: Francis Ng
Sent: Thursday, February 8, 2018 2:15 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: FW: Accident Involving SKS9249K & SLS8656M on 03/02/2018 (PRE-REPAIR SURVEY REQUEST)
Importance: High

Dear Janet,

Please assist, thanks.

Regards,
Francis Ng
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: Torque 5 Assessment [<mailto:assessment@torque5.com>]
Sent: Wednesday, February 7, 2018 3:48 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Cc: 'Torque 5 Assessment' <assessment@torque5.com>
Subject: FW: Accident Involving SKS9249K & SLS8656M on 03/02/2018 (PRE-REPAIR SURVEY REQUEST)
Importance: High

Dear Francis,

As spoken on the phone, kindly assist regarding the matter reflected below.
Thank you.

Warmest Regards,
Stephanie Teo
Assessor | Motor Claims Department



Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Torque 5 Assessment [<mailto:assessment@torque5.com>]

Sent: Tuesday, 6 February, 2018 4:55 PM

To: elaine.cheong@eqinsurance.com.sg; yuxin.ching@eqinsurance.com.sg; 'Tan Wei Yin'

Cc: assessment@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; claims@torque5.com

Subject: Accident Involving SKS9249K & SLS8656M on 03/02/2018 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Sense Car Rental Pte Ltd, to notify you of the aforesaid accident involving our client's vehicle SKS 9249 K and your insured's vehicle SLS 8656 M on 03/02/2018.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SLS 8656 M for damages, costs and disbursements.



Please let us know within **2 working days** from today,

your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Stephanie Teo (9147 8841)

Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 06/02/2018 04.10PM

PRS ARRANGEMENT (Date & Time) : 06/02/2018 04.54PM

PRS ACKNOWLEDGEMENT

Appointed Surveyor :
(Name & Signature)

Date & Time of Inspection :

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

Heng Lee Yi

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com





Bevan Lim (LKK Auto)

From: Torque 5 Claims <claims@torque5.com>
Sent: Tuesday, 10 April 2018 11:41 AM
To: Bevan Lim (LKK Auto)
Cc: Admin A; Vic (LKKAuto); 'Torque 5 Claims'
Subject: RE: ACCIDENT INVOLVING SKS 9249 K & SLS 8656 M ON 03 February 2018. Our Ref: SKS 9249 K
Attachments: SKS 9249K - TAX INVOICE.pdf

WITHOUT PREJUDICE

Dear Bevan,

We accept the settlement for property matter at \$6,828.95 .

Attached tax invoice for your reference.

Will courier out the original LOD & Tax invoice to you.

Thank you

The settlement herein is in respect of our client's claim for damages pertaining to his motor vehicle



and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Warmest Regards,

Rachel Wu

Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 EXT 112 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Tuesday, 10 April 2018 10:25 AM
To: 'Torque 5 Claims '
Cc: Admin A; Vic (LKKAuto)
Subject: RE: ACCIDENT INVOLVING SKS 9249 K & SLS 8656 M ON 03 February 2018. Our Ref: SKS 9249 K

Without Prejudice

Dear Racheal,

We refer to your email below.

We propose settlement as follows:

Cost of Repair	\$6,152.50
Loss of Use (8 days X \$80.00)	\$ 640.00
GIA/LTA Search fee	\$ 36.45
Total	\$6,828.95

Kindly revert Acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Torque 5 Claims [mailto:claims@torque5.com]

Sent: Friday, 16 March 2018 4:48 PM

To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Admin A <admin-

Torque 5 Claims

From: Claims <claims@torque5.com>
Sent: 16 March, 2018 10:34 AM
To: 'Vivian Lau (LKKAuto)'; Zaini (LKK Auto)
Cc: claims@torque5.com
Subject: ACCIDENT INVOLVING SKS 9249 K & SLS 8656 M ON 03 February 2018. Our Ref: SKS 9249 K
Attachments: SKS 9249 K LOD.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

Attached is the Final repair bill, Loss Of Use, GIA & LTA fee of the above mentioned vehicle.

Claim amount as per below:-

1. Repair Cost	\$ 6,152.50
2. Loss of Use for 8Days x \$100/- per day	\$ 800.00
3. LTA/GIA fee	\$ 36.45

TOTAL: \$ 6,988.95

The above settlement is in respect of our client's claim for damages pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation of his personal injuries.

Kindly acknowledge by replying to this email and advise who is the officer in charge.

Your assistance is greatly appreciated.



Thank you.

Warmest Regards,
Michelle Lim
Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875
www.torque5.com





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQI18002788/Amb3

21 MARCH 2017

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVENUE 1
#03-47 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

Dear Sir/Madam,

ACCIDENT INVOLVING SLS 8656M AND SKS 9249K ON 03/02/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)



LETTER OF AUTHORISATION

Accident on 03/02/2018 along 65 Pasir Ris Drive 1
Involving vehicles SKS 9249K, SLS 8656M.

In consideration of **Torque 5 Pte Ltd, 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit #01-50 Singapore 415875**, repairing my/our motor vehicle no SKS 9249K at my request, I/We, Sence Car Rental Pte Ltd ("the claimant") of 19 Tai Seng Ave #01-03 S(534054) (address) bearing NRIC No 201711585M the owner of motor vehicle no SKS 9249K, hereby authorize them to demand claim, settle and receive whatever amount settle payable by the insurance company or third party or commence legal proceeding for cost of repairs, loss of use and etc to any of their appointed solicitors to act for me/us in respect of the said accident/claim and all the amount claimed or settled shall belong and make payable to them absolutely by the insurance company of the third party. I/We further authorized them to give an absolute discharge on my/our behalf and to sign discharge voucher(s) and any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

I/We further agree to fully co-operate and attend all court hearings that are necessary to prosecute the claims maintained by **Torque 5 Pte Ltd**.

I/We further agree and undertake to indemnify them against my/our claim for costs which arise therewith.

In the event that my/our claim is unsuccessful, I/we undertake to pay to **Torque 5 Pte Ltd** the cost of repairs to my/our vehicle.

In the event that the settlement/payment cheque is being made in my/our favour, I/we hereby undertake to return the full amount to **Torque 5 Pte Ltd** account, within 7 days from receiving and clearance of the said settlement/payment cheque. Failing which, **Torque 5 Pte Ltd** will have the legal rights to take legal proceedings against me/us to recover the said sum, with further costs and disbursements to be incurred by me/us.

I/We further authorize **Torque 5 Pte Ltd** to settle the aforesaid claim in a manner that you deem fit and to utilize the monies to pay your charges without further reference to me/us. The payment to **Torque 5 Pte Ltd** shall amount to a good discharge of **Torque 5 Pte Ltd** obligation to me/us in respect of the settlement monies.

Dated this 6 day of February (month) 20 18 (year)

Signed by "the claimant"

Name: Sence Car Rental Pte Ltd

NRIC No: 201711585M



Signed by **Torque 5 Pte Ltd**

Name: Michelle



SATISFACTION VOUCHER

I / We, Sense Car Rental Pte Ltd hereby confirm that repairs to my / our
vehicle no. SKS 9249K have been completed to my / our satisfaction and
that I / we have collected my / our said vehicle on the under-mentioned date.

Date in: 6/2/2018

Date out: 14/2/18



Owner's Signature

Name: Sense Car Rental Pte Ltd

NRIC No.: 201711585M

Date: 14/2/18

Time:



EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110
Tel: 6223 9433

Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Tax Invoice

Inv. No. : T51804129
Inv. Date : 10 Apr 2018
Ref : 03/02/2018
Terms : 30 Days
Veh. No. : SKS9249K
Make & Model : MITSUBISHI LANCER
2.0L MIVEC GLS 6-CVT

#	Description	Qty	UOM	Unit Price	Disc	Amt
1	TO SUPPLY SPARE PARTS AND LABOUR FOR ACCIDENT REPAIR PARTS LUMP SUM AMOUNT	1.00		5,750.00	0.00	5,750.00

I agree to the price as listed above and
affirm that the goods are received in good
condition.

(Customer's Signature and Company Stamp)

Subtotal : S\$ 5,750.00
GST 7.0% : S\$ 402.50
Total : S\$ 6,152.50

For **TORQUE 5 PTE. LTD.**



(Authorised Signature)
Reg no: 201313221G

Receipt



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Feb 2018 / 16:13:15
Receipt Date/Time : 06 Feb 2018 / 16:13:15

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180206-001389

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SLS8656M
As at 03 Feb 2018/15:50:00
Insurance Co: EQ INSURANCE COMPANY LTD
1 Insurance Enquiry - SLS8656M
Enquiry Fee
20180206161132821378

	7.00	0.49	7.49
Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By
20180206161140906 Direct Debit: eNETS Debit
(Internet Banking) 7.45
Total 0.00
Cash Change 7.45
Tendered Amount 0.00
Excess Refundable Amount

SK59749K

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK Save as PDF

2/13/2018


**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

 Our Ref No: GR-18-023888
 Date of Request: 13/02/2018

Your Ref No: Online Purchase

 Torque 5 Pte Ltd
 No. 8 Kaki Bukit Ave 4,
 #01-50
 Singapore 415875

Dear Sir/Madam,

 Date of Accident: 03/02/2018
 Vehicle No: SKS9249K
 Place of Accident: 65 PASIR RIS DRIVE 1
 Involving Vehicle No: SLS8656M

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLS8656M	65 PASIR RIS DRIVE 1	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

2/13/2018

Invoice



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-023886
Date of Request: 13/02/2018
Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 03/02/2018
Place of Accident: 65 PASIR RIS DRIVE 1
Client Vehicle No: SKS9249K

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SLS8656M	PASIR RIS DR 1 OPPO PASIR RIS WEST PLAZA	03/02/2018 15:15

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**Our Ref No: GR-18-023886
Date of Request: 13/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:Date of Accident: 03/02/2018
Place of Accident: 65 PASIR RIS DRIVE 1
Client Vehicle No: SKS9249K

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/04/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLS 8656M (Insd Veh)	Your Ref. No. : DM18HO00348/JT
	SKS 9249K (TP Veh)	Our Ref. No. : CC4/EQI18002788/Amb3q2
Date of Accident	3/2/2018	

Liability	100%	
Final Repair Cost	: \$ 6,152.50	
Loss of Use	: \$ 640.00	8 days
Rental (If any)	: \$	days
Others:	: \$ 36.45	
	: \$	
	6,828.95	
Final Settlement Sum	: \$ 6,828.95	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	TORQUE 5 PTE LTD	: \$ 6,828.95
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ118002788/Amb3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 18-04-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 8656M	Veh. Inspected	SKS 9249K	
Policy No.	DMCFHQ17-000185	Coverage (\$)	0.00	
Claim No.	DM18HO00348/JT	Excess (\$)	0.00	
Assign From	JANET	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JMYSTCY4A8U003047	Colour	BLACK	
Odometer	135816	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	NEXEN	6 mm	
L/H Front Tyre	225/50 R17	NEXEN	6 mm	
R/H Rear Tyre	225/50 R17	NEXEN	6 mm	
L/H Rear Tyre	225/50 R17	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2018	Inspection Date	09/02/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR.		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9249K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	DENTED	1,339.00	685.00
1	REAR BOOTLID SUPPORT GARNISH (LH) (NPA)	NOT NECESSARY	-	-
1	REAR BOOTLID SUPPORT GARNISH (RH) (NPA)	NOT NECESSARY	-	-
1	REAR BOOTLID	DAMAGED	167.00	167.00
1	REAR BOOTLID WEATHER STRIP	CUT	84.50	84.50
1	REAR BOOTLID LOGO	NECESSARY	67.00	67.00
1	REAR BOOTLID EMBLEM -LANCER	NECESSARY	68.00	68.00
1	REAR BOOTLID EMBLEM -CYCLE & CARRIAGE	NECESSARY	68.00	68.00
1	REAR BOOTLID KEY LOCK	NOT NECESSARY	165.00	-
1	REAR BOOTLID INNER TRIM (NPA)	DEFORMED	-	-
10	REAR BOOTLID INNER TRIM CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BOOTLID LAMP (LH)	CRACKED	182.00	182.00
1	REAR BOOTLID LAMP (RH)	CRACKED	182.00	182.00
1	REAR BUMPER	DISTORTED	1,205.00	741.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER RETAINER (LH)	NECESSARY	52.00	52.00
1	REAR BUMPER RETAINER (RH)	NECESSARY	52.00	52.00
1	REAR BUMPER BRACKET (LH)	NOT NECESSARY	82.00	-
1	REAR BUMPER BRACKET (RH)	NOT NECESSARY	82.00	-
1	REAR BUMPER REINFORCEMENT	BENT	211.20	211.20
1	REAR BUMPER TOWING CAP	DEFORMED	50.00	50.00
1	REAR BUMPER REFLECTOR (LH)	MISSING	68.00	68.00
1	REAR BUMPER REFLECTOR (RH)	CRACKED	68.00	68.00
1	REAR BUMPER AIR DUCT (LH) (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER AIR DUCT (RH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (LH)	CRACKED	352.00	352.00
1	TAIL LAMP (RH)	CRACKED	352.00	352.00
2	TAIL LAMP CLIP (LH) @\$5.00	NECESSARY	10.00	10.00
2	TAIL LAMP CLIP (RH) @\$5.00	NECESSARY	10.00	10.00
1	TAIL LAMP BRACKET (LH)	NOT NECESSARY	55.00	-
1	TAIL LAMP BRACKET (RH)	NOT NECESSARY	55.00	-

Report Ref No. CC4/EQ18002788/Amb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DISTORTED	806.00	485.00
1	REAR END PANEL TOP GARNISH	DEFORMED	323.00	323.00
10	REAR END PANEL TOP GARNISH CLIP @\$5.00	NECESSARY	50.00	15.00
1	REAR FENDER (LH)	NOT NECESSARY	850.00	-
1	REAR FENDER (RH)	NOT NECESSARY	850.00	-
1	REAR FENDER COWLING (LH)	NOT NECESSARY	135.00	-
1	REAR FENDER COWLING (RH)	NOT NECESSARY	135.00	-
10	REAR FENDER COWLING CLIP (LH) @\$5.00	NOT NECESSARY	50.00	-
10	REAR FENDER COWLING CLIP (RH) @\$5.00	NOT NECESSARY	50.00	-
1	REAR FENDER INNER TRIM (LH)	TORN	267.00	267.00
1	REAR FENDER INNER TRIM (RH)	TORN	267.00	267.00
10	REAR FENDER INNER TRIM CLIP (LH) @\$5.00	NECESSARY	50.00	30.00
10	REAR FENDER INNER TRIM CLIP (RH) @\$5.00	NECESSARY	50.00	30.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	97.00	-
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	590.00	-
1	SPARE WHEEL PANEL TOP BOARD	NOT NECESSARY	345.00	-
1	SPARE WHEEL PANEL SPONGE (NPA)	NOT NECESSARY	-	-
1	EXHAUST PIPE	BENT	963.00	485.00
2	EXHAUST PIPE MOUNTING @\$35.00	NOT NECESSARY	70.00	-
1	EXHAUST PIPE GASKET	NOT NECESSARY	68.00	-
1	EXHAUST PIPE HEAT SHIELD	DEFORMED	55.00	55.00
	LESS 10% DISCOUNT		-	-546.67
			11,197.70	4,920.03
	SPECIAL NETT ITEMS			
1	REAR BOOTLID STICKER -ASIAN GARAGE (SN)	NECESSARY	50.00	40.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	400.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	SPARE WHEEL PANEL INSULATOR (SN)	NOT NECESSARY	100.00	-

Report Ref No. CC4/EQ18002788/Amb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE WHEEL (SN)	NOT NECESSARY	500.00	-
			1,420.00	350.00
	LABOUR			
	TO R&R ACCIDENT AFFECTED AREAS . INCLUSIVE OF THE REPAIR OF SPARE WHEEL PANEL .		1,750.00	800.00
	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS.		1,500.00	800.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS.		90.00	60.00
	TO R&R REAR BOOT MECHANISM .		80.00	40.00
	TO R&R REAR LUGGAGE COMPARTMENT .		200.00	80.00
	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION .		80.00	50.00
	TO CHECK WIRING LAYOUT OF TAIL LAMP .		80.00	30.00
	TO R&R REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO R&R EXHAUST PIPE ASSY .		180.00	100.00
	TO DO WHEEL ALIGNMENT .	NOT NECESSARY	180.00	-
	TO CHECK FOR WATER SEEPAGE.	NOT NECESSARY	100.00	-
			4,390.00	1,960.00
GRAND TOTAL			17,007.70	7,230.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,750.00

Report Ref No. CC4/EQ118002788/Amb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.