



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

TPEQ.
JCS.

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bootlid <i>Dented</i>	1.00	1,339.00	1,339.00 685
2	Rear bootlid support garnish (LH) <i>3pc</i>	1.00	0.00	0.00 +
3	Rear bootlid support garnish (RH)	1.00	0.00	0.00 -
4	Rear bootlid lock <i>Dented</i>	1.00	167.00	167.00 —
5	Rear bootlid weather strip <i>cut</i>	1.00	84.50	84.50 —
6	Rear bootlid logo <i>3pc</i>	1.00	67.00	67.00 —
7	Rear bootlid emblem - Lancer	1.00	68.00	68.00 —
8	Rear bootlid emblem - Cycle & carriage <i>m</i>	1.00	68.00	68.00 —
9	Rear bootlid key lock <i>1pc</i>	1.00	165.00	165.00 +
10	Rear bootlid inner trim <i>2pc</i>	1.00	0.00	0.00 —
11	Rear bootlid inner trim clip <i>m</i>	10.00	5.00	50.00 30
12	Rear bootlid lamp (LH) <i>2pc</i>	1.00	182.00	182.00 2
13	Rear bootlid lamp (RH) <i>2pc</i>	1.00	182.00	182.00 2
14	Rear bumper <i>Dented</i>	1.00	1,205.00	1,205.00 741
15	Rear bumper clip <i>m</i>	10.00	5.00	50.00 30
16	Rear bumper retainer (LH) <i>3pc</i>	1.00	52.00	52.00 —
17	Rear bumper retainer (RH)	1.00	52.00	52.00 —
18	Rear bumper bracket (LH) <i>3pc</i>	1.00	82.00	82.00 +
19	Rear bumper bracket (RH)	1.00	82.00	82.00 +
20	Rear bumper reinforcement <i>Best</i>	1.00	211.20	211.20 —
21	Rear bumper towing cap <i>2pc</i>	1.00	50.00	50.00 —
22	Rear bumper reflector (LH) <i>Missing</i>	1.00	68.00	68.00 —
23	Rear bumper reflector (RH) <i>2pc</i>	1.00	68.00	68.00 —
24	Rear bumper air duct (LH) <i>1pc</i>	1.00	0.00	0.00 +

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
25	Rear bumper air duct (RH) <i>new</i>	1.00	0.00	0.00 <i>+</i>
26	Tail lamp (LH) <i>new</i>	1.00	352.00	352.00 <i>✓</i>
27	Tail lamp (RH) <i>new</i>	1.00	352.00	352.00 <i>✓</i>
28	Tail lamp clip (LH) <i>new</i>	2.00	5.00	10.00 <i>✓</i>
29	Tail lamp clip (RH) <i>new</i>	2.00	5.00	10.00 <i>✓</i>
30	Tail lamp bracket (LH) <i>new</i>	1.00	55.00	55.00 <i>+</i>
31	Tail lamp bracket (RH) <i>new</i>	1.00	55.00	55.00 <i>+</i>
32	Rear end panel <i>Disheled</i>	1.00	806.00	806.00 <i>465</i>
33	Rear end panel top garnish <i>Disheled</i>	1.00	323.00	323.00 <i>✓</i>
34	Rear end panel top garnish clip <i>new</i>	10.00	5.00	50.00 <i>15</i>
35	Rear fender (LH) <i>new</i>	1.00	850.00	850.00 <i>+</i>
36	Rear fender (RH) <i>new</i>	1.00	850.00	850.00 <i>+</i>
37	Rear fender cowl (LH) <i>new</i>	1.00	135.00	135.00 <i>+</i>
38	Rear fender cowl (RH) <i>new</i>	1.00	135.00	135.00 <i>+</i>
39	Rear fender cowl clip (LH) <i>new</i>	10.00	5.00	50.00 <i>+</i>
40	Rear fender cowl clip (RH) <i>new</i>	10.00	5.00	50.00 <i>+</i>
41	Rear fender inner trim (LH) <i>new</i>	1.00	267.00	267.00 <i>✓</i>
42	Rear fender inner trim (RH) <i>new</i>	1.00	267.00	267.00 <i>✓</i>
43	Rear fender inner trim clip (LH) <i>new</i>	10.00	5.00	50.00 <i>30</i>
44	Rear fender inner trim clip (RH) <i>new</i>	10.00	5.00	50.00 <i>30</i>
45	Rear windscreen moulding <i>new</i>	1.00	97.00	97.00 <i>+</i>
46	Spare wheel panel <i>Repair</i>	1.00	590.00	590.00 <i>+</i>
47	Spare wheel panel top board <i>new</i>	1.00	345.00	345.00 <i>+</i>
48	Spare wheel panel sponge <i>new</i>	1.00	0.00	0.00 <i>+</i>
49	Exhaust pipe <i>Best</i>	1.00	963.00	963.00 <i>485</i>

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-CVT, JMYSTCY4A8U003047
Year of Manufacture : 2007

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
50	Exhaust pipe mounting <i>mm</i>	2.00	35.00	70.00 <i>x</i>
51	Exhaust pipe gasket <i>mm</i>	1.00	68.00	68.00 <i>+</i>
52	Exhaust pipe heat shield <i>del</i>	1.00	0.00	<i>55</i> 0.00 <i>2</i>

5466.70
4920.03

Amt S\$ 11,142.70
Discount (0.00%) S\$ 0.00
Subtotal S\$ 11,142.70

Section: Special Nett Items

53	Rear bootlid sticker - asian garage <i>mm</i>	1.00	50.00	50.00 <i>40</i>
54	Rear number plate <i>Bent</i>	1.00	50.00	50.00 <i>✓</i>
55	Rear bumper reverse sensor <i>By d</i>	1.00	400.00	400.00 <i>200</i>
56	Rear end panel sealant <i>mm</i>	1.00	80.00	80.00 <i>60</i>
57	Rear fender sealant <i>2</i>	1.00	80.00	80.00 <i>+</i>
58	Rear windscreen sealant	1.00	80.00	80.00 <i>+</i>
59	Spare wheel panel sealant <i>mm</i>	1.00	80.00	80.00 <i>+</i>
60	Spare wheel panel insulator	1.00	100.00	100.00 <i>+</i>
61	Spare wheel	1.00	500.00	500.00 <i>+</i>

Amt S\$ 1,420.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,420.00

Section: Labour Items

62	To R&R accident affected areas	1.00	1,750.00	1,750.00 <i>800</i>
63	To putty & respray accident affected areas	1.00	1,500.00	1,500.00 <i>800</i>
64	To rust proof accident affected areas	1.00	90.00	90.00 <i>60</i>
65	To R&R rear boot mechanism	1.00	80.00	80.00 <i>40</i>

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS9249K
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U003047
Year of : 2007
Manufacture

Estimation No. : E18020019
DOA : 03/02/2018

No	Description	Qty	U/P	Amt
66	To R&R rear luggage compartment	1.00	200.00	200.00 80
67	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00 50
68	To check wiring layout of tail lamp	1.00	80.00	80.00 30
69	To R&R rear windscreen	1.00	150.00	150.00 +
70	To R&R exhaust pipe assy	1.00	180.00	180.00 100
71	To do wheel alignment	1.00	180.00	180.00 +
72	To check for water seepage	1.00	100.00	100.00 +

Amt S\$ 4,390.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 4,390.00

Adrian Lj
t/s 09/02/18.

07 Pags.
total: 7230.03.

t/s: 5750 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 11,142.70
Special Nett Items S\$ 1,420.00
Subtotal
Labour Items Subtotal S\$ 4,390.00
Total S\$ 16,952.70