

INS. CASE OWNER:

Stacey

CC 9, AXA 1800

VA 92, R. 1/1/18

LKK:

IDAC:

Surveyor:

RAGUL

DOI:

12/02/18

Date / Time:

12/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDF 9243C

Name of Insured:

QUEE BABY JOSEPHINE

Insured Tel No.:

HP: 9645368

Excess Sec II :\$5

D.O.A: 21/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

58M008QF (3054)

Policy No.:

VPA1 D1924205

Make / Model:

TOYOTA

Place of Accident:

GLMS RW

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLH 9690P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Auto Insure



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/2/18
VIC

SDF 9243C - X

SDF 9243C - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

26/4/2018

After call Itr to OI: 10/05/18 - JIC

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PBR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/4/2018
2:30pm

Spoke to JB (Mr Quirk) at 9645 0182. She confirmed about the accident statement informed about the TP claim and LTTM Vision statement issue. She dispute on liability, but no further evidence capable to her, if no further from LTTM. We may be settle this case on 50/50. I request keep update her the progress on liability issue.

10/05/18

Good letter to email to OI to notify TP claim.

TP LOD is not email.

17/12

50/50 email TP. (Pending confirmation)

18/12

TP agree to 50/50 settlement to settle mandate (pending TP rental inv & agreement, income proof for past 6 months & other incidental inv to justify of the claim)

31-12-18

NO CCTV CONFIRMING VISION TO BE SHARE BY 50% LIABILITY.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

RAGUL

Repair Cost:

VIP

\$5 920.00

(4 days)

Reduction:

\$424.44

% 84

FINAL SETTLEMENT

Date/Time:

Confirm with:

AGREED

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.:

NA

If NO or B 28, Ass. Lia:

Repair Cost:

\$984.40

\$5 420.20

(W/GET)

CONFIRMING BOTHWAYS

Loss of Rental (LOR):

\$5

1

days

Loss of Use (LOU):

200

\$5 100.00

(5.50 x 4

days)

Loss of Income (LOI):

\$5

15

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

31.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$360

Total:

\$5

623.20

Global Sum \$5:

620.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

620.00

Name 1:

Auto Insure Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

X 5/18

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002792/hb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-02-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDF 9243C	Veh. Inspected	SLH 9690P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date		
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto Insure Pte. Ltd.

80-1, 80-2 Woodlands Road
New Tye Industrial Estate
Singapore 737946
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6348 2788 F: 6348 0982
GST No.: 2034279896

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Case No: SJH080P

Form No: SOPS043C

Date: 9-Feb-18

ATTENTION: MOTOR CLAIMS DEPT

email: motor.claims@autoinsure.com.sg

8 Thomson way
#27-01/02 AAB Tower
Singapore 598611

Assessed Vehicle No : SJH080P
Car Make and Model : MITSUBISHI ATTRAGE 1.2 CVT
Date of Accident : 11-Jan-18
Date of Assessment : 9-Feb-18

We have carried out a physical assessment of SJH080P at our workshop Auto Insure Pte Ltd
sustained damages to the REAR RH portion of the vehicle.

A. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had
sustained damages to the REAR RH portion of the vehicle.

Please see attached schedule for details.

Remarks: Nil

Estimated Amount : 200
Adjusted Amount : \$ 8,200.00
Est. Repair Days : 4



** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated
as correct.

Disclaimer

This report is intended for the exclusive use of the person(s) to whom it is issued or the person(s) to whom the assessed vehicle is insured.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE LTD for any reliance on this report by any third party.

Job No: 310900P
 Date: 01/12/2013

S/NO	QTY	DESCRIPTIONS	ASSESSED CONVERTED	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER	\$	1,215.50
2	2	REAR BUMPER REFLECTOR	\$	380.00
3	1	REAR BUMPER SIDE RETAINER	\$	116.00
4	1	REAR END PANEL	\$	856.00
5	1	REAR FENDER RH	\$	691.80
6	1	RIM	\$	500.00
SUB TOTAL			1	3,674.30
LESS 20%			1	734.86
TOTAL AMOUNT			1	2,939.44

R
 XSL
 XSL
 XSL
 R
 R

S/NO	QTY	SPECIAL NOTE/ITEM	ACCESSED CONDITION	EST. BY WORKSHOP
1	2	REAR REVERSE SENSOR		\$ 280.00
2	1 SET	REAR BUMPER CLIPS		\$ 60.00
3	1	REAR LICENCE PLATE WITH HOLDER		\$ 75.00
4	1	REAR END PANEL SEALANT		\$ 60.00
5	1 SET	REAR FLOOR PANEL SOUND INSULATOR		\$ 120.00
6	1	REAR BUMPER TOW CAP		\$ 90.00
SUB TOTAL				\$ 785.00
TOTAL PARTS COST				\$ 3,644.44

X500
XAN
X500
XAN
XAN
XAN

Quoted: SUPPHOP

Quoted: SDF9243C

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 300.00
2	TOWING CHARGE	\$ 100.00
3	TO CONDUCT HEADLAMP FOCUS	\$ -
4	TO REMOVE/REFILL A/C CONDENSATOR & REFILL AIRCON GAS	\$ -
5	TO REMOVE/INSTALL REAR WINDSCREEN	\$ -
6	TO DIAGNOSE/ERASE FAULT MEMORY AFTER REPAIR	\$ 150.00
7	TO REMOVE / REPAIR WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONING	\$ 100.00
8	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ 100.00
9	TO REMOVE / REPAIR BUSHES, GARNISH AND ATTACHMENT PARTS	\$ 100.00
10	TO REMOVE / REPAIR REAR LUGGAGE COMPARTMENT	\$ 150.00
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 150.00
13	TO VACUUM, WAXING & CLEAN	\$ 100.00
14	TO PERFORM WATER DEBRIDE TEST ON REPAIRED PORTIONS	\$ 100.00
TOTAL BEFORE GST		\$ 3,744.44
GST 7%		\$ 262.11
TOTAL (PARTS & LABOUR)		\$ 4,006.55

300

XAN

XAN

XAN

60

XAN

XAN

450

40

40

30

920

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$4,006.55 for direct settlement with the third party insurer.

Yours Faithfully,

Jason Yeng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Rasul
Hp 92000068

4 days

4/5

12/02/18 @ 1710

Resurvey after repair

email: rasul@lkkauto.com



Auto Insure Pte. Ltd.

8th Fl, 381A Woodlands Road
New Tee Industrial Estate
Singapore (677864)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6768 7788 F: 6768 0061
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Car Ref: SLH9690P
Tour Ref: SDF9243C
Date: 9-Feb-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT
email: motor.survey@aaa.com.sg

8 Shenton way
#27-01/02 AXA Tower
Singapore 088811

Assessed Vehicle No : SLH9690P
Car Make and Model : MITSUBISHI ATTRAGE 1.2 CVT
Date of Accident : 31-Jan-18
Date of Assessment : 9-Feb-18

We have carried out a physical assessment of SLH9690P at our workshop Auto Insure Pte Ltd
sustained damages to the REAR RH portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had
sustained damages to the REAR RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : R/P
Adjusted Amount : \$ 6,100.00
Est. Repair Days : 4



** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated
as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.
No liability or responsibility whatsoever shall be held by
AUTOINSURE PTE LTD For any reliance on this report by any third party.

Our Ref: SLH9690P
Your Ref: SDF9243C

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER		\$ 1,126.50
2	2	REAR BUMPER REFLECTOR		\$ 380.00
3	1	REAR BUMPER SIDE RETAINER		\$ 118.00
4	1	REAR END PANEL		\$ 658.00
5	1	REAR FENDER RH		\$ 691.80
1	1	RIM		\$ 500.00
			SUB TOTAL	\$ 3,674.30
			LESS 20%	\$ 734.86
			TOTAL AMOUNT	\$ 2,939.44

R
X
X
X
R
R

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	2	REAR REVERSE SENSOR		\$ 280.00 X
2	1 SET	REAR BUMPER CLIPS		\$ 60.00 X
3	1	REAR LICENCE PLATE WITH HOLDER		\$ 75.00 X
4	1	REAR END PANEL SEALANT		\$ 80.00 X
5	1 SET	REAR FLOOR PANEL SOUND INSULATOR		\$ 120.00 X
6	1	REAR BUMPER TOW CAP		\$ 90.00 X
			SUB TOTAL	\$ 705.00
			TOTAL PARTS COST	\$ 3,644.44

Our Ref: SLH9690P

Your Ref: SDF9243C

S/NO	DESCRIPTION	EST. BY WORKSHOP
	LABOUR & PAINTWORK	
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 600.00 300
2	TOWING CHARGE	\$ 100.00 X
3	TO CONDUCT HEADLAMP FOCUS	\$ -
4	TO REMOVE/REFIX A/C CONDENSOR & REFILL AIRCON GAS	\$ -
5	TO REMOVE/INSTALL REAR WINDSCREEN	\$ -
6	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 150.00 X
7	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00 X
8	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ 150.00 60
9	TO REMOVE / REFIX UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	\$ -
10	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$ 150.00 X
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00 450
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 150.00 40
13	TO VACUUM, WAXING & CLEAN	\$ 100.00 40
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 100.00 30
	TOTAL BEFORE GST	\$ 5,744.44
	GST 7%	\$ 402.11
	TOTAL (PARTS & LABOUR)	\$ 6,146.55

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$6,100.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 9006068
4 days
4/3
12/02/18 @ 1710
Resurvey after repair
email: rasul@lkkauto.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/1/2020

Survey Details:

Date of loss	31-Jan-18
Date of appointment	12-Feb-18
Date of survey	12-Feb-18
Location of survey	AUTO INSURE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLH 9690P
Make and Model	MITSUBISHI ATTRAGE 1.2
Date of registration	1-Nov-16
Parf Rebate	
Market Value	\$ 50,000.00
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	6,146.55
------------------	----------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ -
Labour	\$ 920.00
Total	\$ 920.00
Lump Sum(if applicable)	\$ -

Number of days for repair	4 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 2PRS + 1SAT + 2PH =
10DAYS

Mandate:

Liability(TP)	50%	
Proposed repair cost	\$ 492.20	W/GST
Loss of use	\$ 300.00	10days x \$60
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 31.00	
Others	\$ -	
Proposed Total	\$ 823.20	

<< <MANDATE IA> - S8M008QF {ACCIDENT INVOLVING SDF 9243C (OI) & SLH 9690P (TP) ON 31/01/2018}

Type

🔗 Question

Message

LIABILITY: 50% BOLA NIL (CONFLICTING VERSION) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$823.20 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 17/01/2020

Reply

Auto Insure Pte. Ltd.



6 Marsiling Lane
Singapore (739145)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

TAX INVOICEInvoice No.: **AI-3288-2058**

Date: 10/08/2018
Terms: **30 DAYS**
Ref: C2334

BILLING DETAILS	
NAME	LION CITY RENTALS PTE LTD
VEH REG. NO.	SLH969P
ADDRESS	
ATTENTION TO	AXA INSURANCE SINGAPORE PTE LTD
TEL	
EMAIL	

S/N	DATE	CODE	DESCRIPTION	PRICE w/o GST	GST AMT	AMOUNT (\$)
1	31-Jan-18		Lump Sum Repair Cost: To supply and replace parts, labour charges for repair, panel beating, welding and respray painting.	\$920.00 \$	64.40	\$984.40

Autoinsure

Check Payment should be crossed and issued in favour of
AUTO INSURE PTE. LTD.
No Receipt will be issued.
Thank you for your patronage.

SUBTOTAL	\$920.00
ADD GST 7.00 %	\$ 64.40
TOTAL AMOUNT (\$)	\$ 984.40

This is a computerized document. No signature is required.



Re:<MANDATE IA> - S8M008QF {ACCIDENT INVOLVING SDF 9243C (OI) & SLH 9690P (TP) ON 31/01/2018}

Type

🔍 Question

Message

hi, please offer 4 days x \$50 @50% liab for loss of use.

Reply

**Auto Insure Pte. Ltd.**

6 Marsiling Lane
Singapore (739145)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2628 F: 6368 0081
GST No.: 201437389M

Our Ref: SLH9690P
Your Ref: SDF9243C
Accident Date: 31-Jan-18

WITHOUT PREJUDICE

10-Aug-18

ATTENTION: MOTOR CLAIMS DEPT

Email: motor.survey@axa.com.sg

143 Cecil Street
#01-01, GB Building
Singapore 069542

CLAIMANT: LCRF PTE LTD**ACCIDENT INVOLVING SLH9690P & SDF9243C ALONG SIM AVE JUNCTION OF GEYLANG EAST AVE 1 ON 31/01/2018.**

We are instructed by **LCRF PTE LTD** to claim damages against your insured in connection with a road accident ON involving our client's motor registration number and motor vehicle registration number driven by you or your authorised driver at the material time.

We are instructed that your negligent driving and/or management of your vehicle caused the accident. As a result of the accident, our client's vehicle was damaged and our client was put to loss and expense, particulars of which are as follows;

1) Cost of Repair (with GST) after surveyor final esti.	\$ 984.40
2) Loss of Rental (Includes loss of PRS and loss of Sun & PHs) (10 days x \$120)	\$ 1,200.00
3) LTA/GIA Search Fees	\$ 31.00
4) Other incidentals	\$ 200.00 ✕
5) Towing	\$ -
6) Loss of Income (10 days x \$200)	\$ 2,000.00 ✕
TOTAL:	\$ 4,415.40

A copy of each of the following supporting documents is enclosed:

- 1) GIA report of our Insured
- 2) Repairer's Invoice
- 3) Letter of Authorization
- 4) LTA/GIA Search Receipt

Please note that if you are insured and wish to claim under your insurance policy, you should immediately pass this letter to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within **14 days** of your receipt of this letter, failing which our client will have no alternative but to commence claims against you without further notice to you or your insurer.

Please note that if you have a counterclaim against our client arising out of accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **8 weeks** of your receipt of this letter.

For any further enquiry, kindly contact us via email to claims01@autoinsure.com.sg or call Sam at 3157 2628 directly.

Yours Faithfully,

Jason Heng
Auto Insure Pte Ltd
Claims Director

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18002792/R1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY			Date : 26-02-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDF 9243C	Veh. Inspected	SLH 9690P	
Policy No.	VPA/P1934205	Coverage (\$)	0.00	
Claim No.	S8M008QF	Excess (\$)	0.00	
Assign From		Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE 1.2	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH003475	Colour	GREY	
Odometer	103591	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	ACHILLES	5 mm	
L/H Front Tyre	185/55 R15	ACHILLES	5 mm	
R/H Rear Tyre	185/55 R15	ACHILLES	5 mm	
L/H Rear Tyre	185/55 R15	ACHILLES	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2018	Inspection Date	12/02/2018	
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 9690P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,326.50	-
1	REAR BUMPER REFLECTOR (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR BUMPER SIDE RETAINER (CONSISTENT)	SERVICEABLE	118.00	-
1	REAR END PANEL (CONSISTENT)	SERVICEABLE	658.00	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	691.80	-
1	RIM (CONSISTENT)	TO REPAIR SEE LABOUR	500.00	-
	LESS 20% DISCOUNT		-734.86	-
			2,939.44	-
SPECIAL NETT ITEMS				
2	REAR REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	280.00	-
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	SERVICEABLE	75.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SET REAR FLOOR PANEL SOUND INSULATOR (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR BUMPER TOW CAP (SN) (CONSISTENT)	NOT NECESSARY	90.00	-
			705.00	-
LABOUR				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR FENDER RH AND RIM .		600.00	300.00
	TOWING CHARGE.	NOT NECESSARY	100.00	-
	TO CONDUCT HEADLAMP FOCUS. (NPA)	NOT NECESSARY	-	-
	TO REMOVE /REFIX A/C CONDENSOR & REFILL AIRCON GAS. (NPA)	NOT NECESSARY	-	-
	TO REMOVE/INSTALL REAR WINDSCREEN. (NPA)	NOT NECESSARY	-	-
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	NOT NECESSARY	150.00	-

Report Ref No. CC4/ASM18002792/R1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	✓ 100.00	-
	TO REMOVE/INSTALL REAR REVERSE SENSOR .		✓ 150.00	60.00
	TO REMOVE/REFIX UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS.(NPA)	NOT NECESSARY	✓ -	-
	TO REMOVE/REFIX REAR LUGGAGE COMPARTMENT.	NOT NECESSARY	✓ 150.00	-
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		✓ 600.00	450.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		✓ 150.00	40.00
	TO VACUUM, WAXING & CLEAN.		✓ 100.00	40.00
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.		✓ 100.00	30.00
			2,200.00	920.00
GRAND TOTAL			5,844.44	920.00
RECOMMENDED COST OF REPAIRS				920.00

Report Ref No. QC4/ASM18002792/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SIM0001QF

Reference

CC4/ASM18002792/R1ga3q2

Loss Date

31 January 2018

Report Date

9 Feb 2018 3:20:43 PM

Request Date

16 April 2018

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLH969OP

Make

TPVO MITSUBISHI

Model

ATTRAGE-1.2 (A)

Service Address

Primary Contact/Insured

MRS JOSEPHINE TANG QUEK BAOY JOSEPHINE
BLK 817 TAMPINES STREET B1, #02-576, 520817, Singapore
63249107

Claim Handler

TAN Jas
6548804844
jas.tan@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Approve Invoice

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type			Document SubType			
Upload Documents						
NAME		TYPE	SUB-TYPE	AUTHOR		DATE UPLOADED
LKXInvoice1 (4).pdf		Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)		3 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK inspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 LKKdisputemmt1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 GJA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 LCD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 MANDATE IA DD 17012020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 TP FINAL EST LET.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 LKK INSPECTION PHOTOS.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2018
 LKK REINSPECTION PHOTOS.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2018
 LETTER TO OI.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2018
 Email to OI dd 100818.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP AUTO INSURE-ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LK AUTO CONSULTANTS PTE LTD (TP)	13 February 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LK AUTO CONSULTANTS PTE LTD (TP)	13 February 2018
 GIA SDF9243C INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	9 February 2018
 TP AUTO INSURE-EMAIL ATTACHED ESTIMATE & GIA.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	9 February 2018