ASS, REC, BY: REF: CS ASM 160	00800/7/903 CZ instruction:
ASSIGNME ASSIGNME	NT (Office)
From (Person): Vonne Arrey of Ax	A Date/Time: 12/00/2018
Estimated Cost:	Bill to:
OD) TP + WS+TP RES / OD RES / EVA / INV / MV 7 CS	3
To Inspect Vehicle No: SIV 8 262	
at Workshop m/s Kah Motor	Tel: 90721769 /6514 5766 Vincen
of 255 Alexandru R	d
Policy No:	Claim No: \$8 M 00 8 S 4
Sum Insured:	Excess: \$ 200.00
Make of Veh: (Client's Record)	D.O.A 9/2/18
CA/ REV / REP. / REV 24 HRS	0 - 0
Date/Time: 3.30m-Q toloke	H.O.D. Endorsement:
Date/Time: 3.32pm 2 2 8 Person Contacted:	Sin HAI Vehicle (IN) OUT
Date/Time Action/Instruction () Estimate	
12/-11/0 21/82627 - NBA INC/301	3530/y D.O.A: 25/7/13
13/1/8@ 3-40 pr vevised to grome	Are the Smart Class
73 7/18 @ 4 my confirmed with NO Si	in that final fig 107756-34, 7 days.
(Red \$8065.17, 51%)	110 110 110 110 110 110 110 110 110 110
11/10/8@6-5300 Grane And and to	Testand or a second
* without a s PB	subnut our worst as repairer charing payment.
- 10000 0000	

THE RESERVE TO SERVE THE PROPERTY OF THE PERSON NAMED IN COLUMN TO SERVE THE PERSON NAMED IN COLUMN TO



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation	Internationale Des Experts En Autor	mobile		
AXA	A INSURANCE PT	E LTD	Ref: CS/AXA18002	Ref : CS/AXA18002800/T1qd3		
	HENTON WAY #24 A TOWERSINGAP		Date: 12-02-2018 Code: AXA2			
1.		Policy	Particulars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	SJV 8262Z		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	S88S4M00	Excess (\$)	200.00		
	Assign From	YVONNE ANG	Assign Date	12/02/2018		
2.		Vehic	cle Particulars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	=	Steering			
	Brakes		Modification			
	General					
3.			Conditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		De la Companya de la	escription of Damages			
5.		11/1/10/10/10/10/10	General Information			
	Accident Date	09/02/2018	Inspection Date	12/02/2018		
	Survey held at	KAH MOTOR CO SDN				
		NO. 255 ALEXANDRA I SINGAPORE 159937				
5a.	X NEW YORK		Remarks			
	A)THE MARKET V	ALUE IS S\$(ES CE TO YOUR INSTRUCT	T. AVERAGE)			

LKK AUTO CONSULTANTS PTE LTD (OD) -

Menu



Service Request Details

Claim

S8M008S4

Reference

None 🧳

Loss Date

February 9, 2018

Request Date

February 12, 2018

Due Date

February 20, 2018

Vendor Name


LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize



Vehicle Information

Incident Vehicle Registration # SJV8262Z

Make

HONDA

Menu

Service Address

255 Alexandra Road, , , 159937

Primary Contact/Insured

LEE YOW SHING BLK 181A BOON LAY DRIVE, #11-608, 641181, Singapore 96457780

Claim Handler

ANG Yvonne

6568804461 yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 200

Messages Invoices	History Documents Assessment Metrics Notes
Document Type	Document SubType
+ Upload Documents	
NAME	■ EMAIL RECEIVED FROM WORKSHOP INCLUIDING ESTIAMTE & SJV8262Z INSD GIA.msg
TYPE	Letters and Correspondence
SUB-TYPE	Workshop
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	February 12, 2018

LKK AUTO CONSULTANTS PTE LTD (OD) ▼

Menu



URGENT ASSESSMENT

Type

Q Question

Message

KAH MOTOR IS CHASING FOR PAYMENT, PLEASE LET US HAVE FINAL ASSSESSMENT.

Reply

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 23 July 2018 4:22 PM

To:

'Ng Sin Hai'

Subject:

RE: Submission Pre-Invoice for vehicle SJV8262Z

Dear Sin Hai,

WITHOUT PREJUDISE

Confirm final fig \$7,756.34 before excess \$200.00 & GST and 7 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Thursday, 31 May 2018 5:54 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: FW: Submission Pre-Invoice for vehicle SJV8262Z

Dear Shiau Chan,

Your surveyor has not finalise with me.

Thank you and have a nice day, ⊚

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Menu



SUPPLEMENTARY LIST OF VEHICLE SJV 8262Z UPLAODED

Type

Q Question

Message

Dear Yvonne, we have received supplementary of \$337,79 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S8M008S4

Date: 13th February 2018

Our Ref: CS/ASM18002800/T1qd3

The Motor Claims Department AXA Insurance Singapore Pte L td

Attn: Yvonne

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJV 8262Z .

We thank you for the instruction on 12/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/02/2018 (4pm) at the premises of M/s KAH MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	15,483.72	
Revised Estimate Amount	: <u>S</u> \$	8,138.45	
"Check" Items Amount	: <u>S</u> \$	3,565.27	
Total	: S\$	11,703.72	
Market Value	: <u>S</u> \$	30,000.00	
LTA Reimbursement Value	: S\$	14,229.00	
Nett Value	: <u>S</u> \$	15,771.00	

Description of Damage:

<u>The vehicle sustained damages at the front portion.</u>

nearside front offside

Comments/ Present Status:

<u>Damages consistent.</u>

<u>Recommend days of repair: 7 days</u>

We have authorised the repairs.

Yours faithfully

Taufikh Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
700	
Owner ID:	9668J
Vehicle Details	
Vehicle No.:	SJV8262Z
Vehicle to be Exported:	No
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3L AT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L13Z11021757
Chassis No.:	JHMGE68509S221755
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$18,638.00
Original Registration Date:	10 Feb 2010
First Registration Date:	10 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$18,638.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2020
PARF Rebate Amount:	\$10,250.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$3,979.00
Total Rebate Amount:	\$14,229.00

The information contained herein is correct as at 13 Feb 2018

MKM118020646 / Kah Motor Co Sdn Bhd - Ubi ENTRY DATE & TIME: 10/02/2018 14:54 SUBMITTED BY: NG SIN HAI

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	10/02/2018 14:54	
Date Of Accident	09/02/2018 17:20	
Exact Location Of Accident	AYE TOWARDS TUAS	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

,		
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJV8262Z	
Insured/Policyholder		
Name Of Registered Owner	LEE YOW SHING	
NRIC No	S6979668J	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96457780	
Alternative Phone No	OFFICE-96457780	
Vehicle Particulars		

 Manufacturer
 HONDA

 Model
 JAZZ-1.3 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VPA/P0902240

Cover Note Number

Driver

Name of Driver HOW SI SI JACQUELINE

 NRIC No
 \$8629430C

 Date Of Birth
 02/10/1986

 Occupation
 INDOOR

 Date Of Driving Pass
 19/09/2009

Driving Experience 8 YEARS AND 4 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96457780

Fax Number

Contact Number

EMail Address NOEMAIL

Address

SINGAPORE

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDD6648Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle No	SKET	CH PLAN	Assert D
IMPORTANT NOTICE			
1. Bease report correctly the	details of the accident to speed up to	ne clains process.	
	ed by the Policyholder and/or the		
		sible. Any warul misrepresentation or v	vithholding of material facts may
allow insurance companies to			A CONTRACT OF A
 The issue and acceptance of companies. 	if this Form by insurance companies	is not an admission of potcy liability on t	he part of the insurance
5. Any false reporting may	be referred to the Police for love	stigation.	
		Management Centre established by the or a fee be made available upon applicat	
report being made available afc	resaid,	ent to the archiving of this report at the c	centre and to copies of the
	onal Data Protection Act (PDPA)		
Funderstand, acknowledge, ag			
and/or process my personal da possessed by my insurer (colla who have insured vehicle(s) in collectively referred to as the "I government agency/authority (s	ta/personal information set cut in this actively the "Personal Information" volved in this accident (all insurer(s) nsurers"), the Insurers' law yers/lay such as the police), for the purpose(s	on of Singapore ("GIA") may/are permits [form] and any other personal informed) and disclose and transfer such Person who have incured vehicle(s) involved in v (tims, the Monetary Authority of Sings s) of : settlement of the claims and any necess	ion provided by me or nal information to all insurer(s) in this accident shall be apore and any relevant
the claims;			
(ii) investigating the accident an			
(iv) administering my claims (incidisclosure of cortain personal d		any enquiries by me; statements, invoices, reports or notice of the same as well as on the external o	
packages); and/or (v) complying with applicable by	w in administering, processing, handl	ing and/or dealing with my claims	
(collectively the "Purposes")	e at our what any, in occorring, the total	ing entrol dealing whiting carrie.	
	ed vehicle(s) involved in this accider	nt and the Insurers' law yers/law firms, i	may/are permitted to collect.
use, disclose and/or process m	Personal Information for one or mor	e of the above Purposes; and	The second second
		rers and/or GIA to their third party serving apore, for one or more of the above P	
100			
Sto.		W	M1
Policyholder's Signature / Date &	Driver's Signature (# driver is n	et the policyholder) / Date Witness	ed by Reporting Centre
Time	& Time	Personn	
Sketch Plan		and the second s	
		86 XA	

Vehicle No SJV82				Annex E
	AYE (Lane 1) whe	n I could n	ot brake h	ny car
itence, I collided injured at the p yehicles	d with the car in oint in time. No pa	senger wer u	drivers were	e not in both
You had been advised by the wo	rkshop that in the			
ent that you wish to claim again (OD claim), there is a <u>Fourteer</u> whereby the claim must be stipulated timeframe from the c	(14) days clause nade within the			
eclaration We declare the foregoing particular.	are true in every respect.			
olicyholder's Signature / Date 8	Driver's Signature (If driver is not t & Time	he policyholder) / Date	Wenessed by Reporti	ng Centre





REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8629430C






HOW SI SI, JACQUELINE

CHINESE Date of birth 02-10-1986 Country/Place of birth SINGAPORE

S8629430C







14-09-2017

APT BLK 181A BOON LAY DRIVE #11-608 SINGAPORE 641181

AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 ■ Road Transport Act. 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.

: VPA/P0902240

Account No.: 03365

Coverage

: Comprehensive

Sum Insured

: Market Value At The Time Of Loss

Name of Policy Holder

: LEE YOW SHING

Vehicle Registration No. : SJV8262Z

. HEE TOW BRING

Period of Insurance

: From 10/02/2017 To 09/02/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner

(b) Any other person who is driving on the Policyholder's order or with his permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess

: SGD 400.00

	DITTOUR	
Al	DITIONAL EXCESS APPLICABLE FOR AN	Y AUTHORISED DRIVERS
Age of Driver	Driving Experience Less than 1 year	Driving Experience More than 1 year
Below 22	Own Damage Excess + S\$4,000	Own Damage Excess + S\$4,000
22 to below 27	Own Damage Excess + S\$4,000	Own Damage Excess + S\$2,500
27 to below 70	Own Damage Excess + S\$2,500	Own Damage Excess
70 and above	Own Damage Excess + S\$2,500	Own Damage Excess + S\$2,500

^{*} Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

N.B :

Your authorised workshop is Kah Motor Co Sdn Bhd.

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - WINNER05 on 20/01/2017

IMPORTANT :

Insurance are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.



GST Reg No.: M200050223

Page

1

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: AXA INSURANCE S'PORE PTE LTD Customer

> 8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE 068811

Registration No : SJV8262Z

Chassis No : JHMGE68509S221755

Model

: JAZZ 1.3 AT 09M W/O ALLOYWHEEL

Owner's Name

: LEE YOW SHING

Ins Policy No.

33100-TF0-T01

Date of Accident : 9/2/2018 Document No.

Date

: SQT18000639

: 10. Feb 2018

Customer No. : WA006

Svc Advisor

: L13Z11021757

Engine No Date | Time

: 10. Feb 2018 9:29:50 AM

Surveyor Name

Survey Date

Authorisation Date

0% GST Amount Amount Amount incld GST Item Qty Unit Price Disc % Description

OWN DAMAGE CLAIMS-J/NO:

POLICY/CLAIMS NO:VPA/P0902240

OWNER:LEE YOW SHING ACC DATE:09/02/2018

SURVEYED BY: DATE:12/02/2018 AUTHORIZED ON:

REF NO:

HEADLIGHT R

BO-NUM-COMP-OPC- L	NUMBER PLATE WITH CASING-OPC-L	<i>bt</i> 1	45.00		45.00 3	.15	48.15
60400-TF0-G01ZZ	BULKHEAD	be- 1	388.10	35	252.26 17	.66	269.92
60100-TF0-306ZZ	HOOD COMP	6t~ 1	468.00	35	304.20 21	.29	325.49
60120-TF0-G00ZZ	HINGE R HOOD	W~ ₹1	31.50	35	20.47 1	.43	21.90 Pn
60170-TF0-G00ZZ	HINGE L HOOD	1 1 × 1	31.50	35	20.47 1	.43	21.90 gm
74141-TF0-000	INSULATORHOOD	der	34.40	35	22.36 / 1	.57	23.93
74120-TF0-G11	LOCK ASSY HOOD	ht-1	43.60	35	28.34 1	.98	30.32
74142-TF0-000	RUBBER R HOOD	ne 1	4.10	35	2.66 0	.19	2.85
74192-TF0-000	RUBBER L HOOD	ne1-1	4.10	35	2.66/ 0	.19	2.85
80110-TF0-013	CONDENSER ASSY	bt/1	775.20	35	503.88 / 35	.27	539.15
38611-RBB-003	FANCOOLING	any ? 1	49.50	35	32.17/ 2	.25	34.42
38615-RB1-J51	SHROUD COMP	ova /? 1	73.70	35	47.90 3	.35	51.25
38616-RB0-003	MOTORCOOLING FAN	di>/? 1	189.40	35	123.11 8	.62	131.73
80341-TF0-003	PIPE COMPRECEIVER	X ('? 1	96.80	35	62.92 4	.40	67.32
80315-TF0-003	HOSE COMPDISCHARGE	Wy 7 7 1	169.60	35	110.24 7	.72	117.96
80311-TF0-003	HOSE COMPSUCTION	771	75.50	35	49.07 3	.43	52.50
19010-RB1-J51	RADIATOR COMP	CMV1	1405.10	35	913.31/ 63	.93	977.24
19015-RB0-004	SHROUD COMP	04 2,1	89.30	35	58.04 4	.06	62.10
19020-RB0-004	FAN COOLING	M 2 1	55.70	35	36.20 2	.53	38.73
19030-RB0-004	MOTOR COOLING FAN	NN 7 1	314.90	35	204.68 14	.33	219.01

W/1

335.00

35

217.75 / 15.24

232.99



QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sq

For 24-hours Roadside Assistance, Call 98203838

Customer

: AXA INSURANCE S'PORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE

068811

Registration No

: SJV8262Z

Chassis No

: JHMGE68509S221755

Model

: JAZZ 1.3 AT 09M W/O ALLOYWHEEL : LEE YOW SHING

Owner's Name

Ins Policy No.

Document No.

: SQT18000639

Page

2

Date

: 10. Feb 2018

: WA006

Customer No. Svc Advisor

Engine No

: L13Z11021757

Date | Time

: 10. Feb 2018 9:29:50 AM

Surveyor Name

Survey Date

Authorisation Date

Date of Accident : 9/2/2018

Item	Description	Qty	Unit Price	Disc %	10.7	% GST Amount	Amount incld GST
33150-TF0-T01	HEADLIGHT L	Cra 1	335.00	35	217.75/	15.24	232.99
08CLA-P9911LK8	COOLANTANTI-FREEZE	we/6	23.20	35	90.48	6.33	96.81
71121-TF0-003	BASE FR GRILLE	cutor	124.80	35	81.12	5.68	86.80
75700-TF0-000	EMBLEM (H)	nei/1	22.90	35	14.88	1.04	15.92
90301-ST0-003	NUTPUSH 3MM	re/2	1.90	35	2.47	0.17	2.64
04711-TF0-G00ZZ	FACEFR BUMPER	de 1	548.00	35377	356.20	24.93	381.13
71103-TF0-003	GRILLEFR BUMPER LOWER	der 1	99.70	35	64.80	4.54	69.34
71104-TF0-000ZA	COVERFR.TOWING HOOK	de 1	15.50	35	10.07/	0.70	10.77
71130-TF0-000ZZ	BEAM COMPFR BUMPER	h+/1	242.00	35	157.30	11.01	168.31
71140-TF0-000	BEAMR FR BUMPER COPPER	nu 1	27.50	35	17.87/	1.25	19.12
71190-TF0-000	BEAML FR BUMPER COPPER	ne 1	27.50	35	17.87	1.25	19.12
71193-TF0-003	SPACERR FR BUMPER SIDE	au/1	11.50	35	7.47/	0.52	7.99
71198-TF0-003	SPACERL FR BUMPER SIDE	nu 1	11.50	35	7.47	0.52	7.99
91505-S9A-003	CLIP ABUMPER	vel 8	3.90	35	20.28	1.42	21.70
				Sum Item	4123.72	288.62	4,412.34
BOSUN	SUNDRIES	1	50.00 20		50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00		100.00	7.00	107.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	. 1	180.00		180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FIT	1.50	230.00	184	230.00	16.10	246.10
BKBH12B	CUT OFF & RENEW BULKHEAD FR R HOUSING	OOMI . I		00/1440	4000.00	280.00	4280.00
BP01R	SPRAY PAINT ON REPAIRED/REPLACED AREAS \$350)	.(7PX 1	4000.00 2	450,196	4000.00	280.00	4280.00
BME00D	REMOVE & INSTALL ENGINE COMPARTMENT &	OTHERS1	2800.00 7	1350.7	2800.00	196.00	2996.00
			S	um Labor	11360.00	795.20	12,155.20
1							
Survey By	Tought 97495749.						
Date & Time	12/2/8 @ 1630 Fdays		Tota	al Amount	15,483.72	1,083.82	16,567.54

\$200

Total (Inclusive of GST)

16,567.54

Status

Excess

Printed on 10/2/2018 3:40:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

15821.51



QUOTATION

GST Reg No.: M200050223

Page

3

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer

: AXA INSURANCE S'PORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE

068811

Registration No

: SJV8262Z

Chassis No Model

: JHMGE68509S221755

Owner's Name

Ins Policy No. Date of Accident

: JAZZ 1.3 AT 09M W/O ALLOYWHEEL

: LEE YOW SHING

: 9/2/2018

Description

Document No.

: SQT18000639

Date

: 10. Feb 2018

: WA006

Customer No.

Svc Advisor **Engine No**

Unit Price Disc %

: L13Z11021757

: 10. Feb 2018 9:29:50 AM

Date | Time **Surveyor Name**

Survey Date

Authorisation Date

0% GST

Amount

Amount Amount incld GST

Signature



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

: AXA INSURANCE S'PORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Company Ref. No.: S60FC1380G

QUOTATION

GST Reg No.: M200050223

Document No.

: SQT18000777

Page

8 SHENTON WAY

Customer No.

: 22. Feb 2018

#27-01 AXA TOWER 068811

Svc Advisor

: WA006

SINGAPORE

Date

: L13Z11021757

Registration No Chassis No

: SJV8262Z

Engine No

Model

Customer

: JHMGE68509S221755 : JAZZ 1.3 AT 09M W/O ALLOYWHEEL Date | Time Surveyor Name : 22. Feb 2018 3:18:16 PM

Owner's Name

Date of Accident

: LEE YOW SHING

Survey Date

Ins Policy No.

Authorisation Date

0% GST

Amount

Amount incld GST Amount Qty Unit Price Disc % Description Item OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: OWNER:

ACC DATE:

SURVEYED BY:

DATE:

AUTHORIZED ON:

REF NO:

SUPPLEMENTARY

PANEL R FR FENDER **TANKWASHER**

GARNISH ASSYR FR CORNER

CLIP ABUMPER

HOLDERROD

411.30 58.40 39.90

3

3.20

2.30

35 267.34 35 37.96 35 35

2.66 de 40.62 (A) 1.82 Cra 27.75 (h) 25.93 0.15 Nec 2.23 Uh 2.08

35 Sum Item

Total Amount

70.45 337-79

337.79

70.45

4.48

75.39 4.94 361.44 23.65

0.31 nec 4.79 (m)

Date & Time

76841-TF0-G01

75490-TF0-J00

90672-SCC-003

90682-SEA-003

Excess

Survey By

Status Signature Total (Inclusive of GST)

73.65 4.94

75.39 75.39 361.44

361.44

286.05 4 64



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

21.40

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: Chassis No: WA006 / AXA INSURANCE

JHMGE68509S221755

License No:

SJV8262Z

Mileage: **Engine No:**

BOSUN

189715

L13Z11021757

Document No:

SVO18009210

Printed By:

SHNG

Order Date:

12. February 2018

Order Time:

4:50:04 PM

Service Advisor:

NG SIN HAI

60100-TF0-306ZZ HOOD COMP 1 468.00 74141-TF0-000 INSULATORHOOD 1 34.40 74120-TF0-G11 LOCK ASSY HOOD 1 43.60 74142-TF0-000 RUBBER R HOOD 1 4.10 74192-TF0-000 RUBBER L HOOD 1 4.10 80110-TF0-013 CONDENSER ASSY 1 775.20 38611-RB8-003 FANCOOLING 1 49.50 38616-RB1-J51 SHROUD COMP 1 73.70 38616-RB0-003 MOTORCOOLING FAN 1 189.40 19010-RB1-J51 RADIATOR COMP 1 1,405.10 33100-TF0-T01 HEADLIGHT R 1 335.00 33150-TF0-T01 HEADLIGHT L 1 335.00 302LA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 77570-TF0-001 EMBLEM (H) 1 22.90 90301-ST0-003 NUTPUSH 3MM 2 1.90 971103-TF0-003 GRILLEFR BUMPER LOWER 1 503.20 771101-TF0-G00ZG FACEFR BUMP	C% AMOUNT	7% GST Amount	Amount incld GST
OWNER:LEE YOW SHING ACC DATE:09/02/2018 SURVEYED BY:TAUFIKH DATE:12/02/2018 AUTHORIZED ON: REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCES SUM EXCES BO-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30100-TF0-306ZZ HOOD COMP 1 488.00 74140-TF0-000 INSULATORHOOD 1 4.10 74141-TF0-000 RUBBER R HOOD 1 4.10 74142-TF0-000 RUBBER R HOOD 1 4.10 74192-TF0-001 RUBBER R HOOD 1 4.10 74192-TF0-001 RUBBER R HOOD 1 4.10 88616-RB1-J51 SHROUD COMP 1 73.70 88616-RB0-003 MOTORCOOLING ROTORHOUS HARD ROTORHOOD ROTORHOOD ROTORHOUS HARD ROTORHOOD ROTORHO			
ACC DATE:09/02/2018 SURVEYED BY:TAUFIKH DATE:12/02/2018 AUTHORIZED ON: REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCES S			
SURVEYED BY:TAUFIKH DATE:12/02/2018 AUTHORIZED ON: REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM			
DATE:12/02/2018 AUTHORIZED ON: REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCES SO.NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 80400-TF0-G01ZZ BULKHEAD 1 388.10 80400-TF0-G01ZZ BULKHEAD 1 388.10 80400-TF0-G01ZZ HOOD COMP 1 488.00 14141-TF0-000 INSULATORHOOD 1 34.40 14120-TF0-G11 LOCK ASSY HOOD 1 4.10 14192-TF0-000 RUBBER R HOOD 1 4.10 14192-TF0-000 RUBBER R HOOD 1 4.10 1010-TF0-013 CONDENSER ASSY 1 775.20 8661-RB0-003 FANCOOLING 8616-RB0-003 MOTORCOOLING FAN 1 189.40 9010-RB1-J51 RADIATOR COMP 1 73.70 8616-RB0-004 SHROUD COMP 1 1,405.10 9015-RB1-J51 RADIATOR COMP 1 1,405.10 9015-RB1-J61 ROTIFO-T01 HEADLIGHT R 1 335.00 3150-TF0-T01 HEADLIGHT R 1 335.00 3150-TF0-T01 HEADLIGHT L 1 335.00 8612-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 13031-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1104-TF0-000ZA COVERR-TOWING HOOK 1 15.50 11190-TF0-000 BEAM FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAM FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAM FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACER FR BUMPER SIDE 1 11.50 1193-TF0-003 CLIP ABUMPER 8 3.90 1211-TF0-G00ZZ PANEL FR FENDER 1 11.50 158-40 159-0-0-10 169-0-0-10 1644-TF0-G00Z PANEL FR FENDER 1 11.50 158-40 159-0-0-10 1649-0-TF0-G01 1 ANKWASHER 1 58.40 159-0-0-10 159-0-			
AUTHORIZED ON: REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCES SO-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 1000-TF0-306ZZ HOOD COMP 1 488.00 14141-TF0-000 INSULATORHOOD 1 34.40 1412-TF0-001 RUBBER R HOOD 1 4.10 14192-TF0-001 RUBBER R HOOD 1 4.10 14192-TF0-001 RUBBER L HOOD 1 4.10 14192-TF0-003 RODENSER ASSY 1 775.20 18611-RBB-003 FANCOOLING 1 49.50 18615-RB1-J51 SHROUD COMP 1 73.70 18616-RB0-003 MOTORCOOLING FAN 1 189.40 19010-RB1-J51 RADIATOR COMP 1 1,405.10 19015-RB0-004 SHROUD COMP 1 1,405.10 13150-TF0-T01 HEADLIGHT R 1 335.00 13150-TF0-003 BASE F GRILLE 1 124.80 1300-TF0-000 EMBLEM (H) 1 22.90 1000-TF0-000 EMBLEM (H) 1 22.90 1101-TF0-0003 GRILLEFR BUMPER LOWER 1 99.70 11101-TF0-0002 BEAM CMPF BUMPER 1 503.20 11104-TF0-000 BEAM FR BUMPER COPPER 1 27.50 1199-TF0-000 SPACER FR BUMPER COPPER 1 27.50 1199-TF0-000 SPACER FR BUMPER COPPER 1 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R F FENDER 1 11.50 15490-TF0-G00ZZ PANEL R F FENDER 1 58.40 15490-TF0-G01 TANKWASHER 1 58.40 15490-TF0-G01 TANKWASHER 1 58.40 15490-TF0-G01 TANKWASHER 1 58.40			
REF NO: ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCESS SO-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUM EXCES 30-NUM-COMP-L NUMBER PLATE WITH CASING-L(N) 1 45.00 SUB-EXCES SUM-EXCES			
ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS SUM EXCES SUM EXCES			
### EXTERNAL LABOUR SALES - INS. EXCESS ### EXCES ### EXCESS ### EXCES ### EXCESS ### EXCES #			
### EXCESS			
SUM EXCES 1	-200.00	-14.00	-214.00
NUMBER PLATE WITH CASING-L(N) 1 45.00			
BULKHEAD 1 388.10 1 468.00 1 468.00 1 468.00 1 468.00 1 468.00 1 468.00 1 410-TFO-G011 LOCK ASSY HOOD 1 43.60 1 410-TFO-G011 LOCK ASSY HOOD 1 4.10 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 1 4.10 4.10 1 4.10		1 11.00	
1	45.00		
1	35 252.26 35 304.20		
A4120-TF0-G11			
1	35 22.36 35 28.34		
74192-TF0-000 RUBBER L HOOD 1 4.10 80110-TF0-013 CONDENSER ASSY 1 775.20 88611-RBB-003 FANCOOLING 1 49.50 88615-RB1-J51 SHROUD COMP 1 73.70 88616-RB0-003 MOTORCOOLING FAN 1 189.40 99010-RB1-J51 RADIATOR COMP 1 1,405.10 99015-RB0-004 SHROUD COMP 1 89.30 83100-TF0-T01 HEADLIGHT R 1 335.00 83150-TF0-T01 HEADLIGHT L 1 335.00 86CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 8121-TF0-003 BASE FR GRILLE 1 124.80 85700-TF0-000 EMBLEM (H) 1 22.90 80301-ST0-003 NUTPUSH 3MM 2 1.90 81103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 81101-TF0-G00ZG FACEFR BUMPER 1 503.20 81104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 81190-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 81193-TF0-003 SPA	35 26.54		
80110-TF0-013 CONDENSER ASSY 1 775.20 88611-RBB-003 FANCOOLING 1 49.50 88615-RB1-J51 SHROUD COMP 1 73.70 88616-RB0-003 MOTORCOOLING FAN 1 189.40 99010-RB1-J51 RADIATOR COMP 1 1,405.10 99015-RB0-004 SHROUD COMP 1 89.30 83100-TF0-T01 HEADLIGHT R 1 335.00 83150-TF0-T01 HEADLIGHT L 1 335.00 86CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 8121-TF0-003 BASE FR GRILLE 1 124.80 85700-TF0-000 EMBLEM (H) 1 22.90 80301-ST0-003 NUTPUSH 3MM 2 1.90 80103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 80110-TF0-0003 GRILLEFR BUMPER HOWER 1 503.20 80110-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 80110-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 80110-TF0-000 BEAML FR BUMPER SIDE 1 11.50 801193-TF0-003 <td></td> <td></td> <td></td>			
### ### ### ### ### ### ### ### ### ##			
8615-RB1-J51 SHROUD COMP 1 73.70 8616-RB0-003 MOTORCOOLING FAN 1 189.40 9010-RB1-J51 RADIATOR COMP 1 1,405.10 9015-RB0-004 SHROUD COMP 1 89.30 3100-TF0-T01 HEADLIGHT R 1 335.00 3150-TF0-T01 HEADLIGHT L 1 335.00 3150-TF0-T01 HEADLIGHT L 1 335.00 36CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G002G FACEFR BUMPER 1 503.20 1104-TF0-000Z FACEFR BUMPER 1 242.00 1130-TF0-000Z BEAM COMPFR BUMPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER COPPER 1 27.50 1198-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-G003 SPACER			
8616-RB0-003 MOTORCOOLING FAN 1 189.40 9010-RB1-J51 RADIATOR COMP 1 1,405.10 9015-RB0-004 SHROUD COMP 1 89.30 33100-TF0-T01 HEADLIGHT R 1 335.00 335-00 HEADLIGHT L 1 335.00 88CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAML FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G001			
9010-RB1-J51 RADIATOR COMP 1 1,405.10 9015-RB0-004 SHROUD COMP 1 89.30 3100-TF0-T01 HEADLIGHT R 1 335.00 3150-TF0-T01 HEADLIGHT L 1 335.00 8CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000Z BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1199-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1198-TF0-003 CLIP ABUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER SIDE 1 11.50 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90			Control Control
9015-RB0-004 SHROUD COMP 1 89.30 3100-TF0-T01 HEADLIGHT R 1 335.00 3150-TF0-T01 HEADLIGHT L 1 335.00 8CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1198-TF0-003 CLIP ABUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER SIDE 1 11.50 0211-TF0-G00ZZ PANEL R FR FENDER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 123.11		
3100-TF0-T01	35 913.31		
335.00 3	35 58.04		
86CLA-P9911LK8 COOLANTANTI-FREEZE 6 23.20 1121-TF0-003 BASE FR GRILLE 1 124.80 5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 217.75		
### 124.80 #### 124.80 ####################################	35 217.75		
5700-TF0-000 EMBLEM (H) 1 22.90 0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 90.48		
0301-ST0-003 NUTPUSH 3MM 2 1.90 1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 81.12		86.80 15.92
1103-TF0-003 GRILLEFR BUMPER LOWER 1 99.70 1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 14.88		2.64
1101-TF0-G00ZG FACEFR BUMPER 1 503.20 1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 2.47		
1104-TF0-000ZA COVERFR.TOWING HOOK 1 15.50 1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 1505-S9A-003 CLIP ABUMPER 8 3.90 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 6841-TF0-G01 TANKWASHER 1 58.40 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 64.80		69.34
1130-TF0-000ZZ BEAM COMPFR BUMPER 1 242.00 3 1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 3 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 3 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 3 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 3 1505-S9A-003 CLIP ABUMPER 8 3.90 3 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 327.08		
1140-TF0-000 BEAMR FR BUMPER COPPER 1 27.50 3 1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 3 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 3 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 3 1505-S9A-003 CLIP ABUMPER 8 3.90 3 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 10.07		10.77 168.31
1190-TF0-000 BEAML FR BUMPER COPPER 1 27.50 3 1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 3 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 3 1505-S9A-003 CLIP ABUMPER 8 3.90 3 10211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 16841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 157.30		19.12
1193-TF0-003 SPACERR FR BUMPER SIDE 1 11.50 3 1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 3 1505-S9A-003 CLIP ABUMPER 8 3.90 3 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 17.87		19.12
1198-TF0-003 SPACERL FR BUMPER SIDE 1 11.50 3 1505-S9A-003 CLIP ABUMPER 8 3.90 3 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 17.87		7.99
1505-S9A-003 CLIP ABUMPER 8 3.90 3 0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 7.47		
0211-TF0-G00ZZ PANEL R FR FENDER 1 411.30 3 6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 7.47		21.70
6841-TF0-G01 TANKWASHER 1 58.40 3 5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90 3	35 20.28		btv 286.05
5490-TF0-J00 GARNISH ASSYR FR CORNER 1 39.90	35 267.34 35 37.96		40.62
PROTECTION AND ADMINISTRATION ADMINISTRATION ADMINISTRATION AND ADMINI	35 37.96 35 25.93		27.75
00/2-3CC-003 HOLDERROD 1 3.20 3	35 25.93 35 2.08		2.23
0682-SEA-003 CLIP ABUMPER 3 2.30 3	35 2.08 35 4.48		4.79
0682-SEA-003 CLIP ABUMPER 3 2.30 3 SUM PART:			4,203.31

20.00

20.00

1.40



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

5.60

10.08

12.88

100.80

267.96

528.93

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

WA006 / AXA INSURANCE

JHMGE68509S221755

Document No: Printed By:

SVO18009210

SHNG

20

20

20

20

Chassis No: License No:

SJV8262Z

Mileage:

Order Date:

12. February 2018

80.00

144.00

184.00

1,440.00

3,828.00

7.556.34

189715

Order Time:

4:50:04 PM

Engine No:

L13Z11021757

Service Advisor:

100.00

180.00

230.00

1.800.00

2,450.00

NG SIN HAI

SUNDRIES

BML01I

INSPECT FR LIGHTING MECHANISMS &

FOCUS

HEADLIGHTS.(N)

BMC01D

BMA01D

BKBH12B

REMOVE & INSTALL RADIATOR WITH

FITTINGS.

PRESSURE TEST COOLING SYSTEM.(N)

REMOVE & INSTALL A/C CONDENSER

WITH FITTINGS.

VACUUM & RECHARGE A/C GAS.(N)

CUT OFF & RENEW BULKHEAD FR R

HOUSING COMP. STRAIGHTEN ALIGN FR R FRAME &

RENEW DAMAGE PARTS.

BP01R

SPRAY PAINT ON REPAIRED/REPLACED

AREAS.(7PX\$350)

1,960.00 20

137.20

2,097.20

85.60

154.08

196.88

1,540.80

TOTAL SGD

Total Payable (SGD)

SUM LABOUR:

8,085.27

4,095.96

8,085.27

GST Amount is calculated from individual line(s)



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	nationale Des Experts En Autor	nobile
AXA INSURANCE PTE	E LTD	Ref : CS/ASM18002	:800/T1qd3e2
3 SHENTON WAY #24 AXA TOWERSINGAPO ATTN : YVONNE ANG	ORE 068811	Date: 25-10-2018 Code: ASM	
		culars :- OWN DAMAGE	
Insured Veh.	•	Veh. Inspected	SJV 8262Z
Policy No.	VPA/P0902240	Coverage (\$)	0.00
Claim No.	S8M008S4	Excess (\$)	200.00
Assign From	YVONNE ANG	Assign Date	12/02/2018
2.	Vehicle P	articulars & Condition	A PART OF THE PART
Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMGE68509S221755	Colour	BLACK
Odometer	205932	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/55 R15	MICHELIN	6 mm
L/H Front Tyre	195/55 R15	MICHELIN	6 mm
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm
4.		iption of Damages	
THE VEHICLE SU	ISTAINED DAMAGES AT THE	FRONT PORTION.	
DAMAGES SEE D	ETAILS.		
5.	Gen	eral Information	
Accident Date	09/02/2018	Inspection Date	12/02/2018
Survey held at	Survey held at KAH MOTOR CO SDN BERHAD		
	NO. 255 ALEXANDRA ROAI SINGAPORE 159937	D	
5a.		Remarks	Transport Control
A)THE MARKET \	VALUE IS S\$30,000.00(EST. A CE TO YOUR INSTRUCTIONS	VERAGE)	252422

Estimate Days of Repair

7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 8262Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE WITH CASING-OPC-L (SN)	BENT	45.00	45.00
1	BULKHEAD (SN)	BENT	252.26	252.26
1	HOOD COMP (SN)	BENT	304.20	304.20
1	HINGE R HOOD (SN)	NOT NECESSARY	20.47	
1	HINGE L HOOD (SN)	NOT NECESSARY	20.47	
1	INSULATORHOOD (SN)	DEFORMED	22.36	22.36
1	LOCK ASSY HOOD (SN)	BENT	28.34	28.34
1	RUBBER R HOOD (SN)	NECESSARY	2.66	2.66
1	RUBBER L HOOD (SN)	NECESSARY	2.66	2.66
1	CONDENSER ASSY (SN)	BENT	503.88	503.88
1	FANCOOLING (SN)	CRACKED	32.17	32.17
1	SHROUD COMP (SN)	CRACKED	47.90	47.90
1	MOTORCOOLING FAN (SN)	DISTORTED	123.11	123.1
1	PIPE COMPRECEIVER (SN)	NOT NECESSARY	62.92	
1	HOSE COMPDISCHARGE (SN)	NOT NECESSARY	110.24	
1	HOSE COMPSUCTION (SN)	NOT NECESSARY	49.07	1
1	RADIATOR COMP (SN)	CRACKED	913.31	913.31
1	SHROUD COMP (SN)	CRACKED	58.04	58.04
1	FAN COOLING (SN)	NOT NECESSARY	36.20	= = = = = = = = = = = = = = = = = = = =
1	MOTOR COOLING FAN (SN)	NOT NECESSARY	204.68	
1	HEADLIGHT R (SN)	CRACKED	217.75	217.75
1	HEADLIGHT L (SN)	CRACKED	217.75	217.75
6	COOLANTANTI-FREEZE (SN)	NECESSARY	90.48	90.48
1	BASE FR GRILLE (SN)	сит	81.12	81.12
1	EMBLEM (H) (SN)	NECESSARY	14.88	14.88
2	NUTPUSH 3MM (SN)	NECESSARY	2.47	2.47
1	FACEFR BUMPER (SN)	DEFORMED	356.20	327.08
1	GRILLEFR BUMPER LOWER (SN)	DEFORMED	64.80	64.80
1	COVERFR.TOWING HOOK (SN)	DEFORMED	10.07	10.07
1	BEAM COMPFR BUMPER (SN)	BENT	157.30	157.30
1	BEAMR FR BUMPER COPPER (SN)	NECESSARY	17.87	17.87

Report Ref No. CS/ASM18002800/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BEAML FR BUMPER COPPER (SN)	NECESSARY	17.87	17.87
1	SPACERR FR BUMPER SIDE (SN)	NECESSARY	7.47	7.47
1	SPACERL FR BUMPER SIDE (SN)	NECESSARY	7.47	7.47
8	CLIP ABUMPER (SN)	NECESSARY	20.28	20.28
1	PANEL R FR FENDER (SN) (ADDITIONAL)	BENT	267.34	267.34
1	TANKWASHER (SN) (ADDITIONAL)	DEFORMED	37.96	37.96
1	GARNISH ASSYR FR CORNER (SN) (ADDITIONAL)	CRACKED	25.93	25.93
1	HOLDEROD (SN) (ADDITIONAL)	NECESSARY	2.08	2.08
3	CLIP ABUMPER (SN) (ADDITIONAL)	NECESSARY	4.48	4.48
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			4,511.51	3,948.34
	LABOUR			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		100.00	80.00
	REMOVE & INSTALL RADIATOR WITH FITTINGS.		180.00	144.00
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.		230.00	184.00
	CUT OFF & RENEW BULKHEAD FR R HOUSING COMP.		4,000.00	1,440.00
	SPRAY PAINT ON REPAIRED / REPLACED AREAS (7PX \$350)		4,000.00	1,960.00
	REMOVE & INSTALL ENGINE COMPARTMENT & OTHERS.	NOT NECESSARY	2,800.00	
			11,310.00	3,808.00
	GRAND TOTAL		15,821.51	7,756.34

RECOMMENDED COST OF REPAIRS	7,756.34
LESS EXCESS	-200.00
NETT LIABILITY	7,556.34

Report Ref No. CS/ASM18002800/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.