

JOIN MOTOR & ENGINEERING WORKS

AUTOBAY@KAKI BUKIT
BLK 1, KAKI BUKIT AVENUE 6 01-105, SINGAPORE 417833
TEL : 6747 4169 & 6747 3825
EMAIL : joinmotor@hotmail.com
REG NO. 255220/00J

p/r \$ 5038.60

12/2/2018

YOUR REF : SLJ 8483S

DIRECT ASIA
88 SOUTH BRIDGE
S(058716)
TEL : 6532 1818
EMAIL : claim@directasia.com

ATTN : MOTOR CLAIM DEPT

RE : QUOTATION FOR REPAIR SKR 2975Z (TOYOTAT ALTIS)

ITEM	PRICE
1 PC LH TAIL LAMP 320	\$ 368.50
1 PC LH BOOT REFLECTOR one	\$ 339.50
4 PCS TAIL LAMP CLIP@\$5 11	\$ 20.00 X
1 PC REAR BUMPER D.S	\$ 486.50
1 PC REAR BUMPER REINFORCEMENT 20	\$ 382.70
1 PC REAR LH BUMPER RETAINER 20/1cm 65.10	\$ 104.90
1 PC REAR BUMPER BRACKET 11	\$ 65.70 X
1 PC REAR END PANEL 30/50	\$ 587.20
1 PC REAR BOOT 20/30	\$ 660.50
1 PC REAR BOOT LOCK 20	\$ 382.70
1 PC BOOT WEATHER STRIP 20	\$ 168.20
1 PC SPARE TYRE FLOORBOARD 11	\$ 780.40 X
1 PC "COROLLA" WORD 20	\$ 43.60
1 PC "ALTIS" WORD 20	\$ 39.30
1 PC TOYOTA LOGO 20	\$ 50.80
1 set REVERSE SENSOR SET 20	\$ 280.00 200.00
PANEL BEATING CHARGE TO REMOVE AND REPLACE TO KNOCK & CHANGING ABOVE ITEM	\$ 1,400.00 800
SPRAY PAINTING OF THE AFFECTED PARTS & AREAS.	\$ 1,200.00 1000
TO CHECK UP WIRING AND INSTALL REVERSE SENSORS	\$ 120.00 50
TO APPLY RUSTPROOFING FOR THE REPAIR AREAS	\$ 180.00 60
TO CHECK WIRING	\$ 80.00 20

Rear end panel top garnish 20 250.20 ✓

Rear license plate w/holder 20 405.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
Take photo before repair. p-3824.80
255220/00J
2868.60
5038.60
12/2/18